



Rocky Flats Environmental Technology Site

**RECONNAISSANCE-LEVEL CHARACTERIZATION
REPORT (RLCR)**

GROUP B FACILITIES

REVISION 0

APPENDICES (A – G)

▲
JUL 1 2000
RECEIVED
RECORDS CENTER

Best Available Copy

QUALITY ASSURANCE
IA-A-000530

1/ 203

A-1

T881A – Radiological Survey Data for Exterior Survey Unit

- Summary of Radiological Survey/Sample Results
- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results – Detail
- Laboratory Alpha Spec (Sample) Results – Detail

Radiological Survey/Sample Results for T881A

Total Surface Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-20.9	-215
MAX	18.2	444
MEAN	-5.4	50.2
STD DEV	10.0	138.6
Exterior	# Required	# Obtained
	28	28
MIN	-7.4	-219.0
MAX	84.6	444.4
MEAN	30.6	82.7
STD DEV	22.7	211.6
DCGL _w	100	5000

Removable Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-5	-31.6
MAX	2	35.2
MEAN	0.3	-1.4
STD DEV	1.5	20.5
Exterior	# Required	# Obtained
	28	30
MIN	-0.91	-63.2
MAX	3.94	36.8
MEAN	0.7	-8.9
STD DEV	1.4	21.5
DCGL _w	20	1000

Media Sample Activity


# Required	# Obtained
2	2

<u>Contaminant</u>	<u>Y/N</u>	<u>Det. Sens. dpm/100 cm²</u>
U present	N	79
Pu present	N	79

Total Po-210 Results dpm/100 cm²

MIN	37.8
MAX	52.5
MEAN	45.2
STD DEV	4.5

T881B Exterior



- REST OF SCAN LOCATIONS ON A SEPARATE MAP.

T881A West Office

	West Wall				North Wall				East Wall				South Wall			
2																
1																
	A	B	C	D	A	B	C	D	A	B	C	D	A	B	C	D

Middle Office

	West Wall				North Wall												East Wall			
2																				
1																				
	A	B	C	D	A	B	C	D	E	F	G	H	I	J	K	L	A	B	C	D

	South Wall													
2														
1														
	A	B	C	D	E	F	G	H	I	J	K	L	M	N

Note: There is a small closet against the south wall. It was included in the room measurement since its east and west walls are less than 1 meter.

T881A East Office

	West Wall				North Wall				East Wall				South Wall			
2																
1																
	A	B	C	D	A	B	C	D	A	B	C	D	A	B	C	D

Floor

SCAN LOCATIONS


4													X	X				X	
3			X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	X	
2			X	X											X	X			
1			X	X											X	X		X	
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S

Ceiling

4																			
3																			
2																			
1																			
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22


Seal Locations:



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26

Note: Seal locations were chosen based on most likely to find contamination due to their "high traffic" likelihood in these areas.

T881A Exterior Roof



X-Coordinate	Y-Coordinate
17	3

□ = one square meter

■ = direct & swipe

Roof Surveys randomly chosen with original
 number of survey points (13 survey points)


X	Y	X	Y
1	8	2	11
2	14	4	12
3	10	1	13
4	13	2	20
5	14	3	1
6	12		
7	4		
8	7		
9	13		
10	16		

372 / 242


2/24/00

T881A Exterior


North Wall




South Wall





West Wall



East Wall



 = one square meter

 = direct & swipe

Survey Locations Correspond to original randomly placed locations for the walls
 No change in the survey locations on the walls was necessary for Revision 1

376/242 ~~376/242~~ 3/7/00

Building: T 881A

EXTERIOR WALLS SURVEY LOCATIONS COORDINATE WITH FIRST²⁰
UNREVISED MAP

[illegible]

9

Building: T 881 A

EXTERIOR ROOF SAMPLE LOCATIONS
COORDINATE WITH ¹⁷⁵⁻⁰⁰⁰~~FIRST~~ MAP. (REV. 2)
THIRD

Sample Location	RCT ID #	Inst ID #		Gross Counts (gcpm)		Net Counts (cpm)		Removable Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β
D-2R	4	5	6	1.5	40.5	1.3	1.9 -2.4	3.9	9.6 -7.6
D-4R	4	5	6	1.5	34.5	1.3	-7.9	3.9	-31.6
G-3R	4	5	6	0.0	47.5	-0.2	5.1	-0.6	20.4
H-3R	4	5	6	0.5	41.5	0.3	-0.9	0.9	-3.6
I-4R	4	5	6	0.0	41.0	-0.2	-1.4	-0.6	-5.6
L-3R	4	5	6	0.5	41.0	0.3	-1.4	0.9	-5.6
m-1R	4	5	6	0.5	42.0	0.3	-0.4	0.9	-1.6
m-2R	4	5	6	0.5	42.5	0.3	0.1	0.9	0.4
N-1R	4	5	6	0.0	44.0	-0.2	1.6	-0.6	6.4
N-2R	4	5	6	0.5	36.5	0.3	-5.9	0.9	-23.6
P-3R	4	5	6	0.0	37.5	-0.2	-4.9	-0.6	-19.6
T-4R	4	5	6	0.0	32.0	-0.2	-10.4	-0.6	-41.6
T-4R	4	5	6	0.0	35.0	-0.2	-7.4	-0.6	-29.6


Final Survey NE Electra Scan & Investigation Survey Map

Survey Area: <i>IVA</i>	Survey Unit: <i>EXTERIOR</i>	Building: <i>T 881A</i>
Survey Unit Description: <i>ROOF</i>		
RCT Initials/Date: <i>PC 3-3-00</i>	RCT Initials/Date: <i>MLA</i>	RCT Initials/Date: <i>NB</i>




Refer to the Final Survey NE Electra Scan & Investigation Survey Form for instrumentation, surveyor & approval information.

Legend: "R"- Roof, "W"- West Wall, "S"- South Wall, "E"- East Wall, "N"- North Wall
"C"- Ceiling, "F"- Floor

9 POINT INVESTIGATION



D-4R



* Designates corner closest to A-1 point of reference

Results/Comments:

Electra alpha scans were performed at the locations detailed on the survey map(s). All required accessible areas were scanned. All initial scan results were <225 dpm/100cm², unless noted on the survey form.

Electra beta scans were performed in required accessible areas. Initial scan results indicated no detectable activity above background unless noted on the survey form.

Final Survey NE Electra Scan & Investigation Survey Form

[illegible]
$$\frac{1 \text{ m}^2 \text{ Avg}}{15.3}$$

Oasis Device # 2

RFETS; Golden, CO
Apr 24, 2000 09:53:07

Sample ID: 881A 00A1148-001.001 Type: Unknown

Batch ID: unknown

Acquisition Start: April 20, 2000 08:39:27

Analysis Date: April 24, 2000 09:52:59

Procedure: polonium210 samples

Device: Oasis:02:01

Analysis Method: ROI Analysis

Spectrum File: 00000290.OXS LiveTime: 10,800.00

Calibrations:

Energy = $2.127\text{E}+02 + 2.333\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998

Calibration Date: March 14, 2000 09:19:39 Std: 2:1 energy cal

Shape not Calibrated.

Efficiency = $3.393\text{E}-01 \pm 4.339\text{E}-03$

Calibration Date: August 11, 1999 13:14:16 Std: AS 4188

External Recovery No Ext.Recovery

Original Sample Amount: 1.000 ± 0.000 samp

Aliquot Amount: 1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS		PK EN (keV)	FWHM (keV)
		START	END		
1 Po218	Po218	5552.6	6077.8	5814.6	2.3
2 Po214	Po214	7420.0	7770.1	7594.8	1.2
3 Po212		8521.5	8850.6	8684.3	2.3
4 Po210	Po210	2263.7	5402.1	5177.6	2.3

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF.	CPM	ROI TYPE
Po218	0.2 ± 1.0	0.76	$1.33\text{E}-03 \pm 5.70\text{E}-03$	Unknown
Po214	-0.1 ± 0.1	0.07	$-3.84\text{E}-04 \pm 3.84\text{E}-04$	Unknown
Po212	0.9 ± 1.0	0.14	$4.79\text{E}-03 \pm 5.58\text{E}-03$	Unknown
Po210	154.7 ± 13.0	13.35	0.859 ± 0.072	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm)
Po218	Po218	1.000	$3.92\text{E}-03 \pm 0.017$	$9.29\text{E}-02$
Po214	Po214	1.000	$-1.13\text{E}-03 \pm 1.13\text{E}-03$	$5.90\text{E}-02$
Po212		1.000	0.014 ± 0.016	$6.50\text{E}-02$
Po210	Po210	1.000	2.532 ± 0.215	$2.48\text{E}-01$

Activity reported as of April 20, 2000 08:39:27

ANALYSIS REVIEWED BY: 

APPROVED BY:  5/8/00



Library: OAS_STD.MDB Nuclide: Am241


Acq ALL
Acquire
Stop
Reset

4096
LOG

☐ Lin ☒ Log
☐ Sqrt

Peak
[Left Arrow] [Right Arrow]

Presets
ROIs
Controls
Display
Info
Aux Disp



4095

Spectrum ID

881A 00A1148-001.001

Message Window

System Date

09 May 2000 14:53:19

Channel: 1011 Elapsed Real Time: 10800.05 Elapsed Live Time: 10800.00 Dead Time: 0.0

Energy: 2571.0 Counts: 0 ROI: Integral: 168 Peak: 5,177.63 FWHM: 2.33

Oasis Device # 2

RFETS; Golden, CO
Apr 21, 2000 15:17:03

Sample ID: 881A 00A1148-002.001 Type: Unknown
Batch ID: unknown
Acquisition Start: April 21, 2000 07:49:49
Analysis Date: April 21, 2000 15:14:19
Procedure: polonium210 samples
Device: Oasis:02:01
Analysis Method: ROI Analysis
Spectrum File: 00000297.OXS LiveTime: 26,514.17

Calibrations:
Energy = $2.127\text{E}+02 + 2.333\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998
Calibration Date: March 14, 2000 09:19:39 Std: 2:1 energy cal
Shape not Calibrated.
Efficiency = $3.393\text{E}-01 \pm 4.339\text{E}-03$
Calibration Date: August 11, 1999 13:14:16 Std: AS 4188

External Recovery No Ext.Recovery

Original Sample Amount: 1.000 ± 0.000 samp
Aliquot Amount: 1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS START	EXTENTS END	PK EN (keV)	FWHM (keV)
1 Po218	Po218	5552.6	6077.8	5814.6	2.3
2 Po214	Po214	7420.0	7770.1	7594.8	1.2
3 Po212		8521.5	8850.6	8684.3	1.2
4 Po210	Po210	2263.7	5402.1	4683.0	4.7

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF.	CPM	ROI TYPE
Po218	1.5 ± 2.3	2.46	$3.50\text{E}-03 \pm 5.31\text{E}-03$	Unknown
Po214	0.0 ± 0.0	0.00	$0.00\text{E}+00 \pm 0.00\text{E}+00$	Unknown
Po212	-0.6 ± 0.6	0.61	$-1.39\text{E}-03 \pm 1.39\text{E}-03$	Unknown
Po210	273.8 ± 18.2	36.21	0.620 ± 0.041	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm)
Po218	Po218	1.000	0.010 ± 0.016	$6.17\text{E}-02$
Po214	Po214	1.000	$0.00\text{E}+00 \pm 0.00\text{E}+00$	$1.80\text{E}-02$
Po212		1.000	$-4.09\text{E}-03 \pm 4.09\text{E}-03$	$3.99\text{E}-02$
Po210	Po210	1.000	1.826 ± 0.124	$1.86\text{E}-01$

Activity reported as of April 21, 2000 07:49:49

ANALYSIS REVIEWED BY:

APPROVED BY:

[Signature]
[Signature] 5/8/00



Library:


OAS_STD.MDB

Nuclide:

Am241



5: Static: 00000292.OXS



4095

0

Acq ALL
Acquire
Stop
Erase

4096
LOG

☐ Lin ☒ Log
☐ Sqrt

Peak
[Left Arrow] [Right Arrow]

Presetz
RDis
Controls
Display
Info
Aux Disp

Spectrum ID

881A 00A1148-002.001

System Date

10-May-2000 06:11:46

Message Window

Channel: 1551 Elapsed Real Time: 10800.17 Elapsed Live Time: 10800.00 Dead Time: 0.0

Energy: 3866.8 Count: 0 ROI: [Redacted] Integral: 127 Peak: 5,050.79 FWHM: 2.39

Sample ID: 00A1148-003.001

Type: Unknown

Batch ID: unknowns
Acquisition Start: May 02, 2000 13:02:56
Analysis Date: May 03, 2000 07:11:03
Procedure: Po210 count
Device: Oasis:01:01
Analysis Method: ROI Analysis
Spectrum File: 00000522.OXS
LiveTime: 28,800.00

Calibrations:

Energy = $3.865E+01 + 2.790E+00 * \text{Chn}$ Coeff. of Correlation: -0.998
Calibration Date: April 03, 2000 17:45:10 Std: 1:1 energy cal
Shape not Calibrated.
Efficiency = $3.041E-01 \pm 4.004E-03$
Calibration Date: April 07, 2000 09:49:29 Std: TS4189

External Recovery No Ext.Recovery

Original Sample Amount:

1.000 ± 0.000 samp

Aliquot Amount: 1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS START	END	PK EN (keV)	FWHM (keV)
1 Po218	Po218	5550.0	6104.5	5826.0	4.2
2 Po214	Po214	6588.5	7874.7	7229.6	2.8
3 Po212	Po212	8393.8	8808.6	8599.7	2.8
4 Po210	Po210	2180.3	5343.3	4531.3	2.8

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	19.7 ± 4.7	1.33	$0.041 \pm 9.75E-03$	Unknown
Po214	1.3 ± 1.6	0.67	$2.78E-03 \pm 3.26E-03$	Unknown
Po212	11.3 ± 4.0	2.67	$0.024 \pm 8.28E-03$	Unknown
Po210	161.7 ± 13.9	19.33	0.337 ± 0.029	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm)
Po218	Po218	1.000	0.135 ± 0.032	$5.21E-02$
Po214	Po214	1.000	$9.14E-03 \pm 0.011$	$4.23E-02$
Po212	Po212	1.000	0.078 ± 0.027	$6.61E-02$
Po210	Po210	1.000	1.108 ± 0.097	$1.47E-01$

Activity reported as of May 02 2000 13:02:56

ANALYSIS REVIEWED BY:

APPROVED BY:


spike value:
22.980 d/m
pv 239

Final Survey NE Electra Scan & Investigation Survey Map

Survey Area: NA	Survey Unit: EXTERIOR	Building: T881A
Survey Unit Description: ROOF SAMPLE LOCATIONS		
RCT Initials/Date: NA 3/28/00	RCT Initials/Date: NA	RCT Initials/Date: NA

Refer to the Final Survey NE Electra Scan & Investigation Survey Form for instrumentation, surveyor & approval information.

Legend: "R" - Roof, "W" - West Wall, "S" - South Wall, "E" - East Wall, "N" - North Wall
"C" - Ceiling, "F" - Floor



⊗ CUTOUT LOCATION

* Designates corner closest to A-1 point of reference

Results/Comments:

Electra alpha scans were performed at the locations detailed on the survey map(s). All required accessible areas were scanned. All initial scan results were <225 dpm/100cm², unless noted on the survey form.

Electra beta scans were performed in required accessible areas. Initial scan results indicated no detectable activity above background unless noted on the survey form.

21

Building: T881A

Survey Unit Description

Removable Contamination Data Sheet

[illegible]

22


A-2

T881A – Radiological Survey Data for Interior Survey Unit


- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results – Detail

SURVEY PACKAGE
 SURVEY MAP
 Revision 2

T881A West Office



Middle Office




South Wall




Note: There is a small closet against the south wall. It was included in the room measurement since its east and west walls are less than 1 meter.


T881A East Office



Floor



Ceiling



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22

X-Coordinate	Y-Coordinate
14	8

Total Surface Area = 284 m²

10% Scan Surface Area = 28.4 m²

□ = one square meter

■ = direct & swipe

X	Y	X	Y	X	Y
1	7	12	13	2	21
2	21	4	12	7	15
3	11	6	13	9	16
4	13	14	14	4	9
5	16	13	15	15	8
6	10	10	16	19	12
7	13	9	17	13	5
8	12	8	18	3	16
9	7	6	19	19	10
10	2	15	20	17	11

Survey Area: N/A	Survey Unit: INTERIOR	Building: T881 A
Survey Unit Description Interior		

Removable Contamination Data Sheet

Sample Location	RCT ID #	Inst ID #		Gross Counts (gcpm)		Net Counts (cpm)		Removable Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β
West Office									
A-2-E		1	2	0	40.5	-0.3	-1.9	-0.9	-7.6
C-1-E		3	4	.5	33	0.5	-5.7	1.5	-22.8
D-4-F		1	2	0	34.5	-0.3	-7.9	-0.9	-31.6
Ceiling									
C-1-C		3	4	0	46	0.3 0	7.3	0.9 0	29.2
B-2-C		1	2	.5	41.5	.2	-0.9	0.6	-3.6
B-3-C		3	4	.5	39.5	.5	0.8	1.5	3.2
B-2-C		1	2	1	38	.7	-4.4	2.1	13.3 -17.6
I-1-C		3	4	.5	39.5	.5	0.8	1.5	3.2
P-4-C		1	2	0	43.5	-0.3	1.1	-0.9	4.4
Floor									
J-1-F		3	4	0	38.5	0	-0.2	0	-0.8
J-3-F		1	2	0	39.5	-0.3	-2.9	-0.9	-11.6
M-4-F		3	4	.5	38	.5	-0.7	1.5	-2.8
N-3-F		1	2	1	48	.7	5.3 5.6	2.1	21.2 22.4
N-4-F		3	4	0	44.5	0	5.8	0	23.2
Q-2-F		1	2	.5	35.5	.2	-6.9	0.6	-27.6
S-1-F		3	4	0	50.5	0	11.8	0	47.2
S-3-F		1	2	.5	35	.2	-7.4	0.6	-29.6
S-4-F		3	4	0	36	0	-2.7	0	-10.8
East Office									
A-1-E		1	2	1	45.5	.7	3.1	2.1	12.4
C-1-E		3	4	.5	47.5	.5	8.8	1.5	35.2
D-1-E		1	2	.5	43.5	.2	1.1	0.6	4.4
Main Office									
C-1-E		3	4	0	38	0	-0.7	0	-2.8
K-1-S		1	2	.5	35	.2	3.9 -7.4	0.6	15.6 -25.6
G-1-S		3	4	.5	41.5	.5	2.8	1.5	11.2
D-1-S		1	2	0	37	-0.3	-5.4	-0.9	-21.6
E-1-N		3	4	.5	41	.5	2.3	1.5	9.2

Survey Area: <u>NA</u>	Survey Unit: <u>INTERIOR</u>	Building: <u>T-881A</u>
Survey Unit Description <u>INTERIOR WALLS, CEILING, FLOOR</u>		

Total Surface Activity Data Sheet

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts ^a (cpm)		Net Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β	α	β	α	β
D-4F	1	7	7	90	90	6.0	429	2.7	460	-3.2	31	-15.0	101
G-1F				90	90	2.7	459	2.7	417	0.0	-42	0.0	-137
I-3F				90	90	4.0	429	1.3	481	-2.7	52	-12.3	170
M-4F				90	90	3.3	455	1.3	469	-2.0	14	-9.1	46
N-4F				90	90	6.0	463	2.0	473	-4.0	10	-18.2	33
N-3F				90	90	7.3	440	3.3	491	-4.0	51	-18.2	166
Q-2F				90	90	5.3	409	1.3	475	-4.0	66	-18.2	215
S-1F				90	90	3.3	441	6.0	462	2.7	21	12.3	68
S-3F				90	90	7.3	427	4.0	441	-3.3	14	-15.0	46
S-4F				90	90	4.0	422	1.3	473	-2.7	51	-12.3	166
W-1F OFFICE				90	90	6.7	420	6.0	383	-0.7	-37	-3.2	-121
A-2E				90	90	6.0	342	7.3	347	1.3	5	5.9	16
C-1E				90	90	6.7	372	3.3	368	-3.4	-4	-15.5	-13
E-1N				90	90	6.0	384	5.3	356	-0.7	-28	-3.2	-91
G-1S				90	90	3.3	357	3.3	375	0.0	18	0.0	59
K-1S				90	90	6.7	369	10.7	370	4.0	1	18.2	370 ³
M-2S				90	90	4.0	301	4.0	329	0.0	28	0.0	91
C-1E				90	90	3.3	299	2.0	337	-1.3	38	-5.9	124
ENT OFFICE				90	90	2.7	319	0.7	316	-2.0	-3	-9.1	-10
A-1E				90	90	3.3	301	4.7	308	1.4	7	6.4	23
C-1E				90	90	8.0	329	4.7	355	-3.3	26	-15.0	85
B-2C				90	90	3.3	409	2.0	358	-1.3	-11	-5.9	-36
B-3C				90	90	3.3	423	4.0	357	0.7	-66	5.9 ³²	-215
C-1C				90	90	3.3	382	2.0	402	-1.3	20	-5.9	65
G-2C				90	90	3.3	381	4.0	314	0.7	-65	3.2	-212
I-1C				90	90	4.0	372	4.0	393	0.0	21	0.0	68
M-3C	1	7	7	90	90	4.0	314	4.7	450	0.7	136	3.2	444
P-4C	1	7	7	90	90	7.3	305	2.7	422	-4.6	77	-20.9	251
J-3FQC	2	9	9	90	90	6.0	432	4.0	481	-2	49	-6.0 ³³	196 ⁹⁰
N-3FQC	2	9	9	90	90	4.7	465	5.3	469	0.6	4	1.8 ²⁸	16 ⁹⁰
M-4FQC	2	9	9	90	90	2.7	467	4.7	481	2	14	6.0 ⁹³	56 ⁹⁰
Q-2FQC	2	9	9	90	90	6.7	436	1.3	483	-5.4	47	16.4 ^{25.7}	188 ⁹⁰
D-4FQC	2	9	9	90	90	8.7	447	3.3	467	-5.4	20	16.4 ^{25.7}	80 ⁹⁰

Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" - local area background.

Building: T8814

INTERIOR

[illegible]

A-3

T881A – Asbestos Inspector's Report

T881A

ASBESTOS INSPECTOR'S REPORT

I, the undersigned Certified Asbestos Inspector, certification # [REDACTED]
in the state of Colorado, attest to the asbestos inspection and sampling results as
described below, for the following facility (at RFETS): Trailer 881A.

General Facility Location: northeast of Building 881.

INSPECTION RESULTS

Trailer 881A did not contain any suspect friable asbestos containing materials
and no samples were collected. The duct system is lined internally with
fiberglass, but samples were not collected based on visual observation
identifying the material as fiberglass. Fiberglass insulation was found throughout
the walls.

SAMPLE RESULTS

None required; none taken.

Andre Gonzalez

INSPECTOR'S NAME

Andre Gonzalez

SIGNATURE

7/6/00

DATE

A-4

T881A – D&D Facility Characterization Interview Checklist



D&D Facility Characterization Interview Checklist

ID No.: T-881A
Date: 05/27/99
Page 1 of 2
Groups B & C Series

Check List for - Title: D&D Facility Characterization - Interviews

CRITERIA: Λ *D&D Characterization Protocol*, RFETS MAN-077-DDCP, Rev. 0
 Λ *Facility Disposition Program Manual*, RFETS MAN-076-FDPM
 Λ RFETS Radiological Safety Practices, January 12, 1998

Facility Name & Type (1, 2, or 3) T-881A, Group B Type 1 Facility, Trailer Office Building
Personnel Interviewed (Name & Title/Function) Justin L. Miller, X2218, P212-3996, T-881A, SORC1/ Administrator of the Cost Per Copy Program

-- Y/N --

Does a current WSRIC exist for the facility? N
If so, are there exceptions to the WSRIC as written?.....No WSRIC, No Exceptions

COMMENTS (incl. WSRIC contacts)

WSRIC Contact is James M. Schoen who is in charge of the WSRIC Reports, T130J, X3579, C-83.

Are rad surveys available that indicate current status of the facility? N
Are historical rad surveys available that indicate historical status, or evolution, of the facility? N*

COMMENT N* According to Mark R. Richards, X5148 of SSOC any historical data, which is probably at the Federal Center, would not be adequate for unrestricted release. New monitor surveys would have to be taken.

Is an HRR available for the facility?..... N
Do any other reports exist beyond the HRR (e.g., spill reports, reportable incidents, etc.) that further Characterize the facility relative to chemical &/or radiological contamination? N**
Are engineering drawings (esp. "as-builts") available?..... N
Are any nonconformances or issues with the facility status currently being tracked in PATS? N

If so, what are the issues (note in Comments, below)?

COMMENTS N* Radiological surveys may have been done, but the old data is not available. This unit will have to be resurveyed to meet present standards for unrestricted release. N** The T-881A Trailer is not sitting on IHSS or PAC area land, as per, Nick Demos, ER Characterization/HRR Manager, X4605. Therefore, the T-881A Trailer should not have any CERCLA concerns. Engineering drawings, as-builts, do not exist for the T-881A facility and a Facility Planning sketch does exist. The Plant quit using lead based paints for office buildings in 1989, if this office facility was painted prior to 1989, lead based paints may have been used.

Have any types of chemical characterization, incl. asbestos, been performed recently?..... N*

If so, what types of characterization were performed (note in Comments, below)?

COMMENTS N* No asbestos characterization data exists, according to Kevin Sheehan, X7250, T-452D, Room C-1. The asbestos data reports are located in Cubicle C-13, of T-452D and the reports are under the control of Kevin Sheehan.

Interviewed by: J. R. Sheets , JR Sheets , 05/26/99
Print Name Signature Interview Date



D&D Facility Characterization Interview Checklist

ID No.: T-881A
Date: 05/27/99
Page 2 of 2
Groups B & C Series

What timeframe did the interviewee work in the facility? From 1996 until the present (for approximately three years).

Has the building configuration changed since you worked in the building? If so, in what way?

No, the facility is still an office building.

What types of equipment were in the building during the interviewee's time there?

Refrigerator, 2 computer, 2 printer, a fax machine, a water cooler, 3 microwaves, other office equipment such as 8 desks, 8 chairs, 3 tables, bookcases, 3 file cabinets, three parts and copier supplies storage racks, etc.

Where was the equipment located? (specific rooms/areas) In the open area of the trailer, the hard wall room and office, and at either end of the trailer. The refrigerator, full size is sitting against the north wall of T-881A and a small refrigerator is located in the office on the east end of the trailer.

Were any radioactive materials or metals handled in the building? If so, what types? No, none

Which equipment handled radioactive material? N/A

Were any chemicals handled in the building? If so, what types? N/A

Did any spills or uncontrolled releases of radioactive materials or chemicals occur while you were working in the facility? No, none.

Were these spills/releases cleaned-up? How were they cleaned-up? N/A

Where did these spills/releases occur? N/A

Interviewed by: J. R. Sheets

Print Name

JR Sheets

Signature

05/26/99

Interview Date

Type 1 Facility Checklist

TYPE 1 FACILITY	<u>BUILDING T-881A</u>
CURRENT LANDLORD:	<u>RFCSS</u>
DATE OF COMPLETION:	<u>02/29/00</u>

ITEM	YES	NO
Does the facility contain radiological postings?		X
Does the facility contain chemical postings?		X
Are there any installed hazards?		X
Do the historical surveys (radiological and chemical) indicate the facility is clean?	X	
Are there RCRA units within the facility		X
Is there a history of the building available?	X	
Is there any equipment/furniture left in the facility?		X
Is there a future mission identified for the facility?		X
Will the facility be left unsecured after it is vacated?		X

If any answer to any of the above questions is "Yes", complete the following questions and complete the "graded" PEP in accordance with Chapter 2.

Note: An answer of "Yes" to any question, specifically one dealing with hazards, may indicate the facility is not a Type 1 Facility. Check with the D&D Programs office.

If the answer to all question is "No" complete the "graded" PEP in accordance with Chapter 2.

1. List the Radiological Hazards, location, and quantity:

Based on the historical data found and interviews taken there are no hazards in this trailer.

2. List the Chemical Hazards, location, and quantity:

None. Based on historical data and interviews taken no asbestos data exists and the paint may be lead based.

3. List the Physical Hazards:

NONE

B-1

T881B – Radiological Survey Data for Exterior Survey Unit

- Summary of Radiological Survey/Sample Results
- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results – Detail
- Laboratory Alpha Spec (Sample) Results – Detail

Radiological Survey/Sample Results for T881B

Total Surface Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-3	-394
MAX	22	286
MEAN	7.4	-26.9
STD DEV	7.9	200.6
Exterior	# Required	# Obtained
	28	28
MIN	-6.0	-219.0
MAX	118.2	444.4
MEAN	29.2	82.7
STD DEV	37.7	211.6
DCGL _w	100	5000

Removable Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-0.3	-52
MAX	2.7	56
MEAN	0.8	-0.4
STD DEV	1.1	29.1
Exterior	# Required	# Obtained
	28	28
MIN	0.0	-26.4
MAX	9.0	49.6
MEAN	2.0	5.5
STD DEV	2.3	17.9
DCGL _w	20	1000

Media Sample Activity

# Required	# Obtained
2	2

<u>Contaminant</u>	<u>Y/N</u>	<u>Det. Sens. dpm/100 cm²</u>
U present	N	79
Pu present	N	79

Total Po-210 Results dpm/100 cm²

MIN	60.0
MAX	121.6
MEAN	90.8
STD DEV	6.8

Locations:

1 2 3 4 5 6 7

[illegible]

NORTH WALL

			A B	WEST WALL
3	2	1		

A B WEST WALL

[illegible]

A B C D E F G H I J K L M N O P

			A B EAST WALL
--	--	--	---------------------

A B
EAST
WALL


2																					
1																					
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P					

A B C D E F G H I J K L M N O P
SOUTH WALL

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22

- REST OF SCAN LOCATIONS ON A SEPARATE MAP.

T881B Exterior Roof



X-Coordinate	Y-Coordinate
16	2

□ = one square meter
 ■ = direct & swipe


Roof Surveys randomly chosen with original number of survey points (8 survey points)

X	Y
1	9
2	12
3	4
4	12
5	14
6	17
7	3
8	10

57a / 242

2/24/00

T881B Exterior



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22

X-Coordinate	Y-Coordinate
11	2

Total Surface Area = 124 m^2

10% Scan Surface Area = 13 m^2

□ = one square meter

■ = direct & swipe

X	Y
1	21
2	9
3	3
4	17
5	21
6	10
7	16
8	15
9	12
10	18

Survey Area: N/A

Survey Unit: EXTERIOR

Building: T8813

Survey Unit Description

Roof + Walls of Trailer T8813

Below sample locations were taken from the 1st (unrevised) map.

Removable Contamination Data Sheet

Sample Location	RCT ID #	Inst ID #		Gross Counts (gcpm)		Net Counts (cpm)		Removable Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β
I-1N	2	2	1	0	36	0	-1.6	0	-6.4
L-1N	2	2	1	0	37	0	-0.6	0	-2.4
O-1N	2	2	1	0	39	0	1.4	0	5.6
B-1W	2	2	1	0.5	31	0.5	-6.6	1.5	-26.4
B-3W	2	2	1	0.5	34	0.5	-3.6	1.5	-14.4
A-1E	2	2	1	0.5	36	0.5	-1.6	1.5	-6.4
A-2E	2	2	1	0	40	0	2.4	0	9.6
B-1E	2	2	1	0	40	0	2.4	0	9.6
B-2S	2	2	1	0.5	33	0.5	-4.6	1.5	-18.4
C-2S	2	2	1	0	40	0	2.4	0	9.6
F-1S	2	2	1	0.5	37	0.5	-0.6	1.5	-2.4
A-2S	2	2	1	2.0	31	2.0	-6.6	6.0	-26.4
I-1S	2	2	1	1.0	36	1.0	-1.6	3.0	-6.4
E-2S	2	2	1	1.0	45	1.0	7.4	3.0	29.6
E-2S	2	2	1	1.5	39	1.5	1.4	4.5	5.6
K-1S	2	2	1	0.5	40	0.5	2.4	1.5	9.6
N-2S	2	2	1	2.0	37	2.0	-0.6	6.0	-2.4
O-2S	2	2	1	3.0	42	3.0	4.4	9.0	17.6
P-1S	2	2	1	0.5	40	0.5	2.4	1.5	9.6
B-1R	2	2	1	0	40.5	0	2.9	0	11.6
B-3R	2	2	1	0.5	34	0.5	-3.6	1.5	-14.4
F-3R	2	2	1	0.5	40.5	0.5	2.9	1.5	11.6
G-3R	2	2	1	0	39	0	1.4	0	5.6
M-1R	2	2	1	0	42	0	4.4	0	17.6
N-1R	2	2	1	0.5	40.5	0.5	2.9	1.5	11.6
N-2R	2	2	1	1.5	46	1.5	8.4	4.5	33.6
O-3R	2	2	1	1.5	46	1.5	8.4	4.5	33.6
P-2S	2	2	1	0	50	0	12.4	0	49.6

Survey Area: <u>N/A</u>	Survey Unit: <u>EXTERIOR</u>	Building: <u>T881B</u>
Survey Unit Description: <u>Roof + Walls of TRAILER T881B</u>		

SAMPLE LOCATIONS BELOW WERE TAKEN FROM THE 1ST (UNREVISED) MAP.

Total Surface Activity Data Sheet

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts (cpm)		Net Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β	α	β	α	β
I-1W	1	7	7	90	90	1.3	349	3.3	361	2.0	12	9	40
L-1W	1	7	7	90	90	2.0	390	4.0	317	2.0	-73	9	-240
O-1W	1	7	7	90	90	2.7	345	6.7	345	4.0	0	18	0
B-1W	1	7	7	90	90	0.7	317	2.0	287	1.3	-30	6	-99
B-3W	1	7	7	90	90	2.0	377	4.0	381	2.0	4	9	13
A-1E	1	7	7	90	90	2.7	349	7.3	360	4.6	11	21	36
A-2E	1	7	7	90	90	2.7	348	8.0	327	5.3	-21	24	-69
B-1E	1	7	7	90	90	2.7	377	6.0	401	3.3	24	15	79
B-2S	1	7	7	90	90	2.0	367	6.0	379	4.0	12	18	40
C-2S	1	7	7	90	90	2.7	370	2.7	327	0.0	-43	0	-142
F-1S	1	7	7	90	90	1.3	317	2.0	383	0.7	66	3	217
H-2S	1	7	7	90	90	1.3	310	4.0	370	2.7	60	12	198
I-1S	1	7	7	90	90	2.0	345	6.0	367	4.0	22	18	72
J-2S	1	7	7	90	90	2.0	391	2.0	377	0.0	-14	0	-46
J-2S	1	7	7	90	90	1.3	328	6.0	344	4.7	16	21	53
K-1S	1	7	7	90	90	2.7	344	7.3	349	4.6	5	21	16
N-2S	1	7	7	90	90	2.0	342	6.7	362	4.7	20	21	66
O-2S	1	7	7	90	90	2.0	354	6.7	376	4.7	22	21	72
P-1S	1	7	7	90	90	2.0	362	2.0	370	0.0	8	0	26
P-2S	1	7	7	90	90	1.3	287	0.0	349	-1.3	62	-6	204
B-1R	3	9	9	90	90	4.0	400	16.7	467	12.7	67	59.0	224
B-3R	3	9	9	90	90	11.3	440	11.3	440	0.0	0	0.0	0
M-1R	3	9	9	90	90	1.3	415	24.7	469	23.4	54	103.4 ^a	180
N-1R	3	9	9	90	90	22.7	440	22.7	477	0.0	37	0.037 ^a	124
N-2R	4	9	9	90	90	5.3	428	30.7	446	18.4 ^a	18	118.2	-60
O-3R	4	9	9	90	90	6.0	480	26.0	467	20.0	-13	93.1	-43
F-3R	4	9	9	90	90	4.7	471	24.4 ^a	495	20.0	24	93.1	80
G-3R	4	9	9	90	90	4.7	443	21.3	501	22.6	58	105.2	194
F-1QC	8	10	10	90	90	6.7	516	14.0	373	7.3	-143	34.0	665 ^a 478
K-1QC	8	10	10	90	90	9.3	556	10.7	380	1.4	-176	6.5	219 ^a 589
B-1WQC	8	10	10	90	90	8.0	606	7.3	409	-0.7	-197	-3.3	917 ^a 658
L-1WQC	8	10	10	90	90	4.7	500	6.0	399	+1.3	-101	+6.0	473 ^a 337
I-1WQC	8	10	10	90	90	6.7	522	12.7	367	6.0	-155	27.9	727 ^a 518

Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" ~ local area background.


Page ____ of ____

Final Survey NE Electra Scan & Investigation Survey Map

Survey Area: NA	Survey Unit: EXTERIOR	Building: T 881B
Survey Unit Description: WALLS, ROOF		
RCT Initials/Date: <i>me</i> 3-3-00	RCT Initials/Date:	RCT Initials/Date:

Refer to the Final Survey NE Electra Scan & Investigation Survey Form for instrumentation, surveyor & approval information.

Legend: "R"- Roof, "W"- West Wall, "S"- South Wall, "E"- East Wall, "N"- North Wall
"C"- Ceiling, "F"- Floor



* Designates corner closest to A-1 point of reference

Results/Comments:

Electra alpha scans were performed at the locations detailed on the survey map(s). All required accessible areas were scanned. All initial scan results were <225 dpm/100cm², unless noted on the survey form.

Electra beta scans were performed in required accessible areas. Initial scan results indicated no detectable activity above background unless noted on the survey form.

Final Survey NE Electra Scan & Investigation Survey Form

Survey Area: NA					Survey Unit: EXTERIOR			Building: T8813	
Survey Unit Description: WALLS, ROOF									
Loc. ID #	Electra DP-6 Beta				Electra DP-6 Alpha				
	RCT ID #	Inst. ID #	Elevated Audible observed? "Y" or "N"	60-sec PAT (dpm/100cm ²)	RCT ID #	Inst. ID #	4-sec Audible observed? "Y" or "N"	30-sec Static (gcpm)	90-sec PAT (dpm/100cm ²)
N-IRA	1	7	NA	NA	1	7	NA	NA	83.7
N-IRB	1	7			1	7			95.3
N-IRC	1	7			1	7			95.3
N-IRD	1	7			1	7			62.6
N-IRE	1	7			1	7			95.3
N-IRF	1	7			1	7			53.4
N-IRG	1	7			1	7			53.4
N-IRH	1	7			1	7			83.7
N-IRI	1	7	Y	Y	1	7	Y	Y	95.3
B-2W1	1	7	N	NA	1	7	Y	8	NA
L-WJ	1	7	N	NA	1	7	N	NA	NA
F-2S1	2	8	N	NA	2	8	Y	8	NA
K-2S1	2	8	N	NA	2	8	Y	12	NA
O-2N1	2	8	N	NA	2	8	Y	10	NA
I-2N1	2	8	N	NA	2	8	Y	16	NA
I-2N2	2	8	N	NA	2	8	Y	6	NA
I-2N3	2	8	N	NA	2	8	Y	4	NA
I-2N4	2	8	N	NA	2	8	Y	6	NA
A-3E	2	8	N	NA	2	8	N	NA	NA
N A									

1m²
79

43

Sample ID: 00A1148-004.001

Type: Unknown

Batch ID: unknowns
Acquisition Start: April 24, 2000 16:15:32
Analysis Date: April 25, 2000 06:26:04
Procedure: Po210 count
Device: Oasis:01:01
Analysis Method: ROI Analysis
Spectrum File: 00000483.OXS
LiveTime: 10,800.00

Calibrations:

Energy = $3.865\text{E}+01 + 2.790\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998
Calibration Date: April 03, 2000 17:45:10 Std: 1:1 energy cal
Shape not Calibrated.
Efficiency = $3.041\text{E}-01 \pm 4.004\text{E}-03$
Calibration Date: April 07, 2000 09:49:29 Std: TS4189

External Recovery No Ext.Recovery

Original Sample Amount:

1.000 ± 0.000 samp

Aliquot Amount:

1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS START	EXTENTS END	PK EN (keV)	FWHM (keV)
1 Po218	Po218	5550.0	6104.5	5826.0	2.8
2 Po214	Po214	6588.5	7874.7	7229.6	2.8
3 Po212	Po212	8393.8	8808.6	8599.7	2.8
4 Po210	Po210	2180.3	5343.3	5192.6	3.5

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	0.5 ± 1.0	0.47	$2.95\text{E}-03 \pm 5.62\text{E}-03$	Unknown
Po214	2.7 ± 1.7	0.28	$0.015 \pm 9.64\text{E}-03$	Unknown
Po212	0.9 ± 1.0	0.09	$5.03\text{E}-03 \pm 5.57\text{E}-03$	Unknown
Po210	158.4 ± 12.9	6.56	0.880 ± 0.071	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm)
Po218	Po218	1.000	$9.71\text{E}-03 \pm 0.018$	$9.16\text{E}-02$
Po214	Po214	1.000	0.050 ± 0.032	$8.21\text{E}-02$
Po212	Po212	1.000	0.017 ± 0.018	$6.83\text{E}-02$
Po210	Po210	1.000	2.895 ± 0.238	$2.07\text{E}-01$

Activity reported as of April 24, 2000 16:15:32

ANALYSIS REVIEWED BY:

APPROVED BY:

44

OASIS - MCA

File Edit View Acq Params Tools Reports Close Help



Library:


OAS_STD.MDB

Nuclide:

Am241



1: Static: 00000483.DXS



Acq ALL
Acquire
Stop
Pause

4096



LOG

☐ Lin ☒ Log
☐ Sqrt

Peak



Spectrum ID

00A1148-004.001

System Date

09-May-2000 14:09:11

Message Window

Channel: 1363

Elapsed Real Time: 10799.99

Elapsed Live Time: 10800.00

Dead Time: 0.0

Energy: 3843.1

Counts: 1

ROI: 1

Integral: 165

Peak: 5,192.61

FWHM: 3.49

4095

Oasis Device # 2

RFETS; Golden, CO
Apr 19, 2000 07:30:58

Sample ID: 881B coupon 00A1148-005.001 Type: Unknown
Batch ID: unknown
Acquisition Start: April 18, 2000 13:05:01
Analysis Date: April 19, 2000 07:30:52
Procedure: polonium210 samples
Device: Oasis:02:01
Analysis Method: ROI Analysis
Spectrum File: 00000282.OXS LiveTime: 10,800.00

Calibrations:

Energy = $2.127\text{E}+02 + 2.333\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998
Calibration Date: March 14, 2000 09:19:39 Std: 2:1 energy cal
Shape not Calibrated.
Efficiency = $3.393\text{E}-01 \pm 4.339\text{E}-03$
Calibration Date: August 11, 1999 13:14:16 Std: AS 4188

External Recovery No Ext.Recovery

Original Sample Amount:

Aliquot Amount: 1.000 ± 0.000 samp
 1.000 ± 0.000 samp

ROI DATA

ROI ID	ASSOCIATED	EXTENTS	PK EN	FWHM
#	NUCLIDE	START	END	(keV)
1 Po218	Po218	5552.6	6077.8	5814.6
2 Po214	Po214	7420.0	7770.1	7594.8
3 Po212		8521.5	8850.6	8684.3
4 Po210	Po210	2263.7	5402.1	5152.0

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	-1.0 ± 0.5	1.00	$-5.56\text{E}-03 \pm 2.78\text{E}-03$	Unknown
Po214	0.0 ± 0.0	0.00	$0.00\text{E}+00 \pm 0.00\text{E}+00$	Unknown
Po212	-0.3 ± 0.3	0.25	$-1.39\text{E}-03 \pm 1.39\text{E}-03$	Unknown
Po210	358.3 ± 19.4	14.75	1.990 ± 0.108	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY	MDA
			(dpm/samp)	(dpm)
Po218	Po218	1.000	$-1.64\text{E}-02 \pm 8.19\text{E}-03$	$1.05\text{E}-01$
Po214	Po214	1.000	$0.00\text{E}+00 \pm 0.00\text{E}+00$	$4.43\text{E}-02$
Po212		1.000	$-4.09\text{E}-03 \pm 4.09\text{E}-03$	$7.44\text{E}-02$
Po210	Po210	1.000	5.866 ± 0.327	$2.76\text{E}-01$

Activity reported as of April 18, 2000 13:05:01

ANALYSIS REVIEWED BY:

J. Roberts 07/18/00

APPROVED BY:



Library:


OAS_STD.MDB

Nuclide:

Am241



5: Static: 00000282.OXS



Acq ALL

Acquire

Stop

Exit

4096



LOG

☐ Lin ☒ Log
☐ Sqrt

Peak



Presets

ROI's

Controls

Display

Info

Aux Disp

Spectrum ID

881B coupon 00A1148-005.001

System Date

10-May-2000 06:15:43

Message Window

Channel: 1692

Elapsed Real Time: 267802.13

Elapsed Live Time: 267799.07

Dead Time: 0.0

Energy: 4231.1

Counts: 5

ROI: [redacted]

Integral: 8.871

Peak: 5,189.12

FWHM: 125.20

Sample ID: 00A1148-006.001

Type: Unknown

Batch ID: unknowns

Acquisition Start: May 01, 2000 15:37:58

Analysis Date: May 02, 2000 06:53:01

Procedure: Po210 count

Device: Oasis:01:02

Analysis Method: ROI Analysis

Spectrum File: 00000521.OXS

LiveTime: 28,800.00

Calibrations:

Energy = $5.823\text{E}+01 + 2.790\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998

Calibration Date: April 07, 2000 14:55:56 Std: 1:2 energy cal

Shape not Calibrated.

Efficiency = $3.089\text{E}-01 \pm 4.062\text{E}-03$

Calibration Date: April 07, 2000 15:15:30 Std: TS4189

External Recovery No Ext.Recovery

Original Sample Amount:

1.000 ± 0.000 samp

Aliquot Amount:

1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS START END	PK EN (keV)	FWHM (keV)
1 Po218	Po218	5550.0 6104.5	6038.1	2.8
2 Po214	Po214	6588.5 7874.7	7229.6	2.8
3 Po212	Po212	8393.8 8808.6	8775.5	3.5
4 Po210	Po210	2180.3 5343.3	5234.5	3.3

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	41.0 ± 6.4	0.00	0.085 ± 0.013	Unknown
Po214	8.3 ± 3.1	0.68	$0.017 \pm 6.41\text{E}-03$	Unknown
Po212	48.0 ± 6.9	0.00	0.100 ± 0.014	Unknown
Po210	524.7 ± 23.4	12.31	1.093 ± 0.049	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm)
Po218	Po218	1.000	0.276 ± 0.043	$1.82\text{E}-02$
Po214	Po214	1.000	0.056 ± 0.021	$4.21\text{E}-02$
Po212	Po212	1.000	0.324 ± 0.047	$1.82\text{E}-02$
Po210	Po210	1.000	3.538 ± 0.164	$1.19\text{E}-01$

Activity reported as of May 01, 2000 15:37:58

ANALYSIS REVIEWED BY:

APPROVED BY:

spike activity:
22,790 d/m
Pu 239

48

OASIS - MCA

File

Edit

View

Acq Params

Tools

Reports

Close

Help

Library:

DAS_STD.MDB

Nuclide:

Am241

Acq ALL

Acquire

Stop

4096

LOG

☐ Lin

☒ Log

☐ Sqrt

Peak

Presets

ROIs

Controls

Display

Info

Aux Disp

0

4095

PRESETS

Real Time (secs)	Live Time (secs)	Peak (cnts)	Integral (cnts)	Region to Use	<input type="checkbox"/> Enable Presets
				0	

Energy: 5174.5

Counts: 1

ROI:

Integral: 537

Peak: 5,234.46

FWHM: 3.35


00A1148-0006.001

Final Survey NE Electra Scan & Investigation Survey Map

Survey Area: NA	Survey Unit: EXTERIOR	Building: T881B
Survey Unit Description: Roof Sample Location		
RCT Initials/Date: <i>mg</i> 3/28/00	RCT Initials/Date: NA	RCT Initials/Date: NA

Refer to the Final Survey NE Electra Scan & Investigation Survey Form for instrumentation, surveyor & approval information.

Legend: "R"- Roof, "W" - West Wall, "S" - South Wall, "E" - East Wall, "N" - North Wall
"C" - Ceiling, "F" - Floor



⊗ SAMPLE CUTOUT

* Designates corner closest to A-1 point of reference

Results/Comments:

Electra alpha scans were performed at the locations detailed on the survey map(s). All required accessible areas were scanned. All initial scan results were <225 dpm/100cm², unless noted on the survey form.

Electra beta scans were performed in required accessible areas. Initial scan results indicated no detectable activity above background unless noted on the survey form.


50

B-2

T881B – Radiological Survey Data for Interior Survey Unit

- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results - Detail

LOCATION: 6A2




NOTE: SEW LOCATIONS WITH ²⁻⁹⁻¹⁵⁻⁰⁰ ~~WERE~~ ^{WERE} CLOSED BASED ON MOST LIKELY TO FIND CONTAMINATION DUE TO THEIR "HIGH TRAFFIC" LIKELIHOOD IN THESE AREAS.

PAGE 3 OF 8

3-127



SURVEY PACKAGE SURVEY MAP



Total Surface Area = 196 m²

10% Scan Surface Area = 20 m²

 = one square meter

= direct & swipe

Survey Area: N/A Survey Unit: INTERIOR Building: T881B
 Survey Unit Description FLOORS, WALLS, + CEILINGS OF TRAILER T881B

Total Surface Activity Data Sheet

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts (cpm)		Net Activity (dpm/100cm2)	
		α	β	α	β	α	β	α	β	α	β	α	β
Room 1	1			90	90								
E-2W	1	7	7	90	90	2.0	477	3.3	371	1.3	-106	6	-345
K-2W	1	7	7	90	90	0.0	370	1.3	336	1.3	-34	6	-111
A-2F	1	7	7	90	90	3.3	468	2.7	525	-0.6	57	-3	186
A-3F	1	7	7	90	90	0.0	454	4.0	498	4.0	44	19	143
B-2F	1	7	7	90	90	1.3	444	2.0	508	0.7	64	3	208
C-1F	1	7	7	90	90	2.7	489	2.7	489	0.0	0.0	0.0	0.0
Room 2	2			90	90								
B-1W	1	7	7	90	90	2.0	440	6.7	345	4.7	-95	22	-309
C-1W	1	7	7	90	90	2.0	422	2.7	345	0.7	-77	3	-251
F-2W	1	7	7	90	90	1.3	468	4.7	373	3.4	-95	16	-309
I-2W	1	7	7	90	90	2.0	444	6.7	346	4.7	-98	22	-319
L-1W	1	7	7	90	90	2.7	439	2.7	451	0.0	12	0	40 ² 39
Q-1W	1	7	7	90	90	3.3	378	3.3	427	0.0	49	0	160
Q-2W	1	7	7	90	90	1.3	470	3.3	349	2.0	-121	9	-394
X-2W	1	7	7	90	90	1.3	448	1.3	388	0.0	-60	0	-195
Y-2W	1	7	7	90	90	2.0	451	6.7	370	4.7	-81	22	-264
C-2F	1	7	7	90	90	1.3	472	3.3	512	2.0	40	9	+130
F-1F	1	7	7	90	90	0.0	477	0.7	477	0.7	0	3	0
I-2F	1	7	7	90	90	1.3	465	4.7	459	3.4	-6	16	-20
J-1F	1	7	7	90	90	1.3	444	2.0	479	0.7	35	3	114
J-2F	1	7	7	90	90	1.3	448	1.3	482	0.0	34	0	111
B-2C	3	9	9	90	90	4.0	447	4.0	465	0.0	18	0	60
C-2C	3	9	9	90	90	2.7	429	2.7	466	0.0	37	0	123
C-3C	3	9	9	90	90	1.3	431	3.3	482	2.0	51	11	169
S-1C	3	9	9	90	90	0.7	433	4.0	463	3.3	30	18	100
				90	90								
				90	90								
QC				90	90								
QC				90	90								
QC				90	90								
QC				90	90								
QC				90	90								

Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" ~ local area background.

Building: T8818

Survey Unit Description

FLOORS, WALLS, & CEILINGS OF TRAILER T881B

Total Surface Activity Data Sheet

(CONTINUATION SHEET)

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts (cpm)		Net Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β	α	β	α	β
ZOOM	3			90	90								
D-1W	1	7	7	90	90	0.7	487	1.3	427	0.6	-60	3	-195
C-3F	1	7	7	90	90	0.7	463	2.7	551	2.0	88	9	-195 ^a / ₂₈
B-ZC	3	9	9	90	90	1.3	465	2.7	433	1.4	-32	7	-106 ^a / ₁₀
C-ZC	3	9	9	90	90	2.7	425	3.3	433	0.6	8	3	27 ^c / ₂₇
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
				90	90								
K-2WQC	8	11	11	90	90	6.7	360	2.7	378	-4.0	18	-19	59
B-2FQC	8	11	11	90	90	1.3	309	2.0	525	0.7	216	3	705
C-1WQC	8	11	11	90	90	2.7	385	3.3	373	0.6	-12	3	-39
C-2FQC	8	11	11	90	90	3.3	485	0.7	531	-2.6	46	-12	150
C-3FQC	8	11	11	90	90	2.0	442	3.3	524	1.3	82	6	268

Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" ~ local area background.

B-3

T881B – Asbestos Inspector's Report

T881B

ASBESTOS INSPECTOR'S REPORT

I, the undersigned Certified Asbestos Inspector, certification # [REDACTED]
in the state of Colorado, attest to the asbestos inspection and samp
described below, for the following facility (at RFETS): Trailer 881B

General Facility Location: northeast of Building 881.

INSPECTION RESULTS

Trailer 881B is identical to T881A and did not contain any suspect friable
asbestos containing materials and no samples were collected.

SAMPLE RESULTS

None required; none taken.

Andre Gonzalez

INSPECTOR'S NAME

[Signature]

SIGNATURE

7/6/00

DATE

B-4

T881B – D&D Facility Characterization Interview Checklist

60



D&D Facility Characterization Interview Checklist

ID No.: T-881B
Date: 05/27/99
Page 1 of 2
Groups B & C Series

Check List for - Title: D&D Facility Characterization - Interviews

CRITERIA: A *D&D Characterization Protocol*, RFETS MAN-077-DDCP, Rev. 0
 A *Facility Disposition Program Manual*, RFETS MAN-076-FDPM
 A RFETS Radiological Safety Practices, January 12, 1998

Facility Name & Type (1, 2, or 3) T-881B, Group B Type 1 Facility, Trailer Office Building

Personnel Interviewed (Name & Title/Function) Daniel W. Coyne, X2820, P212-6200, Building 444, RMRS

-- Y/N --

Does a current WSRIC exist for the facility? N

If so, are there exceptions to the WSRIC as written?.....No WSRIC, No Exceptions

COMMENTS (incl. WSRIC contacts)

WSRIC Contact is James M. Schoen who is in charge of the WSRIC Reports, T130J, X3579, C-83.

Are rad surveys available that indicate current status of the facility? N

Are historical rad surveys available that indicate historical status, or evolution, of the facility? N*

COMMENT N* According to Mark R. Richards, X5148 of SSOC any historical data, which is probably at the Federal Center, would not be adequate for unrestricted release. New monitor surveys would have to be taken.

Is an HRR available for the facility?..... N

Do any other reports exist beyond the HRR (e.g., spill reports, reportable incidents, etc.) that further Characterize the facility relative to chemical &/or radiological contamination? N**

Are engineering drawings (esp. "as-builts") available?..... N

Are any nonconformances or issues with the facility status currently being tracked in PATS? N

If so, what are the issues (note in Comments, below)?

COMMENTS N* Radiological surveys may have been done, but the old data is not available.

This unit will have to be resurveyed to meet present standards for unrestricted release. N** The T-881B Trailer is not sitting on IHSS or PAC area land, as per, Nick Demos, ER Characterization/HRR Manager, X4605. Therefore, the T-881B Trailer should not have any CERCLA concerns. Engineering drawings, as-builts, do not exist for the T-881B facility and a Facility Planning sketch does exist. The Plant quit using lead based paints for office buildings in 1989, if this office facility was painted prior to 1989, lead based paints may have been used.

Have any types of chemical characterization, incl. asbestos, been performed recently?..... N*

If so, what types of characterization were performed (note in Comments, below)?

COMMENTS N* No asbestos characterization data exists, according to Kevin Sheehan, X7250, T-452D, Room C-1. The asbestos data reports are located in Cubicle C-13, of T-452D and the reports are under the control of Kevin Sheehan.

Interviewed by: J. R. Sheets

Print Name

JR Sheets

Signature

05/26/99

Interview Date



D&D Facility Characterization Interview Checklist

ID No.: T-881B
Date: 05/27/99
Page 2 of 2
Groups B & C Series

What timeframe did the interviewee work in the facility? N/A The interviewee did not work in this facility. The facility has been vacant for approximately 3.5 years.

Has the building configuration changed since you worked in the building? If so, in what way? ⁹

N/A The facility is still an unused office building.

What types of equipment were in the building during the interviewee's time there? N/A

Where was the equipment located? (specific rooms/areas) In the open cubicle area of the trailer, the hard wall room and office, and at either end of the trailer. The only equipment remaining in this facility is the desks and chairs in the offices and office cubicles. In addition, the trailer has a Plant Public Address System and a Fire Department Smoke Detection System.

Were any radioactive materials or metals handled in the building? If so, what types? No, none

Which equipment handled radioactive material? N/A

Were any chemicals handled in the building? If so, what types? N/A

Did any spills or uncontrolled releases of radioactive materials or chemicals occur while you were working in the facility? No, none.

Were these spills/releases cleaned-up? How were they cleaned-up? N/A

Where did these spills/releases occur? N/A

Interviewed by: J. R. Sheets / J.R. Sheets / 05/26/99
Print Name Signature Interview Date

Type 1 Facility Checklist

TYPE 1 FACILITY

BUILDING T-881B

CURRENT LANDLORD:

RFCSS

DATE OF COMPLETION:

02/29/00

ITEM	YES	NO
Does the facility contain radiological postings?		X
Does the facility contain chemical postings?		X
Are there any installed hazards?		X
Do the historical surveys (radiological and chemical) indicate the facility is clean?	X	
Are there RCRA units within the facility		X
Is there a history of the building available?	X	
Is there any equipment/furniture left in the facility?		X
Is there a future mission identified for the facility?		X
Will the facility be left unsecured after it is vacated?		X

If any answer to any of the above questions is "Yes", complete the following questions and complete the "graded" PEP in accordance with Chapter 2.

Note: An answer of "Yes" to any question, specifically one dealing with hazards, may indicate the facility is not a Type 1 Facility. Check with the D&D Programs office.

If the answer to all question is "No" complete the "graded" PEP in accordance with Chapter 2.

1. List the Radiological Hazards, location, and quantity:

Based on the historical data found and interviews taken there are no hazards in this trailer.

2. List the Chemical Hazards, location, and quantity:

None. Based on historical data and interviews taken no asbestos data exists and the paint may be lead based.

3. List the Physical Hazards:

NONE

C-1

T883A – Radiological Survey Data for Exterior Survey Unit

- Summary of Radiological Survey/Sample Results
- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results – Detail
- Laboratory Alpha Spec (Sample) Results – Detail

Radiological Survey/Sample Results for T883A

Total Surface Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-3.4	-205
MAX	51	633
MEAN	6.3	168.7
STD DEV	10.2	226.0
Exterior	# Required	# Obtained
	28	28
MIN	-2.9	-237
MAX	128.4	458
MEAN	64.2	124.3
STD DEV	42.4	196.2
DCGL _w	100	5000

Removable Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-1.2	-46.8
MAX	3.6	44.8
MEAN	0.2	7.3
STD DEV	1.5	23.3
Exterior	# Required	# Obtained
	28	28
MIN	-1.2	-159.6
MAX	6.4	32.4
MEAN	1.0	-18.3
STD DEV	1.8	34.6
DCGL _w	20	1000

Media Sample Activity

# Required	# Obtained
2	2


<u>Contaminant</u>	<u>Y/N</u>	<u>Det. Sens. dpm/100 cm²</u>
U present	N	79
Pu present	N	79

Total Po-210 Results dpm/100 cm²

MIN	71.4
MAX	122.8
MEAN	97.1
STD DEV	5.2


65

Sean Location



3 of 18

SURVEY PACKAGE SURVEY MAP



X	Y	X	Y	X	Y	X	Y
1	13	14	11	16	7	21	3
2	11	13	2	6	8	22	20
3	8	16	13	7	5	23	2
4	30	9	14	5	16	24	3
5	24	14	15	8	8	25	20
6	8	7	16	5	12	26	6
7	15	3	17	17	15	27	14
8	28	13	8	6	12	28	11
9	7	11	19	17	7		
10	4	16	20	7	7		

□ = one square meter
 ■ = direct & swipe

X-Coordinate	Y-Coordinate
24	9

Total Surface Area = 340 m²
 10% Scan Surface Area = 34 m²

97/242 RO

68.

Building: T883A

Exterior WALLS

Removable Contamination Data Sheet

A-3E

Building: T883A

Exterior Roof

Sample Location	RCT ID #	Inst ID #		Gross Counts (gcpm)		Net Counts (cpm)		Removable Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β
B-18R	3	5	6	0.0	38	-0.3	-4.4	-0.91	-17.6
C-5R	3	5	6	0.0	38.5	-0.3	-3.9	-0.91	-15.6
C-13R	3	5	6	1.0	32.5	0.7	-3.9	2.1	-15.6
D-5R	3	5	6	1.0	36	0.7	-6.4	2.1	-25.6
E-5R	3	5	6	0.0	34	-0.3	-8.4	-0.91	-33.6
E-9R	3	5	6	1.0	38.5	0.7	-3.9	2.1	-15.6
F-9R	3	5	6	0.0	39	-0.3	-3.4	-0.91	-13.6
F-13R	3	5	6	1.5	38.5	1.2	-3.9	3.6	-15.6
F-14R	3	5	6	0.5	32.5	0.2	-9.9	0.6	-39.6
F-20R	3	5	6	1.5	39	1.2	-3.4	3.6	-13.6
G-10R	3	5	6	0.5	32.5	0.2	-9.9	0.6	-39.6
G-14R	3	5	6	1.5	32.5	1.2	-9.9	3.6	-39.6
G-16R	3	5	6	0.0	38	-0.3	-4.4	-0.91	-17.6
H-5R	3	5	6	0.5	33	0.2	-9.4	0.6	-37.6
H-13R	3	5	6	0.0	36	-0.3	-6.4	-0.91	-25.6
NA									

70

Survey Area: NA	Survey Unit: EXTERIOR	Building: 883A
Survey Unit Description EXTERIOR WALLS AND CEILING ROOF		

Total Surface Activity Data Sheet

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts (cpm)		Net Activity (dpm/100cm2)	
		α	β	α	β	α	β	α	β	α	β	α	β
A-1 NW	1	8	8	90	90	2.7	294	12.0	294	9.3	0	45.0	0
D-3 NW	1			90	90	3.3	322	8.7	343	5.4	21	26.2	69
E-1 NW	1			90	90	5.3	303	11.3	335	6.0	32	24.2	105
F-3 WW	1			90	90	3.3	424	12.0	377	8.7	-52	42.2	-171
I-3 WW	1			90	90	4.0	387	8.7	327	4.7	-60	22.8	-197
L-1 WW	1			90	90	11.3	306	14.7	329	3.4	23	16.3	75
V-1 WW	1			90	90	5.3	363	18.0	367	12.7	4	61.7	13
A-3 EW	1			90	90	5.3	333	9.3	331	4.0	-2	19.4	-7
C-2 EW	1			90	90	3.3	336	10.7	313	7.4	-23	35.9	-75
I-1 EW	1			90	90	4.7	277	4.7	298	0	21	0	69
L-3 EW	1			90	90	7.3	307	12.7	323	5.4	16	26.2	53
P-2 EW	1	✓	✓	90	90	5.3	319	4.7	325	-0.6	6	-2.9	20
T-3 EW	1	8	8	90	90	2.7	314	26.8	332	24.1	13	110.7	43
B-13R	2	11	11	90	90	2.3	366	24.7	464	22.4	98	100.2	322
C-5R	2	11	11	90	90	4.7	381	27.3	447	22.6	66	101.1	217
C-13R	2	11	11	90	90	5.3	359	29.3	495	24.0	136	107.4	255
D-5R	2	11	11	90	90	2.7	360	31.3	478	28.6	118	128.0	422
E-5R	2	11	11	90	90	3.3	343	30.7	426	27.4	83	122.6	273
E-9R	2	11	11	90	90	2.0	366	26.0	440	24.0	74	107.4	244
F-9R	2	11	11	90	90	3.3	326	28.0	409	24.7	83	110.5	273
F-13R	2	11	11	90	90	7.3	469	26.0	432	18.7	-37	83.7	-122
F-14R	2	11	11	90	90	11.3	358	26.0	497	14.7	139	65.8	458
F-20R	2	11	11	90	90	4.0	469	30.7	397	26.7	-72	119.5	-237
G-10R	2	11	11	90	90	3.3	344	32.0	455	28.7	111	128.4	366
G-14R	2	11	11	90	90	3.3	315	24.7	406	21.4	91	95.7	300
G-16R	2	11	11	90	90	6.0	332	25.3	440	19.3	108	86.4	356
H-5R	2	11	11	90	90	4.0	364	16.7	386	12.7	22	98.2	72
H-13R	2	11	11	90	90	6.0	444	18	453	12.0	9	48.3	30
V-14QC	8	9	9	90	90	2.0	403	5.3	371	3.3	-32	15.4	-107
L-14QC	8			90	90	2.7	511	6.0	328	3.3	-183	15.4	-611
E-14QC	8			90	90	5.3	435	10.0	337	4.7	-98	21.9	-327
T-14QC	8			90	90	6.0	292	8.7	321	2.7	29	12.6	96.9
CZ-EQC	8	9	9	90	90	3.3	469	9.3	329	6	-140	27.9	-467.6





Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" ~ local area background.

Final Survey NE Electra Scan & Investigation Survey Map

Survey Area: <i>NA</i>	Survey Unit: <i>EXTERIOR</i>	Building: <i>T883A</i>
Survey Unit Description: <i>ROOF 9 PT INVESTIGATION SCAN</i>		
RCT Initials/Date: <i>PC 3-3-00</i>	RCT Initials/Date: <i>NA</i>	RCT Initials/Date: <i>NA</i>

Refer to the Final Survey NE Electra Scan & Investigation Survey Form for instrumentation, surveyor & approval information.

Legend: "R"- Roof, "W" - West Wall, "S" - South Wall, "E" - East Wall, "N" - North Wall
"C" - Ceiling, "F" - Floor



* Designates corner closest to A-1 point of reference

Results/Comments:

Electra alpha scans were performed at the locations detailed on the survey map(s). All required accessible areas were scanned. All initial scan results were <225 dpm/100cm², unless noted on the survey form.

Electra beta scans were performed in required accessible areas. Initial scan results indicated no detectable activity above background unless noted on the survey form.

**Final Survey NE Electra
Scan & Investigation Survey Form
(Continuation Sheet)**

[illegible]

Rev. 020900

c:\Final Survey\DPElectraSurvey020900.doc

Page 3 of 5

Oasis Device # 2

RFETS; Golden, CO
Apr 21, 2000 15:18:44

Sample ID: 881A 00A1148-007.001 Type: Unknown
Batch ID: unknown
Acquisition Start: April 21, 2000 07:40:11
Analysis Date: April 21, 2000 15:12:57
Procedure: polonium210 samples
Device: Oasis:02:04
Analysis Method: ROI Analysis
Spectrum File: 00000298.OXS LiveTime: 10,800.00

Calibrations:

Energy = $1.412\text{E}+02 + 2.389\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998
Calibration Date: April 05, 2000 09:30:14 Std: AS 4188
Shape not Calibrated.
Efficiency = $3.398\text{E}-01 \pm 4.596\text{E}-03$
Calibration Date: April 05, 2000 09:40:39 Std: AS 4188

External Recovery No Ext.Recovery

Original Sample Amount:

1.000 ± 0.000 samp

Aliquot Amount:

1.000 ± 0.000 samp

ROI DATA

ROI ID	ASSOCIATED	EXTENTS	PK EN	FWHM	
#	NUCLIDE	START	END	(keV)	(keV)
1 Po218	Po218	5552.6	6077.8	5815.3	2.4
2 Po214	Po214	7420.0	7770.1	7595.2	1.2
3 Po212		8521.5	8850.6	8684.6	1.2
4 Po210	Po210	2263.7	5402.1	5026.9	2.4

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	1.3 ± 1.5	0.72	$7.14\text{E}-03 \pm 8.10\text{E}-03$	Unknown
Po214	-0.2 ± 0.2	0.18	$-9.93\text{E}-04 \pm 9.93\text{E}-04$	Unknown
Po212	-0.4 ± 0.3	0.36	$-1.99\text{E}-03 \pm 1.40\text{E}-03$	Unknown
Po210	210.7 ± 15.2	17.34	1.170 ± 0.084	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY	MDA
			(dpm/samp)	(dpm)
Po218	Po218	1.000	0.021 ± 0.024	$9.36\text{E}-02$
Po214	Po214	1.000	$-2.92\text{E}-03 \pm 2.92\text{E}-03$	$6.89\text{E}-02$
Po212		1.000	$-5.85\text{E}-03 \pm 4.13\text{E}-03$	$7.92\text{E}-02$
Po210	Po210	1.000	3.444 ± 0.253	$2.87\text{E}-01$

Activity reported as of April 21, 2000 07:40:11

ANALYSIS REVIEWED BY:

APPROVED BY:

Sample ID: 00A1148-008.001

Type: Unknown

Batch ID: unknowns
Acquisition Start: May 02, 2000 16:31:11
Analysis Date: May 03, 2000 08:08:44
Procedure: Po210 count
Device: Oasis:01:02
Analysis Method: ROI Analysis
Spectrum File: 00000517.OXS

LiveTime: 28,800.00

Calibrations:

Energy = $5.823\text{E}+01 + 2.790\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998
Calibration Date: April 07, 2000 14:55:56 Std: 1:2 energy cal
Shape not Calibrated.
Efficiency = $3.089\text{E}-01 \pm 4.062\text{E}-03$
Calibration Date: April 07, 2000 15:15:30 Std: TS4189

External Recovery No Ext.Recovery

Original Sample Amount:

1.000 ± 0.000 samp

Aliquot Amount:

1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS START END	PK EN (keV)	FWHM (keV)
1 Po218	Po218	5550.0 6104.5	5826.0	2.8
2 Po214	Po214	6588.5 7874.7	7229.6	2.8
3 Po212	Po212	8393.8 8808.6	8599.7	2.8
4 Po210	Po210	2180.3 5343.3	5245.6	6.5

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	6.0 ± 2.4	0.00	$0.013 \pm 5.10\text{E}-03$	Unknown
Po214	0.3 ± 1.2	0.68	$6.58\text{E}-04 \pm 2.52\text{E}-03$	Unknown
Po212	3.0 ± 1.7	0.00	$6.25\text{E}-03 \pm 3.61\text{E}-03$	Unknown
Po210	278.7 ± 30.0	12.31	1.831 ± 0.062	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm)
Po218	Po218	1.000	0.040 ± 0.017	$1.82\text{E}-02$
Po214	Po214	1.000	$2.13\text{E}-03 \pm 8.17\text{E}-03$	$4.21\text{E}-02$
Po212	Po212	1.000	0.020 ± 0.012	$1.82\text{E}-02$
Po210	Po210	1.000	5.926 ± 0.217	$1.19\text{E}-01$

Activity reported as of May 02, 2000 16:31:11

ANALYSIS REVIEWED BY:

APPROVED BY:

spike value:
22.892 dpm
Pu 239

90210
8-11

OASIS - MCA

File Edit View Acq Params Tools Reports Close Help

Library: DAS_STD.MDB

Nuclide: Am241

Acq ALL
Acquire
Stop
Pretels

4096

LOG

☐ Lin ☒ Log
☐ Sqrt

Peak

Pretels
ROIs
Controls
Display
Info
Aux Disp

0

4095

Spectrum ID
00A1148-008.001

System Date
03-May-2000 08:19:17

Message Window

Channel: 1638

Elapsed Real Time: 28800.77

Elapsed Live Time: 28800.00

Dead Time: 0.0

Energy: 4797.3

Counts: 2

ROI:

Integral: 891

Peak: 5245.63

FWHM: 6.51

77

Sample ID: 00A1148-009.001

Type: Unknown

Batch ID: unknowns

Acquisition Start: May 03, 2000 08:42:23

Analysis Date: May 03, 2000 16:42:46

Procedure: Po210 count

Device: Oasis:01:04

Analysis Method: ROI Analysis

Spectrum File: 00000527.OXS

LiveTime: 28,800.00

Calibrations:

Energy = $8.600\text{E}+01 + 2.746\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998

Calibration Date: April 12, 2000 10:28:56 Std: 1:4 energy cal

Shape not Calibrated.

Efficiency = $3.084\text{E}-01 \pm 4.055\text{E}-03$

Calibration Date: April 12, 2000 11:45:10 Std: TS4189

External Recovery No Ext.Recovery

Original Sample Amount:

1.000 ± 0.000 samp

Aliquot Amount:

1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS START	EXTENTS END	PK EN (keV)	FWHM (keV)
1 Po218	Po218	5550.0	6104.5	5826.2	2.7
2 Po214	Po214	6588.5	7874.7	7232.4	15.8
3 Po212	Po212	8393.8	8808.6	8600.1	2.7
4 Po210	Po210	2180.3	5343.3	5186.2	3.6

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	2.7 ± 2.2	1.33	$5.56\text{E}-03 \pm 4.61\text{E}-03$	Unknown
Po214	-0.7 ± 0.7	0.67	$-1.39\text{E}-03 \pm 1.39\text{E}-03$	Unknown
Po212	6.0 ± 2.4	0.00	$0.013 \pm 5.10\text{E}-03$	Unknown
Po210	552.7 ± 23.9	11.33	1.151 ± 0.050	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm)
Po218	Po218	1.000	0.018 ± 0.015	$5.14\text{E}-02$
Po214	Po214	1.000	$-4.50\text{E}-03 \pm 4.50\text{E}-03$	$4.17\text{E}-02$
Po212	Po212	1.000	0.041 ± 0.017	$1.83\text{E}-02$
Po210	Po210	1.000	3.734 ± 0.169	$1.15\text{E}-01$

Activity reported as of May 03, 2000 08:42:23

ANALYSIS REVIEWED BY:

[Signature]

APPROVED BY:

CJ Bianconi 5/8/00

Library: DAS_STD.MDB Nuclide: Am241

2-Static: 00000527.DXS


Acq ALL
Acquire
Stop
Exit

4096

LOG
☐ Lin ☒ Log
☐ Sqrt

Peak

Presets
ROIs
Controls
Display
Info
Aux Disp



Spectrum ID: 00A1148-009.001

System Date: 09-May-2000 15:15:11

Channel: 1534 Elapsed Real Time: 28801.17 Elapsed Live Time: 28800.00 Dead Time: 0.0


Energy: 4298.6 Counts: 0 ROI: Integral: 564 Peak: 5,186.24 FWHM: 3.57

Final Survey NE Electra Scan & Investigation Survey Map

Survey Area: <u>NA</u>	Survey Unit: <u>EXTERIOR</u>	Building: <u>T883A</u>
Survey Unit Description: <u>Roof Sample Location</u>		
RCT Initials/Date: <u>NA</u> 3-28-00	RCT Initials/Date: <u>NA</u>	RCT Initials/Date: <u>NA</u>

Refer to the Final Survey NE Electra Scan & Investigation Survey Form for instrumentation, surveyor & approval information.

Legend: "R"- Roof, "W" - West Wall, "S" - South Wall, "E" - East Wall, "N" - North Wall
"C" - Ceiling, "F" - Floor



⊗ SAMPLE CUTOUT

* Designates corner closest to A-1 point of reference

Results/Comments:

Electra alpha scans were performed at the locations detailed on the survey map(s). All required accessible areas were scanned. All initial scan results were <225 dpm/100cm², unless noted on the survey form.

Electra beta scans were performed in required accessible areas. Initial scan results indicated no detectable activity above background unless noted on the survey form.

Removable Contamination Data Sheet

[illegible]


C-2

T883A – Radiological Survey Data for Interior Survey Unit


- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results - Detail

ROOF SAMPLE LOCATIONS


T883A Main Area




South Office




North Office




Southeast Closet



South Wall




East Wall




South Wall



East Wall




South Wall




East Wall



T883A Floor



T883A Ceiling



1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

X-Coordinate	Y-Coordinate
10	11

Total Surface Area = 546 m²

10% Scan Surface Area = 54.6 m²

□ = one square meter

■ = direct & swipe

X	Y	X	Y	X	Y
1	2	11	16	21	20
2	23	12	3	26	27
3	7	13	17	2	23
4	24	14	13	29	24
5	18	15	17	3	25
6	8	16	5	18	26
7	11	9	17	16	3
8	19	26	18	14	11
9	15	4	19	16	8
10	3	7	20	25	4

Building: T883A

INTERIOR WALLS, Floor, and Ceiling

Removable Contamination Data Sheet									
Sample Location	RCT ID #	Inst ID #		Gross Counts (gcpm)		Net Counts (cpm)		Removable Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β
B.21.C	2	1	2	1	41.5	.6	3.7	1.8	14.8
E.16.C	2	3	4	0	44.5	-.3	4.8	-0.9	19.2
C.12.C	2	1	2	0	46	-.4	8.2	-1.2	32.8
H.11.C	2	3	4	.5	34.5	.2	-5.2	0.6	-20.8
G.16.C	2	1	2	1.5	36.5	1.1	-1.3	3.3	-5.2
F.6.C	2	3	4	1.5	30.5	1.2	-9.2	3.6	-36.8
D.4.C	2	1	2	.5	44.5	.1	6.7	0.3	26.8
H.5.C	2	3	4	1	38	.7	-1.7	2.1	-6.8
A.3.C	2	1	2	0	42.5	-.4	4.7	-1.2	18.8
AC.2.W	2	3	4	0	33	-.3	-6.7	-0.9	-26.8
AA.1.W	2	1	2	0	39	-.4	1.2	-1.2	4.8
Q.1.W	2	3	4	0	38	-.3	-1.7	-0.9	-6.8
R.2.W	2	1	2	.5	48.5	.1	10.7	0.3	42.8
W	2	3	4	0	36	-.3	-3.7	-0.9	-14.8
S	2	1	2	.5	40	.1	2.2	0.3	8.8
V.2.E	2	3	4	0	28	-.3	-11.7	-0.9	-46.8
H.15.F	2	1	2	.5	43	.1	5.2	0.3	20.8
E.14.F	2	3	4	.5	35.5	.2	-4.2	0.6	-12.8-16.8
B.11.F	2	1	2	0	44	-.4	6.2	-1.2	-1.2 24.8
G.11.F	2	3	4	.5	44	.2	4.3	0.6	0.6 17.2
C.6.F	2	1	2	1	47.5	.6	9.7	1.8	38.8
B.6.F	2	3	4	1.5	44	1.2	4.3	3.6	17.2
E.6.F	2	1	2	.5	42	.1	4.2	0.3	-12.8 16.8
H.3.F	2	3	4	0	38.5	-.3	-1.2	-0.9	-4.8
North Office									
B.1.W	2	1	2	0	43	-.4	5.2	-1.2	20.8
B.2.S	2	3	4	.5	41	.2	1.3	0.6	5.2
South Office + 2									
C.2.N	2	1	2	0	49	-.4	11.2	-1.2	44.8
Southeast Closet									
A.1.W	2	3	4	0	43.5	-.3	3.8	-0.9	15.2

Survey Area: NA

Survey Unit: Interior

Building: 883A

Survey Unit Description

Interior Floor, Walls, Ceiling

Total Surface Activity Data Sheet

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts # (cpm)		Net Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β	α	β	α	β
MAIN AREA				90	90								
B-6F	3	8	8	90	90	2.0	403	2.7	417	0.7	14	3.4	47.8 47
C-6F	3	8	8	90	90	0.7	410	0.7	422	0.0	12	0.0	40.3 40
B-11F	3	8	8	90	90	2.0	423	2.7	534	0.7	111	3.4	374
E-6F	3	8	8	90	90	3.3	407	32.0	479	28.7	72	140.3	242
E-14F	3	8	8	90	90	1.3	383	0.7	451	-0.6	68	-2.9	229
G-11F	3	8	8	90	90	1.3	429	2.0	455	0.7	26	3.4	88
H-3F	3	8	8	90	90	0.7	437	0.0	457	-0.7	20	-3.4	67
H-15F	3	8	8	90	90	2.0	414	2.0	457	0.0	43	0.0	145
Q-1W	3	8	8	90	90	2.7	342	3.3	314	0.6	-28	2.9	-94
Z-2W	3	8	8	90	90	2.0	318	2.7	332	0.7	14	3.4	47
S-2W	3	8	8	90	90	2.7	360	3.3	300	0.6	-60	2.9	-202
AA-1W	3	8	8	90	90	1.3	312	0.7	330	-0.6	18	-2.9	61
AC-2W	3	8	8	90	90	2.0	300	4.7	328	2.7	28	13.2	94
Y-2E	3	8	8	90	90	3.3	370	2.7	319	-0.6	51	-2.9	172
H-1S	3	8	8	90	90	2.0	327	2.7	344	0.7	17	3.4	57
A-3C	3	8	8	90	90	2.0	383	4.0	537	2.0	154	9.8	519
B-21C	3	8	8	90	90	1.3	407	3.3	478	2.0	71	9.8	239
C-12C	3	8	8	90	90	2.7	412	4.7	510	2.0	98	9.8	330
D-4C	3	8	8	90	90	0.7	336	1.3	524	0.6	188	2.9	633
E-16C	3	8	8	90	90	2.0	374	2.0	478	0.0	104	0.0	350
F-6C	3	8	8	90	90	2.7	360	3.3	497	0.6	137	2.9	461
G-16C	3	8	8	90	90	0.7	407	2.7	522	2.0	115	9.8	387
H-5C	3	8	8	90	90	0.0	328	2.0	476	2.0	148	9.8	498
H-11C	3	8	8	90	90	1.3	391	2.7	466	1.4	75	6.8	253
NORTH OFFICE				90	90								
B-1W	3	8	8	90	90	0.7	387	2.7	326	2.0	-61	9.8	-205
B-2S	3	8	8	90	90	0.7	348	5.3	301	4.6	-47	22.5	-158
E-6FQC	8	11	11	90	90	5.3	386	11.3	448	6.0 3.8	62	27.3 3.8	207
G-11FQC	8	11	11	90	90	4.7	425	4.3	414	-0.4	-11	-1.9	36.7 37
E-14FQC	8	11	11	90	90	6.7	460	8.7	473	2.0	13	9.3	43.4 43
B-11FQC	8	11	11	90	90	6.0	423	2.0	493	-4.0	70	-18.6	233.8 234
B-6FQC	8	11	11	90	90	6.0	392	4.7	414	-1.3	22	-6.0	73.5 73

Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" - local area background.

[illegible]

Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" ~ local area background.

Final Survey NE Electra Scan & Investigation Survey Map

Survey Area: <u>NA</u>	Survey Unit: <u>INTERIOR</u>	Building: <u>T-883A</u>
Survey Unit Description: <u>INTERIOR FLOOR</u>		
RCT Initials/Date: <u>ASC / 3.1.00</u>	RCT Initials/Date: <u>N/A</u>	RCT Initials/Date: <u>N/A</u>

Refer to the Final Survey NE Electra Scan & Investigation Survey Form for instrumentation, surveyor & approval information.

Legend: "R" - Roof, "W" - West Wall, "S" - South Wall, "E" - East Wall, "N" - North Wall
"C" - Ceiling, "F" - Floor

DSF

DSF 90 seconds PAT AREA

1A 1B 1C
1D 1E 1F
1G 1H 1I

N
A

* Designates corner closest to A-1 point of reference

Results/Comments:

Electra alpha scans were performed at the locations detailed on the survey map(s). All required accessible areas were scanned. All initial scan results were <225 dpm/100cm², unless noted on the survey form.

Electra beta scans were performed in required accessible areas. Initial scan results indicated no detectable activity above background unless noted on the survey form.

**Final Survey NE Electra
Scan & Investigation Survey Form
(Continuation Sheet)**

Survey Area:		Survey Unit:		Building:					
NA		INTERIOR		T883A					
Survey Unit Description:									
INTERIOR FLOOR SCANS									
Loc. ID #	Electra DP-6 Beta				Electra DP-6 Alpha				
	RCT ID #	Inst. ID #	Elevated Audible observed? "Y" or "N"	60-sec PAT (dpm/100cm ²)	RCT ID #	Inst. ID #	4-sec Audible observed? "Y" or "N"	30-sec Static (gcpm)	90-sec PAT (dpm/100cm ²)
E-7F	1	7	N	NA	1	7	N	NA	NA
G-1F					3	8	N	NA	
B-1F1					3	8	Y	8	
B-2F1					3	8	Y	10	
E-4F					4	9	N	NA	
H-4F					4	9	N		
G-4F					4	9	N		
F-4F					4	9	N	Y	
B-3F1					5	10	Y	12.0	
B-4F1					5	10	Y	14.0	
A-5F					5	10	N	NA	
B-5F					5	10	N		
C-5F	Y	Y	Y	Y	5	10	N	Y	Y
NA									

C-3

T883A – Asbestos Inspector's Report

T883A

ASBESTOS INSPECTOR'S REPORT

I, the undersigned Certified Asbestos Inspector, certification # [REDACTED] in the state of Colorado, attest to the asbestos inspection and sampling results as described below, for the following facility (at RFETS): Trailer 883A.

General Facility Location: north-northeast of Building 881.

INSPECTION RESULTS

Trailer 883A contains friable ceiling tile. Fiberglass insulation was found throughout the walls. The following table summarizes the results of the samples collected and the percent and type of asbestos detected:

SAMPLE RESULTS

Sample Number	Material Sampled & Location	Analytical Results
T883A-03012000-05-001	Miscellaneous material: 2' x 4' white ceiling tile. Coordinate D4C	None Detected
T883A-03012000-05-002	Miscellaneous material: 2' x 4' white ceiling tile. Coordinate C12C	None Detected

Andre Gonzalez

INSPECTOR'S NAME

Andre Gonzalez

SIGNATURE

7/6/00

DATE

C-4

T883A – D&D Facility Characterization Interview Checklist



D&D Facility Characterization Interview Checklist

ID No.: T-883A
Date: 06/08/99
Page 1 of 2
Groups B & C Series

Check List for - Title: D&D Facility Characterization - Interviews

CRITERIA: A D&D Characterization Protocol, RFETS MAN-077-DDCP, Rev. 0
 A Facility Disposition Program Manual, RFETS MAN-076-FDPM
 A RFETS Radiological Safety Practices, January 12, 1998

Facility Name & Type (1, 2, or 3) T-883A Group B Type 1 Facility, Trailer Office Building
Personnel Interviewed (Name & Title/Function) Leslie Dustin, X3599, Senior Specialist, Residue Stabilization, P-212-4455, T-115A, Cube 2, SSOC Residue Stabilization

-- Y/N --

Does a current WSRIC exist for the facility? N
If so, are there exceptions to the WSRIC as written? No WSRIC, No Exceptions

COMMENTS (incl. WSRIC contacts)

WSRIC Contact is James M. Schoen who is in charge of the WSRIC Reports, T130J, X3579, C-83.

Are rad surveys available that indicate current status of the facility? N
Are historical rad surveys available that indicate historical status, or evolution, of the facility? N*

COMMENT N* According to Mark R. Richards, X5148 of SSOC any
Historical data, which is probably at the Federal Center, would not be
Adequate for unrestricted release. New monitor surveys would have to be taken.

Is an HRR available for the facility? N

Do any other reports exist beyond the HRR (e.g., spill reports, reportable incidents, etc.) that further
Characterize the facility relative to chemical &/or radiological contamination? Y**

Are engineering drawings (esp. "as-builts") available? N

Are any nonconformances or issues with the facility status currently being tracked in PATS? N

If so, what are the issues (note in Comments, below)?

COMMENTS N* Radiological surveys may have been done, but the old data is not available.
This unit will have to be resurveyed to meet present standards for unrestricted release. Y** The T-883A
Trailer is not sitting on IHSS or PAC area land, as per, Nick Demos, ER Characterization/HRR Manager, X4605.
Therefore, the T-883A Office Trailer does not have CERCLA concerns. Engineering drawings, as-builts, do not
exist for the T-883A facility. There are no PATS items outstanding for this facility. The Plant quit using lead
based paints for office buildings in 1989, if this office facility was painted prior to 1989, lead based paints
may have been used.

Have any types of chemical characterization, incl. Asbestos, been performed recently? N*

If so, what types of characterization were performed (note in Comments, below)?

COMMENTS N* No asbestos characterization data exists, according to
Kevin Sheehan, X7250, T-452D, Room C-1. The asbestos data reports are located in
Cubicle C-13, of T-452D and the reports are under the control of Kevin Sheehan.

Interviewed by: J. R. Sheets JR Sheets 06/03/99

Print Name

Signature

Interview Date



D&D Facility Characterization Interview Checklist

ID No.: T-883A
Date: 06/08/99
Page 2 of 2
Groups B & C Series

What timeframe did the interviewee work in the facility? From the Fall of 1995 until August 1997 (for approximately 2 years).

Has the building configuration changed since you worked in the building? If so, in what way? Yes, the facility had up to a maximum 15 people during the time SSOC Residue Stabilization occupied the office trailer facility.

Yes, all the office cubicles have been removed, the electrical wiring is being totally redone. It appears that the facility might be getting prepared to be a computer training facility and would hold approximately 30 people.

What types of equipment were in the building during the interviewee's time there?

Approximately 15 computers, approximately 12 printers, a fax machine, a photocopier machine, other office equipment such as desks, 12 chairs, 3 tables, bookcases, 8 file cabinets, etc

Where was the equipment located? (specific rooms/areas) In the hard wall offices and the office cubicles. The prior occupants (prior to March 1995) an Information Resource Management group that did software support for AutoCad and software support for CAD/CAM for Building 460 Machining Operations. The IR Management group had approximately 12 employees in T-883A from 1991 until March 1995. Computers, printers, fax machine, photocopier, and office equipment were in the hard wall offices and office cubicles during this 1991 to March 1995 time frame.

Were any radioactive materials or metals handled in the building? If so, what types? No, none

Which equipment handled radioactive material? N/A

Were any chemicals handled in the building? If so, what types? N/A

Did any spills or uncontrolled releases of radioactive materials or chemicals occur while you were working in the facility? No, none.

Were these spills/releases cleaned-up? How were they cleaned-up? N/A

Where did these spills/releases occur? N/A

Interviewed by: J. R. Sheets / JR Sheets / 06/03/99
Print Name Signature Interview Date

Type 1 Facility Checklist

TYPE 1 FACILITY	BUILDING T-883A
CURRENT LANDLORD:	RFCSS
DATE OF COMPLETION:	02/29/00

ITEM	YES	NO
Does the facility contain radiological postings?		X
Does the facility contain chemical postings?		X
Are there any installed hazards?		X
Do the historical surveys (radiological and chemical) indicate the facility is clean?	X	
Are there RCRA units within the facility		X
Is there a history of the building available?	X	
Is there any equipment/furniture left in the facility?		X
Is there a future mission identified for the facility?		X
Will the facility be left unsecured after it is vacated?		X

If any answer to any of the above questions is "Yes", complete the following questions and complete the "graded" PEP in accordance with Chapter 2.

Note: An answer of "Yes" to any question, specifically one dealing with hazards, may indicate the facility is not a Type 1 Facility. Check with the D&D Programs office.

If the answer to all question is "No" complete the "graded" PEP in accordance with Chapter 2.

1. List the Radiological Hazards, location, and quantity:

Based on the historical data found and interviews taken there are no hazards in this trailer.

2. List the Chemical Hazards, location, and quantity:

None. Based on historical data and interviews taken no asbestos data exists and the paint may be lead based.

3. List the Physical Hazards:

NONE

D-1

T883B – Radiological Survey Data for Exterior Survey Unit

- Summary of Radiological Survey/Sample Results
- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results – Detail
- Laboratory Alpha Spec (Sample) Results – Detail

Radiological Survey/Sample Results for T883B

Total Surface Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-3.1	-356
MAX	33	405
MEAN	14.5	-51.0
STD DEV	10.8	225.0
Exterior	# Required	# Obtained
	28	28
MIN	0.0	-295
MAX	137.4	392
MEAN	64.2	71.7
STD DEV	40.2	211.7
DCGL _w	100	5000

Removable Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-1.5	-45
MAX	0.0	24
MEAN	-0.7	-10.5
STD DEV	1.0	15.3
Exterior	# Required	# Obtained
	28	28
MIN	-0.9	-39.6
MAX	5.5	43.2
MEAN	1.5	-1.5
STD DEV	1.9	21.6
DCGL _w	20	1000

Media Sample Activity


# Required	# Obtained
2	2

<u>Contaminant</u>	<u>Y/N</u>	<u>Det. Sens. dpm/100 cm²</u>
U present	N	79
Pu present	N	79

Total Po-210 Results dpm/100 cm²

MIN	85.7
MAX	89.8
MEAN	87.8
STD DEV	5.8

SURVEY PACKAGE SURVEY MAP



X Coordinate	Y Coordinate
30	5

□ = one square meter
 ■ = direct & swipe


X	Y	X	Y	X	Y
1	25	7	23	14	21
2	20	2	6	6	22
3	15	9	15	13	23
4	2	8	1	12	24
5	14	14	4	5	25
6	30	14	16	24	9
7	6	1	27	2	27
8	4	17	8	2	28
9	16	14	4	9	
10	6	13	20	4	13

Total Surface Area = 340 m²


10% Scan Surface Area = 34 m²

"X" Represents Scan Locations


T883B Main Area




Southwest Office




West Middle Office




Northwest Office




Bathroom



T883B Floor




T883B Ceiling



- = one square meter
- = 1.5"/sec scan
- = direct & smear
- = additional QA survey


X	Y	QA readings
1	9	1
2	10	2
3	11	3
4	12	4
5	13	5
6	14	
7	15	
8	16	



NOTE: SCAN AREA DETERMINED UPON HIGH TIDALIC READINGS.

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42

Survey Image Coverage Survey Map



X-Coordinate	Y-Coordinate
30	5

□ = one square meter

■ = direct & swipe

Total Surface Area = 340 m²

10% Scan Surface Area = 34 m²

X	Y	X	Y	X	Y			
25	7	23	14	21	7	12		
2	20	2	6	6	22	7	5	
3	15	9	3	15	13	23	14	3
4	2	8	1	12	24	8	20	
5	14	14	5	4	5	25	21	14
6	30	14	16	24	9	28	16	1
7	6	1	17	27	2	27	6	8
8	4	17	8	2	28	5	8	
9	16	14	9	4	9			
10	6	13	20	4	13			

Survey Unit: Exterior

Building: T883 R

Exterior Roof

Sample Location	RCT ID #	Inst ID #		Gross Counts (gcpm)		Net Counts (cpm)		Removable Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β
A-9R	4	5	6	0.0	39.5	-0.3	-2.9	-0.9	-11.6
B-13R	4	5	6	2.0	75	1.7	-7.4	5.2 5.1	-29.6
D-4R	4	5	6	0.0	35	-0.3	-7.4	-0.9	-29.6
D-8R	4	5	6	1.0	48	0.7	5.6	2.1	22.4
D-12R	4	5	6	1.0	46	0.7	3.6	2.1	14.4
D-16R	4	5	6	0.0	33.5	-0.3	-8.9	-0.9	-35.6
E-13R	4	5	6	1.0	38.5	0.7	-3.9	2.1	-15.6
F-8R	4	5	6	1.0	37.5	0.7	-4.9	2.1	-19.6
F-13R	4	5	6	0.0	41	-0.3	-1.4	-0.9	-5.6
F-15R	4	5	6	1.0	42.5	0.7	0.1	2.1	0.4
F-20R	4	5	6	1.0	35.5	0.7	-6.9	2.1	-27.6
G-9R	4	5	6	1.0	37	0.7	-5.4	2.1	-21.6
G-16R	4	5	6	0.0	32.5	-0.3	-9.9	-0.9	-39.6
H-1R	4	5	6	1.0	46.5	0.7	4.1	2.1	16.4
I-19R	4	5	6	0.0	38	-0.3	-4.4	-0.9	-17.6
NA									

Survey Area: N/A	Survey Unit: Exterior	Building: T883 B
-------------------------	------------------------------	-------------------------

Survey Unit: Exterior

Building: T883 B

Survey Unit Description

Exterior WALLS

Removable Contamination Data Sheet

Sample Location	RCT ID #	Inst ID #		Gross Counts (gcpm)		Net Counts (cpm)		Removable Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β
F.3.N	1	1	2	.5	38	.1	-4	0.3	-16
D.1.N	1	3	4	.5	48.5	.3	10.8	0.9	43.2
A.2.S	1	1	2	2	46.5	1.6	4.5	4.8	18
H.2.S	1	3	4	1.5	39.5	1.3	1.8	3.9	7.2
E.1.W	1	1	2	1	43	.6	1	1.8	4
P.1.W	1	3	4	.5	41.5	.3	3.8	0.9	15.2
Q.3.W	1	1	2	.5	43.5	.1	1.5	0.3	6
D.2.E	1	3	4	1.5	40	1.3	2.3	3.9	9.2
F.2.E	1	1	2	.5	41	.1	-1	0.3	-4
E.3.E	1	3	4	.5	43.5	.3	5.8	0.9	23.2
M.2.E	1	1	2	.5	44.5	.1	2.5	0.3	10
O.2.E	1	3	4	2	46.5	1.8	8.8	5.5	35.2
V.2.E	1	1	2	1	43.5	.6	1.5	1.8	6

Survey Area: NW	Survey Unit: EXTERIOR	Building: 82373
Survey Unit Description EXTERIOR WALL / ROOF		

Total Surface Activity Data Sheet

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts (cpm)		Net Activity (dpm/100cm2)	
		α	β	α	β	α	β	α	β	α	β	α	β
E-1 WW	2	7	7	90	90	5.7	338	6.0	327	5.3	-11	16.0	-36
P-1 WW	2			90	90	8.0	281	11.2	341	5.3	6.0	16.0	197
A-2 SW	2			90	90	2.7	323	10.7	373	8.0	5.0	38.7	164
H-2 SW	2			90	90	4.0	314	14.0	361	10.0	45	48.4	148
D-2 EW	2			90	90	3.3	323	6.7	341	3.4	18	16.4	59
F-2 EW	2			90	90	6.0	309	11.3	371	5.3	62	25.6	203
M-2 EW	2			90	90	9.3	335	16.0	375	6.7	40	32.4	131
G-2 EW	2			90	90	5.3	425	5.3	365	0.0	-64	0.0	210
V-2 EW	2			90	90	3.3	323	11.3	357	8.0	34	38.7	112
D-1 WW	2			90	90	6.0	316	8.7	351	2.7	69	13.1	226
R-3 WW	2			90	90	5.3	421	14.0	331	8.7	-98	42.1	-322
E-3 EW	2			90	90	4.7	424	16.0	353	11.3	-76	54.7	249
D-3 WW	2	7	7	90	90	6.0	338	13.3	323	7.3	-15	35.3	-49
A-9R	3	11	11	90	90	4.0	469	17.3	391	13.3	-78	59.5	-257
B-13R	3	11	11	90	90	3.3	340	18.0	403	14.7	63	65.8	208
D-4R	3	11	11	90	90	14.7	451	25.3	399	10.6	-52	47.4	-171
D-8R	3	11	11	90	90	2.7	440	25.3	436	22.6	-4	101.1	-13
D-12R	3	11	11	90	90	3.3	332	34.0	437	30.7	105	137.4	346
D-16R	3	11	11	90	90	3.3	403	17.3	441	14.0	38	62.6	125
E-13R	3	11	11	90	90	4.0	326	20.0	427	16.0	101	71.6	333
F-8R	3	11	11	90	90	6.7	340	31.3	441	24.6	101	71.6	333
F-13R	3	11	11	90	90	6.0	345	30.7	459	24.7	114	110.5	375
F-15R	3	11	11	90	90	7.3	399	34.0	454	26.7	55	119.5	181
F-20R	3	11	11	90	90	3.3	406	32.0	418	28.7	12	128.4	40
G-9R	3	11	11	90	90	7.3	360	28.0	406	20.7	46	92.6	152
G-16R	3	11	11	90	90	6.7	478	29.3	411	22.6	-67	101.1	-221
H-1R	3	11	11	90	90	2.0	366	22.7	485	20.7	119	92.6	392
H-19R	3	11	11	90	90	4.0	485	30.7	419	26.7	-66	119.5	-217
A-25QC	8	9	9	90	90	2.7	508	8.7	361	6.	-147	27.9	-491.0
H-25QC	8			90	90	2.7	439	4.0	339	1.3	-100	6.0	-334.0
D-25QC	8			90	90	3.3	411	6.7	325	3.4	-86	15.8	-287
D-19QC	8			90	90	4.0	525	12.7	333	8.7	-192	40.5	-641.3
E-19QC	8	9	9	90	90	3.3	391	4.0	287	0.7	-104	3.26	-347


Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" ~ local area background.

Final Survey NE Electra Scan & Investigation Survey Map




Survey Area: <u>NA</u>	Survey Unit: <u>EXTERIOR</u>	Building: <u>T 883 C</u>
Survey Unit Description: <u>ROOF 9 PT INVESTIGATION SCAN</u>		
RCT Initials/Date: <u>PC 3-3-00</u>	RCT Initials/Date: <u>N/A</u>	RCT Initials/Date: <u>N/A</u>

Refer to the Final Survey NE Electra Scan & Investigation Survey Form for instrumentation, surveyor & approval information.

Legend: "R"- Roof, "W" - West Wall, "S" - South Wall, "E" - East Wall, "N" - North Wall
"C" - Ceiling, "F" - Floor



H-19R



* Designates corner closest to A-1 point of reference

Results/Comments:

Electra alpha scans were performed at the locations detailed on the survey map(s). All required accessible areas were scanned. All initial scan results were <225 dpm/100cm², unless noted on the survey form.

Electra beta scans were performed in required accessible areas. Initial scan results indicated no detectable activity above background unless noted on the survey form.

Final Survey NE Electra Scan & Investigation Survey Form

Survey Area:		Survey Unit:		Building:					
NA		EXTERIOR		T 883 B					
Survey Unit Description:									
ROOF 9 PT INVESTIGATION SCAN									
Loc. ID #	Electra DP-6 Beta				Electra DP-6 Alpha				
	RCT ID #	Inst. ID #	Elevated Audible observed? "Y" or "N"	60-sec PAT (dpm/100cm ²)	RCT ID #	Inst. ID #	4-sec Audible observed? "Y" or "N"	30-sec Static (gcpm)	90-sec PAT (dpm/100cm ²)
H-19R1					1	7			23.3
H-19R2					1	7			27.3
H-19R3					1	7			17.3
H-19R4					1	7			20.0
H-19R5			N		1	7		N A	27.3
H-19R6			A		1	7			17.3
H-19R7					1	7			27.3
H-19R8					1	7			17.3
H-19R9					1	7			20.0
								1m ² Avg →	21.9
N A									

105

Oasis Device # 2

RFETS; Golden, CO
Apr 18, 2000 14:46:41

Sample ID: 883B coupon 00A1148-010.001 Type: Unknown

Batch ID: unknown

Acquisition Start: April 18, 2000 13:06:25

Analysis Date: April 18, 2000 14:46:35

Procedure: polonium210 samples

Device: Oasis:02:03

Analysis Method: ROI Analysis

Spectrum File: 00000284.OXS LiveTime: 6,005.32

Calibrations:

Energy = 1.604E+02 +2.389E+00 * Chn Coeff. of Correlation: -0.998

Calibration Date: April 04, 2000 15:34:53 Std: 2:3 energy cal

Shape not Calibrated.

Efficiency = 3.357E-01 ± 4.547E-03

Calibration Date: April 05, 2000 09:20:34 Std: AS 4188

External Recovery No Ext.Recovery

Original Sample Amount:

1.000 ± 0.000 samp

Aliquot Amount:

1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS		PK EN (keV)	FWHM (keV)
		START	END		
1 Po218	Po218	5552.6	6077.8	5815.3	1.2
2 Po214	Po214	7420.0	7770.1	7595.1	1.2
3 Po212		8521.5	8850.6	8686.9	1.2
4 Po210	Po210	2263.7	5322.8	5163.1	2.4

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	-0.1 ± 0.1	0.14	-1.39E-03 ± 1.39E-03	Unknown
Po214	-0.3 ± 0.2	0.28	-2.78E-03 ± 1.96E-03	Unknown
Po212	0.0 ± 0.0	0.00	0.00E+00 ± 0.00E+00	Unknown
Po210	140.3 ± 12.1	5.70	1.402 ± 0.121	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm)
Po218	Po218	1.000	-4.14E-03 ± 4.14E-03	1.19E-01
Po214	Po214	1.000	-8.27E-03 ± 5.85E-03	1.36E-01
Po212		1.000	0.00E+00 ± 0.00E+00	8.05E-02
Po210	Po210	1.000	4.175 ± 0.365	3.30E-01

Activity reported as of April 18, 2000 13:06:25

ANALYSIS REVIEWED BY:

APPROVED BY:



Nuclide:
Am241

5:Static: 00000284.0XS

Acq ALL

Acquire

Stop

4096

LOG

Lin Log

OSgt

Peak

Spectrum ID

8838 coupon 00A1148-010.001

System Date

11 MAY 2000 06:27:57

Message Window

channel 2327

Elastic: Heal Time: 10800.01

Time: 10800.00

0.0
ime:

Energy: 5720.1

0

ROI

Integral:

Peak:

EWING 0.00

Oasis Device # 2

RFETS; Golden, CO
Apr 24, 2000 09:54:10

Sample ID: 883B coupon 00A1148-011.001 Type: Unknown
Batch ID: unknown
Acquisition Start: April 18, 2000 13:06:24
Analysis Date: April 24, 2000 09:54:04
Procedure: polonium210 samples
Device: Oasis:02:02
Analysis Method: ROI Analysis
Spectrum File: 00000283.OXS LiveTime: 10,800.00

Calibrations:

Energy = $1.436\text{E}+01 + 2.491\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998
Calibration Date: April 04, 2000 15:25:18 Std: 2:2 energy calibration
Shape not Calibrated.
Efficiency = $3.436\text{E}-01 \pm 4.641\text{E}-03$
Calibration Date: April 05, 2000 09:05:57 Std: AS 4188

External Recovery No Ext.Recovery

Original Sample Amount:

1.000 ± 0.000 samp

Aliquot Amount:

1.000 ± 0.000 samp

ROI DATA

ROI ID	ASSOCIATED	EXTENTS	PK EN	FWHM	
#	NUCLIDE	START	END	(keV)	(keV)
1 Po218	Po218	5552.6	6077.8	5814.5	2.5
2 Po214	Po214	7420.0	7770.1	7593.4	2.5
3 Po212		8521.5	8850.6	8687.1	2.5
4 Po210	Po210	2263.7	5322.8	5159.2	4.7

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	0.5 ± 1.5	1.50	$2.78\text{E}-03 \pm 8.56\text{E}-03$	Unknown
Po214	0.3 ± 1.1	0.75	$1.39\text{E}-03 \pm 6.05\text{E}-03$	Unknown
Po212	1.0 ± 1.0	0.00	$5.56\text{E}-03 \pm 5.56\text{E}-03$	Unknown
Po210	268.0 ± 16.8	12.00	1.489 ± 0.093	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY	MDA
			(dpm/samp)	(dpm)
Po218	Po218	1.000	$8.09\text{E}-03 \pm 0.025$	$1.17\text{E}-01$
Po214	Po214	1.000	$4.04\text{E}-03 \pm 0.018$	$9.53\text{E}-02$
Po212		1.000	0.016 ± 0.016	$4.38\text{E}-02$
Po210	Po210	1.000	4.334 ± 0.278	$2.50\text{E}-01$

Activity reported as of April 18, 2000 13:06:24

ANALYSIS REVIEWED BY:

APPROVED BY:

Sample ID: 00A1148-012.001

Type: Unknown

Batch ID: unknowns
Acquisition Start: May 03, 2000 16:57:27
Analysis Date: May 04, 2000 07:06:32
Procedure: Po210 count
Device: Oasis:01:03
Analysis Method: ROI Analysis
Spectrum File: 00000538.OXS
LiveTime: 28,800.00

Calibrations:

Energy = $6.596\text{E}+01 + 2.779\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998
Calibration Date: April 24, 2000 13:03:27 Std: 1:3 Energy Cal
Shape not Calibrated.
Efficiency = $3.120\text{E}-01 \pm 4.098\text{E}-03$
Calibration Date: April 24, 2000 10:05:48 Std: TS4189

External Recovery No Ext.Recovery

Original Sample Amount:

1.000 ± 0.000 samp

Aliquot Amount:

1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS START END	PK EN (keV)	FWHM (keV)
1 Po218	Po218	5550.0 6104.5	6055.4	2.8
2 Po214	Po214	6588.5 7874.7	7231.0	2.8
3 Po212	Po212	8393.8 8808.6	8601.2	2.8
4 Po210	Po210	2180.3 5343.3	5179.9	3.9

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	18.7 ± 4.6	1.33	$0.039 \pm 9.52\text{E}-03$	Unknown
Po214	-1.7 ± 1.7	2.67	$-3.47\text{E}-03 \pm 3.47\text{E}-03$	Unknown
Po212	9.0 ± 3.0	0.00	$0.019 \pm 6.25\text{E}-03$	Unknown
Po210	836.0 ± 29.4	18.00	1.742 ± 0.061	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm)
Po218	Po218	1.000	0.125 ± 0.031	$5.08\text{E}-02$
Po214	Po214	1.000	$-1.11\text{E}-02 \pm 0.011$	$6.44\text{E}-02$
Po212	Po212	1.000	0.060 ± 0.020	$1.81\text{E}-02$
Po210	Po210	1.000	5.582 ± 0.210	$1.38\text{E}-01$

Activity reported as of May 03, 2000 16:57:27


ANALYSIS REVIEWED BY:

APPROVED BY:

[Signature]
CJ Bianconi 5/8/00

*spike value
22. 892 dpm
pv 239*

Library: **OAS_STD.MDB** Nucide: **Am241**



0 **4095**

Spectrum ID
00A1148-012.001

System Date
04-May-2000 07:02:11

Channel: 1751 **Elapsed Real Time:** 28800.05 **Elapsed Live Time:** 28800.00 **Dead Time:** 0.0

Energy: 4933.2 **Counts:** 3 **ROI:** **Integral:** 854 **Peak:** 5,179.88 **FWHM:** 3.94

Acq ALL Acquire Stop Erase

4096

LOG

☐ Lin ☒ Log ☐ Sqrt

Peak

Presets ROIs Controls Display Info Aux Disp


Final Survey NE Electra Scan & Investigation Survey Map

Survey Area: <u>NA</u>	Survey Unit: <u>EXTERIOR</u>	Building: <u>T883B</u>
Survey Unit Description: <u>Roof Sample Location</u>		
RCT Initials/Date: <u>NA 3/23/00</u>	RCT Initials/Date: <u>NA</u>	RCT Initials/Date: <u>NA</u>


Refer to the Final Survey NE Electra Scan & Investigation Survey Form for instrumentation, surveyor & approval information.

Legend: "R"- Roof, "W" - West Wall, "S" - South Wall, "E" - East Wall, "N" - North Wall
"C" - Ceiling, "F" - Floor



F-20R



H-19R



N
↓



⊗ SAMPLE CUTOFF

* Designates corner closest to A-1 point of reference

Results/Comments:

Electra alpha scans were performed at the locations detailed on the survey map(s). All required accessible areas were scanned. All initial scan results were <225 dpm/100cm², unless noted on the survey form.

Electra beta scans were performed in required accessible areas. Initial scan results indicated no detectable activity above background unless noted on the survey form.

Removable Contamination Data Sheet

[illegible]

D-2

T883B – Radiological Survey Data for Interior Survey Unit

- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results - Detail

[illegible]

South Wall

A B

East Wall



A B C

South Wall

A B





East Wall

A B C

	A	B	C	D	E	F	G	H
21								
20								
19								
18								
17								
16								
15								
14								
13								
12								
11								
10								
9								
8								
7								
6								
5								
4								
3								
2								
1								

X-Coordinate	Y-Coordinate
--------------	--------------

 = one square meter
 = 1.5"/sec scan
 = direct & smear
 = additional QA survey

X	Y
1	
2	
3	
4	
5	
6	
7	
8	

X	Y
9	
10	
11	
12	
13	
14	
15	
16	

QA readings	X	Y
1		
2		
3		
4		
5		

$\leftarrow Z$

NOTE: SCAN AREA DEFINED

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42

1. $\frac{1}{2} \times \frac{1}{2} = \frac{1}{4}$

3-292

Survey Area: N/A

Survey Unit: INTERIOR

Building: T883B

Survey Unit Description

Interior Walls, Floor, and Ceiling

Removable Contamination Data Sheet

Sample Location	RCT ID #	Inst ID #		Gross Counts (gcpm)		Net Counts (cpm)		Removable Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β
MAIN AREA									
R-2-E	2	1	2	0	45	-1.5	2.7	-1.5	11
T-2-E	2	3	4	0	34.5	-1.5	-5.0	-1.5	-20
W-2-E	2	1	2	0	38.5	-1.5	-3.8	-1.5	-15
L-2-E	2	3	4	0	40	-1.5	0.5	-1.5	2
C-2-N	2	1	2	0	39	-1.5	-3.3	-1.5	-13
E-2-N	2	3	4	0	36	-1.5	-3.5	-1.5	-14
L-1-W	2	1	2	.5	39	0	-3.3	0	-13
O-2-W	2	3	4	.5	35.5	0	-4	0	-16
AC-2-W	2	1	2	1	39	.5	-3.3	1.5	-13
AL-2-W	2	3	4	0	35.5	-1.5	-4	-1.5	-16
AH-2-W	2	1	2	0	44	-1.5	1.7	-1.5	7
U-2-W	2	3	4	0	38.5	-1.5	-1	-1.5	-4
A-R-C	2	1	2	1	43.5	.5	1.2	1.5	5
B-2-C	2	3	4	.5	37.5	0	-2	0	-8
B-16-C	2	1	2	0	31	-1.5	-11.3	-1.5	-45
C-2-C	2	3	4	.5	36.5	0	-3	0	-12
C-6-C	2	1	2	0	33.5	-1.5	-8.8	-1.5	-35
C-11-C	2	3	4	0	36	-1.5	-3.5	-1.5	-14
D-8-C	2	1	2	.5	38.5	0	-3.8	0	-15
H-8-F	2	3	4	0	39	-1.5	-1.5	-1.5	-2
F-8-F	2	1	2	.5	36.5	0	-5.8	0	-23
F-8-F	2	3	4	.5	28.5	0	-11	0	-44
D-15-F	2	1	2	.5	43.5	0	1.2	0	5
C-14-F	2	3	4	.5	35.5	0	-4	0	-16
B-13-F	2	1	2	0	43.5	-1.5	1.2	-1.5	5
G-1-E	2	3	4	.5	37	0	-2.5	0	-10
SOUTHWEST office									
B-2-W	2	1	2	.5	41	0	-1.3	0	-5
Middle office									
A-2-E	2	3	4	0	45.5	-1.5	6	-1.5	24

Survey Area: NA Survey Unit: INTERIOR Building: T883B
 Survey Unit Description
 FLOOR, WALLS, CEILINGS

Total Surface Activity Data Sheet

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts (cpm)		Net Activity (dpm/100cm2)	
		α	β	α	β	α	β	α	β	α	β	α	β
MAIN AREA				90	90								
D-15F	1	7	7	90	90	0.0	315	6.7	359	6.7	44	30.0	145
C-14F	1	7	7	90	90	0.7	352	2.7	371	2.0	19	8.9	63
B-13F	1	7	7	90	90	3.3	359	2.7	410	-0.6	51	-2.7	168
F-8F	1	7	7	90	90	2.0	329	1.3	349	-0.7	20	-3.1	66
F-18F	1	7	7	90	90	0.7	397	2.7	401	2.0	4	8.9	13
H-8F	1	7	7	90	90	1.3	353	5.3	345	4.0	-8	17.9	-26
L-1W	1	7	7	90	90	2.0	337	1.3	266	-0.7	-71	-3.1	-234
O-2W	1	7	7	90	90	1.3	357	4.0	261	2.7	-96	12.1	-316
U-2W	1	7	7	90	90	2.7	361	6.7	259	4.0	-102	17.9	-336
AC-2W	1	7	7	90	90	2.7	372	4.0	283	1.3	-89	5.8	-293
AH-2W	1	7	7	90	90	1.3	375	3.3	319	2.0	-56	8.9	-184
AI-2W	1	7	7	90	90	2.0	391	2.0	391	0.0	0	0.0	0
C-2N	1	7	7	90	90	4.0	353	5.3	291	1.3	-62	5.8	-204
E-2N	1	7	7	90	90	2.0	393	5.3	292	3.3	-101	14.8	-333
L-2E	1	7	7	90	90	1.3	346	7.3	288	6.0	-58	26.8	-191
O-1E	1	7	7	90	90	1.3	373	8.7	307	7.4	-66	33.1	-217
R-2F	1	7	7	90	90	1.3	329	6.7	289	5.4	-40	24.2	-132
T-2E	1	7	7	90	90	2.0	367	8.7	289	6.7	-78	30.0	-257
W-2E	1	7	7	90	90	0.7	379	3.3	271	2.6	-108	11.6	-356
I-12C	1	7	7	90	90	0.0	374	6.0	456	6.0	82	26.8	270
S-2C	1	7	7	90	90	1.3	382	6.7	462	5.4	80	24.2	264
J-16C	1	7	7	90	90	2.7	360	5.3	483	2.6	123	11.6	405
K-2C	1	7	7	90	90	2.0	365	5.3	399	3.3	34	14.8	112
K-6C	1	7	7	90	90	1.3	392	7.3	412	6.0	20	26.8	66
K-11C	1	7	7	90	90	0.7	366	6.0	436	5.3	70	23.7	231
L-8C	1	7	7	90	90	1.3	361	5.3	444	4.0	83	17.9	273
NA				90	90								
F8F QC	1	8	8	90	90	2.0	421	0.7	453	-1.3	32	-6.0	104
D15F QC	1	8	8	90	90	0.0	343	3.3	406	3.3	63	15.3	206
F8F QC	1	8	8	90	90	0.7	419	0.7	399	0.0	-20	0.0	-65
H8F QC	1	8	8	90	90	0.7	381	2.0	463	1.3	82	6.0	268
R2E QC	1	8	8	90	90	2.7	304	0.7	363	-2.0	59	-9.3	192

Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" - local area background.

D-3

T883B – Asbestos Inspector's Report

T883B

ASBESTOS INSPECTOR'S REPORT

I, the undersigned Certified Asbestos Inspector, certification # [REDACTED]
in the state of Colorado, attest to the asbestos inspection and sampling results as
described below, for the following facility (at RFETS): Trailer 883B.

General Facility Location: north-northeast of Building 881.

INSPECTION RESULTS

Trailer 883B contains friable ceiling tile. Fiberglass insulation was found throughout the walls. The following table summarizes the results of the samples collected and the percent and type of asbestos detected:

SAMPLE RESULTS

Sample Number	Material Sampled & Location	Analytical Results
T883B-03012000-05-003	Miscellaneous material: 2' x 4' white ceiling tile. Coordinate C2C	None Detected
T883B-03012000-05-004	Miscellaneous material: 2' x 4' white ceiling tile. Coordinate C6C	None Detected

Andre Gonzalez
INSPECTOR'S NAME

[Signature]
SIGNATURE

7/6/00
DATE

D-4

T883B - D&D Facility Characterization Interview Checklist



D&D Facility Characterization Interview Checklist

ID No.: T-883B

Date: 06/07/99

Page 1 of 2
Groups B & C SeriesCheck List for - Title: D&D Facility Characterization - Interviews

CRITERIA: A *D&D Characterization Protocol*, RFETS MAN-077-DDCP, Rev. 0
 A *Facility Disposition Program Manual*, RFETS MAN-076-FDPM
 A RFETS Radiological Safety Practices, January 12, 1998

Facility Name & Type (1, 2, or 3) T-883B Group B Type 1 Facility, Trailer Office BuildingPersonnel Interviewed (Name & Title/Function) Douglas C. Fisher, Senior Engineer, SSOC Residue Stabilization, P-212-4895, Building 750, Room 132C, SSOC Residue Stabilization

-- Y/N --

Does a current WSRIC exist for the facility? NIf so, are there exceptions to the WSRIC as written? No WSRIC, No Exceptions

COMMENTS (incl. WSRIC contacts)

WSRIC Contact is James M. Schoen who is in charge of the WSRIC Reports, T130J, X3579, C-83.Are rad surveys available that indicate current status of the facility? NAre historical rad surveys available that indicate historical status, or evolution, of the facility? N*COMMENT N* According to Mark R. Richards, X5148 of SSOC anyHistorical data, which is probably at the Federal Center, would not beAdequate for unrestricted release. New monitor surveys would have to be taken.Is an HRR available for the facility? N

Do any other reports exist beyond the HRR (e.g., spill reports, reportable incidents, etc.) that further

Characterize the facility relative to chemical &/or radiological contamination? Y**Are engineering drawings (esp. "as-builts") available? NAre any nonconformances or issues with the facility status currently being tracked in PATS? N

If so, what are the issues (note in Comments, below)?

COMMENTS N* Radiological surveys may have been done, but the old data is not available.This unit will have to be resurveyed to meet present standards for unrestricted release. Y** The T-883BTrailer is not sitting on IHSS or PAC area land, as per, Nick Demos, ER Characterization/HRR Manager, X4605.Therefore, the T-883B Office Trailer does not have CERCLA concerns. Engineering drawings, as-builts, do notexist for the T-883A Facility. There are no PATS items outstanding for this facility. The Plant quit using leadbased paints for office buildings in 1989, if this office facility was painted prior to 1989, lead based paintsmay have been used.Have any types of chemical characterization, incl. Asbestos, been performed recently? N*

If so, what types of characterization were performed (note in Comments, below)?

COMMENTS N* No asbestos characterization data exists, according toKevin Sheehan, X7250, T-452D, Room C-1. The asbestos data reports are located inCubicle C-13, of T-452D and the reports are under the control of Kevin Sheehan.Interviewed by: J. R. Sheets06/03/99

Print Name

Signature

Interview Date

124



D&D Facility Characterization Interview Checklist

ID No.: T-883B
Date: 06/07/99
Page 2 of 2
Groups B & C Series

What timeframe did the interviewee work in the facility? From the Fall of 1995 until August 1997 (for approximately 2 years).

Has the building configuration changed since you worked in the building? If so, in what way? Yes, the facility had up to a maximum 15 people during the time that SSOC Residue Stabilization occupied the facility. Yes, all the office cubicles have been removed. T-883B has remained vacant since approximately August 1997.

What types of equipment were in the building during the interviewee's time there?
Approximately 15 computers, approximately 12 printers, a fax machine, a photocopier machine, other office equipment such as desks, 15 chairs, 3 tables, bookcases, 8 file cabinets, etc. There was a conference room this in this facility.

Where was the equipment located? (specific rooms/areas) In the conference room, the hard wall offices, the office cubicles. The prior occupants (prior to March 1995) an Information Resource Management group that did software support for AutoCad and software support for CAD/CAM for Building 460 Machining Operations. The IR Management group had approximately 12 employees in T-883B from 1991 until March 1995. Computers, printers, fax machine, photocopier, and office equipment were in the hard wall offices and office cubicles during this 1991 to March 1995 time frame.

Were any radioactive materials or metals handled in the building? If so, what types? No, none

Which equipment handled radioactive material? N/A

Were any chemicals handled in the building? If so, what types? N/A

Did any spills or uncontrolled releases of radioactive materials or chemicals occur while you were working in the facility? No, none.

Were these spills/releases cleaned-up? How were they cleaned-up? N/A

Where did these spills/releases occur? N/A

Interviewed by: J. R. Sheets / JR Sheets / 06/03/99
Print Name Signature Interview Date

Type 1 Facility Checklist

TYPE 1 FACILITY	BUILDING T-883B
CURRENT LANDLORD:	RFCS
DATE OF COMPLETION:	02/29/00

ITEM	YES	NO
Does the facility contain radiological postings?		X
Does the facility contain chemical postings?		X
Are there any installed hazards?		X
Do the historical surveys (radiological and chemical) indicate the facility is clean?	X	
Are there RCRA units within the facility		X
Is there a history of the building available?	X	
Is there any equipment/furniture left in the facility?		X
Is there a future mission identified for the facility?		X
Will the facility be left unsecured after it is vacated?		X

If any answer to any of the above questions is "Yes", complete the following questions and complete the "graded" PEP in accordance with Chapter 2.

Note: An answer of "Yes" to any question, specifically one dealing with hazards, may indicate the facility is not a Type 1 Facility. Check with the D&D Programs office.

If the answer to all question is "No" complete the "graded" PEP in accordance with Chapter 2.

1. List the Radiological Hazards, location, and quantity:

Based on the historical data found and interviews taken there are no hazards in this trailer.

2. List the Chemical Hazards, location, and quantity:

None. Based on historical data and interviews taken no asbestos data exists and the paint may be lead based.

3. List the Physical Hazards:

NONE

E-1

T439A – Radiological Survey Data for Exterior Survey Unit

- Summary of Radiological Survey/Sample Results
- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results – Detail
- Laboratory Alpha Spec (Sample) Results – Detail

Radiological Survey/Sample Results for T439A

Total Surface Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-21	-406
MAX	21	849
MEAN	4.1	-89.1
STD DEV	9.9	264.1
Exterior	# Required	# Obtained
	28	28
MIN	-24	-346
MAX	53	685
MEAN	17.1	122.5
STD DEV	18.4	286.7
DCGL _w	100	5000

Removable Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-1.5	-22
MAX	4.8	62
MEAN	-0.3	13.7
STD DEV	1.4	24.6
Exterior	# Required	# Obtained
	28	28
MIN	-1.5	-55.6
MAX	3.3	30.0
MEAN	0.0	-0.6
STD DEV	1.2	22.7
DCGL _w	20	1000

Media Sample Activity

# Required	# Obtained
N/A	N/A

<u>Contaminant</u>	<u>Y/N</u>	<u>Det. Sens. dpm/100 cm²</u>
U present	N/A	N/A
Pu present	N/A	N/A


Total Po-210 Results dpm/100 cm²

MIN	N/A
MAX	N/A
MEAN	N/A
STD DEV	N/A

Scan Locations:

N

T439A Exterior




Scal Locations:

[illegible]
$$z$$
[illegible]

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28

T439A Exterior Roof



□ = one square meter
 ■ = direct & swipe

X-Coordinate	Y-Coordinate
5	2

Roof Surveys randomly chosen with original number of survey points (9 survey points)

X	Y
1	11
2	7
3	8
4	14
5	9
6	4
7	6
8	3
9	17

187a/242

2/24/00

131

Survey Area: N/A

Survey Unit: EXTERIOR

Building: T439A

Survey Unit Description

Roof + Walls of Transverse T439A

Total Surface Activity Data Sheet

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts (cpm)		Net Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β	α	β	α	β
B-2S	3	7	7	90	90	7.3	436	9.3	486	2	50	9	165
C-2S	3	7	7	90	90	8.7	422	7.3	469	-1.4	67	-6	221
D-1S	3	7	7	90	90	9.3	391	4.7 ²⁷	387	-4.6	-4	-21	-13
E-1S	1	9	9	90	90	6.0	550	7.3	383	1.3	33	7	111
I-2S	1	9	9	90	90	4.7	395	8.7	395	4.0	-3	20	-10
L-2S	1	9	9	90	90	9.3	353	12.0	389	2.7	36	+80 ¹⁴	121
M-1S	1	9	9	90	90	4.0	368	9.3	373	5.3	5	28 ²⁷	17
M-2S	1	9	9	90	90	9.3	380	12.0	416	2.7	36	14 ¹⁸⁰	121
B-2W	3	7	7	90	90	9.3	433	16.0	419	6.7	-14	30	-46
C-2W	3	7	7	90	90	0.7	379	4.0	423	3.3	44	15	145
B-1W	3	7	7	90	90	8.0	349	5.3	363	-2.7	14	-12	46
C-1W	3	7	7	90	90	4.7	378	8.0	353	3.3	-25	15	-82
D-2W	2	8	8	90	90	2.0	401	6.0	352	+4.0	-49	+19	-164
G-1W	3	7	7	90	90	10.0	322	4.7	420	-5.3	98	-24	323
G-2W	2	8	8	90	90	1.3	349	4.0	303	3.3	-96	15	-322
A-2W	2	8	8	90	90	1.3	409	5.3	346	4.0	-63	19	-211
K-2W	2	8	8	90	90	2.0	414	6.7	316	4.7	-48	+22	-329
L-2W	2	8	8	90	90	1.3	401	4.7	352	3.4	-49	16	-164
M-1W	3	7	7	90	90	5.3	421	4.7	316	-0.6	-105	-3	-346
C-2R	4	11	11	90	90	2.0	526	9.3	583	7.3	57	34	190
D-2R	4	11	11	90	90	2.0	368	11.3	556	9.3	188	43	628
F-2R	4	11	11	90	90	2.7	399	11.3	579	8.6	180	40	601
G-2R	4	11	11	90	90	2.0	392	8.7	495	6.7	103	31	344
A-1R	4	11	11	90	90	2.7	352	14.0	557	11.3	205	53	685
I-2R	4	11	11	90	90	3.3	445	8.7	519	5.4	74	25	247
K-2R	4	11	11	90	90	5.3	427	12.0	552	6.7	125	31	418
N-4R	4	11	11	90	90	4.0	491	10.0	545	6.0	54	28	180
Q-2R	4	11	11	90	90	0.7	392	8.7	558	8.0	166	27	554
M-1SQC	8	10	10	90	90	0.7	341	6.0	317	5.3	-24	25	-78
B-1WQC	8	10	10	90	90	3.3	290	8.7	317	5.4	27	25	88
B-2WQC	8	10	10	90	90	2.0	375	1.3	340	-0.7	-35	-3	-114
A-1RQC	9	11	11	90	90	2.0	372	2.0	380	0	8	0	27
N-4RQC	9	11	11	90	90	4.7	504	4.0	485	-0.7	-9	-3	-30

Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" ~ local area background.

E-2

T439A -- Radiological Survey Data for Interior Survey Unit

- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results - Detail




[illegible]

Figure 1 displays a 10x10 grid representing the spatial distribution of 1000 simulated individuals. The grid is divided into two 5x10 sections: 'Floor' (top) and 'Ceiling' (bottom). The columns are labeled A through K. The rows are labeled 1 through 3. A compass rose indicates North (N) is at the top. The 'Floor' section shows a single black square at row 1, column H. The 'Ceiling' section shows black squares at row 1, column A; row 2, columns A and B; and row 3, column K.



Walls



= one square meter

= direct & swipe

X-Coordinate	Y-Coordinate
15	5

X	Y
1	5
2	17
3	2
4	18
5	14
6	15
7	12
8	19
9	15
10	27

X	Y
1	8
2	1
3	2
4	7
5	6
6	5
7	7
8	7
9	4
10	8

X	Y
1	21
2	9
3	8
4	6
5	15
6	4
7	25
8	18
9	2
10	16

X	Y
1	5
2	7
3	1
4	8
5	6
6	3
7	26
8	7
9	6
10	2

X	Y
1	21
2	22
3	23
4	24
5	25
6	3
7	27
8	28
9	10
10	10

Total Surface Area = 174 m²

10% Scan Surface Area = 18 m²

172/242

PO

52

Survey Area: N/A Survey Unit: INTERIOR Building: T439A
 Survey Unit Description: FLOORS, WALLS, + CEILINGS OF TRAILER T439A

Removable Contamination Data Sheet

Sample Location	RCT ID #	Inst ID #		Gross Counts (gcpm)		Net Counts (cpm)		Removable Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β
ROOM 1									
B-3F	2	1	4	0	42	-0.1	1.5	-0.3	6
C-2F	2	2	4	0.5	48	0	7.5	0	30
D-1F	2	3	4	0	50	-0.4	9.5	-1.2	38
B-2C	2	1	4	0	43	-0.1	2.5	-0.3	10
B-3C	2	2	4	0	41	-0.5	0.5	-1.5	2
D-3C	2	3	4	0.5	52	0.1	11.5	0.3	46
E-2W	2	1	4	0.5	41	0.4	0.5	1.2	2
F-1W	2	2	4	0	44	-0.5	3.5	-1.5	14
L-2W	2	3	4	0	40	-0.4	-0.5	-1.2	-2
M-1W	2	1	4	0	48	-0.1	7.5	-0.3	30
ROOM 2									
H-1F	2	2	4	0	39	-0.5	-1.5	-1.5	-6
A-1C	2	3	4	0	48	-0.4	7.5	-1.2	30
B-1C	2	1	4	0	48	-0.1	7.5	-0.3	30
B-2C	2	2	4	0	42	-0.5	1.5	-1.5	6
B-3C	2	3	4	0	43	-0.4	2.5	-1.2	10
H-2C	2	1	4	0.5	36	0.4	-4.5	1.2	-18
K-1C	2	2	4	0	43	-0.5	2.5	-1.5	10
A-2W	2	3	4	0	36	-0.4	-4.5	-1.2	-18
B-2W	2	1	4	0.5	35	0.4	-5.5	1.2	-22
E-1W	2	2	4	0	56	-0.5	15.5	-1.5	62
G-2W	2	3	4	2.0	35	1.6	-5.5	4.8	-22
I-2W	2	1	4	0	48	-0.1	7.5	-0.3	30
L-2W	2	2	4	0.5	53	0	12.5	0	50
P-2W	2	3	4	0.5	42	0.1	1.5	0.3	6
R-2W	2	1	4	0	37	-0.1	-3.5	-0.3	-14
S-2W	2	2	4	0	54	-0.5	13.5	-1.5	54
Y-2W	2	3	4	1.0	36	0.6	-4.5	1.8	-18
AA-1W	2	1	4	0	50	-0.1	9.5	-0.3	38
N/A									

Survey Area: <u>N/A</u>	Survey Unit: <u>INTERIOR</u>	Building: <u>T439A</u>
Survey Unit Description: <u>Floors, Walls, & Ceilings of Trailer T439A</u>		

Total Surface Activity Data Sheet

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts (cpm)		Net Activity (dpm/100cm2)	
		α	β	α	β	α	β	α	β	α	β	α	β
Room 1				90	90								
B-3F	1	7	7	90	90	2.0	402	2.0	463	0	61	0	205
C-2F	1	7	7	90	90	5.3	429	1.3	509	-4.0	80	-19	268
D-1F	1	7	7	90	90	0.7	443	5.3	576	4.6	133	21	446
B-2C	1	7	7	90	90	2.7	424	1.3	383	-1.4	-41	-6	-138
B-3C	1	7	7	90	90	2.7	411	2.0	409	-0.7	-2	-3	-7
D-3C	1	7	7	90	90	5.3	421	0.7	408	-4.6	-13	-21	-44
E-2W	1	7	7	90	90	3.3	411	5.3	325	2.0	-86	9	-288
F-1W	1	7	7	90	90	2.7	395	2.0	375	-0.7	-20	-3	-67
L-2W	1	7	7	90	90	2.0	433	2.7	312	0.7	-121	3	-406
M-1W	1	7	7	90	90	1.3	400	2.0	344	0.7	-56	3	-188
Room 2				90	90								
H-1F	1	7	7	90	90	2.7	407	2.0	660	-0.7	253	-3	849
A-1C	1	7	7	90	90	2.7	409	4.0	379	1.3	-30	6	-101
B-1C	1	7	7	90	90	2.0	411	2.7	397	0.7	-14	3	-47
B-2C	1	7	7	90	90	0.0	411	2.0	411	2.0	0	9	0
B-3C	1	7	7	90	90	0.7	407	1.3	390	0.6	-17	3	-57
H-2C	1	7	7	90	90	1.3	421	2.7	413	1.4	-8	6	-27
K-1C	1	7	7	90	90	1.3	422	2.7	376	1.4	-46	6	-154
A-2W	1	7	7	90	90	1.3	398	3.3	335	2.0	-63	9	-211
B-2W	1	7	7	90	90	0.7	404	2.0	343	1.3	-61	6	-205
E-1W	1	7	7	90	90	1.3	429	2.0	352	0.7	-77	3	-258
G-2W	1	7	7	90	90	2.7	436	6.7	346	4.0	-90	19	-302
I-2W	1	7	7	90	90	1.3	429	2.0	315	0.7	-114	3	-382
L-2W	1	7	7	90	90	0.7	381	4.0	293	3.3	-88	15	-295
P-2W	1	7	7	90	90	1.3	410	2.0	329	0.7	-81	3	-272
R-2W	1	7	7	90	90	2.7	409	2.0	330	-0.7	-79	-3	-205
S-2W	1	7	7	90	90	0.7	400	5.3	348	4.6	-52	21	-174
QC				90	90								
QC				90	90								
QC				90	90								
QC				90	90								
QC				90	90								

Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" ~ local area background.

Building: T439A

FLOORS, WALLS, + CEILINGS OF TRAILER T439A


138

E-3

T439A – Asbestos Inspector's Report

T439A

ASBESTOS INSPECTOR'S REPORT

I, the undersigned Certified Asbestos Inspector, certification #  in the state of Colorado, attest to the asbestos inspection and sampling results as described below, for the following facility (at RFETS): Trailer 439A.

General Facility Location: south of Buildings 450 and 444.

INSPECTION RESULTS

Trailer 439A contains non-friable fiberboard wall panels and drywall (no tape joint compound associated with the drywall). Fiberglass insulation was found throughout the walls. Suspect friable asbestos containing materials were not observed and no samples were collected.

SAMPLE RESULTS

None required; none taken.

Andre Gonzalez

INSPECTOR'S NAME

Andre Gonzalez

SIGNATURE

7/6/00

DATE

E-4

T439A – D&D Facility Characterization Interview Checklist



D&D Facility Characterization Interview Checklist

IDNo.:T439A
Date:6/14/99
Page 1 of 2
Groups B & C Series

Check List for - Title: D&D Facility Characterization - Interviews

CRITERIA: Λ *D&D Characterization Protocol*, RFETS MAN-077-DDCP, Rev. 0
 Λ *Facility Disposition Program Manual*, RFETS MAN-076-FDPM
 Λ RFETS Radiological Safety Practices, January 12, 1998

Facility Name & Type (1, 2, or 3) T439A, Group B Type 1 Facility

Personnel Interviewed (Name & Title/Function) Wes Dycus /RMRS Maintenance, X7511, John Bert/SSOC/X4948, Dan Coyne/RMRS/X2820

Does a current WSRIC exist for the facility?..... N
If so, are there exceptions to the WSRIC as written?..... N

COMMENTS (incl. WSRIC contacts).....
Contacted Jim Schoen regarding WSRIC, X3579

Are rad surveys available that indicate current status of the facility?..... N
Are historical rad surveys available that indicate historical status, or evolution, of the facility?..... N

COMMENTS.....
.....

Is an HRR available for the facility?..... N
Do any other reports exist beyond the HRR (e.g., spill reports, reportable incidents, etc.) that further characterize the facility relative to chemical &/or radiological contamination?..... Y*
Are engineering drawings (esp. "as-builts") available?..... N
Are any nonconformances or issues with the facility status currently being tracked in PATS? N

If so, what are the issues (note in Comments, below)?
COMMENTS Y* This unit is located inside of IHSS #157.2, per Nick Demos, ER Characterization/HRR Mgr., X4605. He indicated there are RADs and non-Rads, toxic metals, Be, and volatile organics in shallow soil.

Have any types of chemical characterization, incl. asbestos, been performed recently?..... N
If so, what types of characterization were performed (note in Comments, below)?

COMMENTS No asbestos characterization data exists, according to Kevin Sheehan, X7250

Interviewed by: R. G. Alexander/ DR Sheets FOR R.G. ALEXANDER 6/14/99
Print Name Signature Interview Date

142



D&D Facility Characterization Interview Checklist

ID No.: T439A

Date: 6/14/99

Page 2 of 2

Groups B & C Series

What time frame did the interviewee work in the facility? Jerry Blair, late 70's with the Mod Center, John Bert about 82 - 86, Darroll Crabb(retired) 88 - 89, Wes Dycus 95 - 97.

Has the building configuration changed since you worked in the building? If so, in what way?
Wes Dycus- the two entry door openings were widen for bigger doors.

What types of equipment were in the building during the interviewee's time there? None. Offices (HVAC equip)

Where was the equipment located? (specific rooms/areas) Furnace located in alcove on south side of trailer, and 3 wall A/C units.

Were any radioactive materials or metals handled in the building? If so, what types? N/A

Which equipment handled radioactive material? N/A

Were any chemicals handled in the building? If so, what types? N/A

Did any spills or uncontrolled releases of radioactive materials or chemicals occur while you were working in the facility? No

Were these spills/releases cleaned-up? How were they cleaned-up? N/A

Where did these spills/releases occur? N/A

Interviewed by: Roy G. Alexander/

R. Sheets
FOR Roy G. Alexander

16/14/99

Print Name

Signature

Interview Date

Type 1 Facility Checklist

TYPE 1 FACILITY	BUILDING T-439A
CURRENT LANDLORD:	RFCSS
DATE OF COMPLETION:	02/29/00

ITEM	YES	NO
Does the facility contain radiological postings?		X
Does the facility contain chemical postings?		X
Are there any installed hazards?		X
Do the historical surveys (radiological and chemical) indicate the facility is clean?	X	
Are there RCRA units within the facility		X
Is there a history of the building available?	X	
Is there any equipment/furniture left in the facility?		X
Is there a future mission identified for the facility?		X
Will the facility be left unsecured after it is vacated?		X

If any answer to any of the above questions is "Yes", complete the following questions and complete the "graded" PEP in accordance with Chapter 2.

Note: An answer of "Yes" to any question, specifically one dealing with hazards, may indicate the facility is not a Type 1 Facility. Check with the D&D Programs office.

If the answer to all question is "No" complete the "graded" PEP in accordance with Chapter 2.

1. List the Radiological Hazards, location, and quantity:

Based on the historical data found and interviews taken there are no hazards in this trailer.

2. List the Chemical Hazards, location, and quantity:

None. Based on historical data and interviews taken there are no chemical hazards in this trailer. There may be asbestos in the floor tile under the carpet and lead in the paint.

3. List the Physical Hazards:

NONE

F-1

T439D – Radiological Survey Data for Exterior Survey Unit

- Summary of Radiological Survey/Sample Results
- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results – Detail
- Laboratory Alpha Spec (Sample) Results – Detail

Radiological Survey/Sample Results for T439D

Total Surface Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-16	-451
MAX	36	221
MEAN	4.3	-51.4
STD DEV	10.4	228.7
Exterior	# Required	# Obtained
	28	28
MIN	3	-557
MAX	149	122
MEAN	56.8	-236.6
STD DEV	42.6	173
DCGL _w	100	5000

Removable Activity Measurements dpm/100 cm²

	Alpha	Beta
Interior	# Required	# Obtained
	28	28
MIN	-0.9	-46.4
MAX	3.9	45.6
MEAN	0.7	1.2
STD DEV	1.6	21.9
Exterior	# Required	# Obtained
	28	28
MIN	-0.9	-54.4
MAX	5.2	29.6
MEAN	1.3	-8.7
STD DEV	1.9	20
DCGL _w	20	1000

Media Sample Activity

# Required	# Obtained
2	2


<u>Contaminant</u>	<u>Y/N</u>	<u>Det. Sens. dpm/100 cm²</u>
U present	N	79
Pu present	N	79

Total Po-210 Results dpm/100 cm²




MIN	106.2
MAX	149.4
MEAN	127.8
STD DEV	7.8

146

SCAN LOCATIONS:




T439D Exterior







1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22

Scav Locations:



SURVEY PACKAGE SURVEY MAP

T439D Exterior



X-Coordinate	Y-Coordinate
7	14


□ = one square meter

■ = direct & swipe

X	Y	X	Y	X	Y
1	11	5	11	9	11
2	15	6	12	10	12
3	14	7	11	11	11
4	2	8	14	12	12
5	10	9	15	13	12
6	20	10	16	14	12
7	16	11	17	15	12
8	10	12	18	16	12
9	4	13	19	17	12
10	8	14	20	18	12

Total Surface Area = 1226 m²

10% Scan Surface Area 23 m²



X-Coordinate	Y-Coordinate
11	3

☐ = one square meter

☒ = direct & swipe

Roof Surveys randomly chosen with original
 number of survey points (13 survey points)

X	Y	X	Y
1	2	6	11
2	6	4	12
3	13	6	13
4	14	1	19
5	2	2	7
6	3	6	18
7	9	6	6
8	6	1	7
9	17	4	
10	11	6	

2172/242

~~2172~~ 2/24/00

Building: T434D

Survey Unit Description

Roof + Walls of TRUNK T439D

Removable Contamination Data Sheet									
Sample Location	RCT ID #	Inst ID #		Gross Counts (gcpm)		Net Counts (cpm)		Removable Activity (dpm/100cm ²)	
		α	β	α	β	α	β	α	β
B-1N	1	1	3	0	30	-0.3	-13.6	-0.9	-54.4
B-8N	1	2	3	1.0	38	0.8	-5.6	2.4	-22.4
A-16N	1	1	3	0.5	46	0.2	2.4	0.6	9.6
B-7S	1	2	3	0.5	40	0.3	-3.6	0.9	-14.4
A-10S	1	1	3	0	43	-0.3	-0.6	-0.9	-2.4
A-12S	1	2	3	0.5	44	0.3	0.4	0.9	1.6
B-14S	1	1	3	0.5	46	0.2	2.4	0.6	9.6
B-16S	1	2	3	1.0	41	0.8	-2.6	2.4	-10.4
A-18S	1	1	3	0.5	40	0.2	-3.6	0.6	-14.4
B-2E	1	2	3	0	44	-0.2	0.4	-0.6	1.6
F-2E	1	1	3	0	36	-0.3	-7.6	-0.9	-30.4
B-2W	1	2	3	0.5	51	0.3	7.4	0.9	29.6
D-1W	1	1	3	1.5	42	1.2	-1.6	3.6	-6.4
F-1W	1	2	3	1.0	40	0.8	-3.6	2.4	-14.4
J-2W	1	1	3	0.5	51	0.3	7.4	0.9	29.6
B-2R	6	4	6	1.0	36.5	0.7	-5.9	2.1	-23.6
B-6R	6	5	13	0.0	48.5	-0.2	1.6	-0.6	6.4
C-2R	6	4	6	0.0	40.0	-0.3	-2.4	-0.9	-9.6
F-4R	6	5	13	1.0	38.5	0.8	-2.4	2.4	-9.6
F-7R	6	4	6	2.0	42.0	1.7	-0.4	5.2	-1.6
G-3R	6	5	13	0.0	28.5	-0.2	-12.4	-0.6	-49.6
I-2R	6	4	6	0.0	39.0	-0.3	-3.4	-0.9	-13.6
K-2R	6	5	13	1.5	45.5	1.3	4.6	3.9	18.4
M-2R	6	4	6	2.0	35.5	1.7	-6.9	5.2	-27.6
N-7R	6	5	13	1.0	40.5	0.8	-0.4	2.4	-1.6
Q-4R	6	4	6	1.5	34.5	1.2	-7.9	3.6	-31.6
R-2R	6	5	13	0.0	42.0	-0.2	1.1	-0.6	4.4
S-1R	6	4	6	1.5	38.0	1.2	-4.4	3.6	-17.6
N A									

151

Survey Area: N/A	Survey Unit: EXTERIOR	Building: T439D
Survey Unit Description: ROOF + WALLS OF TRAILER T439D		

Total Surface Activity Data Sheet

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts (cpm)		Net Activity (dpm/100cm2)	
		α	β	α	β	α	β	α	β	α	β	α	β
B-1N	4	9	9	90	90	2.0	486	7.3	450	5.3	-36	24	-122
B-8N	4	9	9	90	90	0.7	509	16.7	461	16.0	-48	73	-163
A-16N	4	9	9	90	90	2.0	467	4.7	452	2.7	-15	12	-51
B-7S	4	9	9	90	90	4.0	517	16	440	12.0	-77	55	-261
A-10S	4	9	9	90	90	1.3	438	4.7	418	3.4	-20	16	-68
A-12S	4	9	9	90	90	2.0	496	5.3	431	3.3	-65	15	-221
B-14S	4	9	9	90	90	2.7	509	3.3	405	0.6	-104	3	-353
B-16S	4	9	9	90	90	1.3	467	4.7	458	3.4	-9	16	-31
A-18S	4	9	9	90	90	0.7	485	4.7	382	4.0	-103	18	-350
B-2E	4	9	9	90	90	0.0	509	6.0	423	6.0	-86	27	-292
F-2E	4	9	9	90	90	3.3	511	6.7	458	3.4	-53	16	-180
B-2W	4	9	9	90	90	2.0	511	12.0	423	10.0	-88	46	-299
D-1W	4	9	9	90	90	2.0	476	6.7	401	4.7	-75	21	-254
G-1W	4	9	9	90	90	1.3	496	6.0	482	4.7	-14	21	-48
S-2W	4	9	9	90	90	2.0	481	6.0	509	4.0	28	18	95
B-2R	5	11	11	90	90	1.3	615	34.7	513	33.4	-102	149	-336
B-6R	5	11	11	90	90	2.7	622	20.0	453	17.3	-169	77	-557
C-2R	5	11	11	90	90	1.3	635	34.7	487	33.4	-148	149	-487
F-4R	5	11	11	90	90	2.7	587	9.3	423	6.6	-164	30	-540
F-7R	5	11	11	90	90	2.0	567	24.0	491	22.0	-76	98	-250
G-3R	5	11	11	90	90	2.7	519	21.3	504	18.6	-15	83	-49
I-2R	5	11	11	90	90	6.0	458	26.0	495	20.0	37	89	122
K-2R	5	11	11	90	90	1.3	635	22.0	511	20.7	-124	93	-408
M-2R	5	11	11	90	90	3.3	583	22.0	489	18.7	-94	84	-310
N-7R	5	11	11	90	90	1.3	597	14.7	489	13.4	-100	60	-356
Q-4R	5	11	11	90	90	0.7	526	23.3	467	22.6	-59	101	-194
R-2R	5	11	11	90	90	1.3	577	19.3	484	18.0	-93	81	-306
S-1R	5	11	11	90	90	1.3	583	26.7	475	25.4	-108	114	-356
A-16QC	8	10	10	90	90	0.7	456	8.0	396	7.3	-60	34	-196
A-18QC	8	10	10	90	90	2.0	419	8.7	449	6.7	30	31	98
G-1WQC	8	10	10	90	90	3.3	417	10.7	443	7.4	26	34	85
G-3RQC	9	11	11	90	90	2.0	461	20.00	487	18.0	26	81	86
M-2RQC	9	11	11	90	90	1.3	453	16.7	437	15.4	-16	-69	-53

Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" ~ local area background.


152

Final Survey NE Electra Scan & Investigation Survey Map

Survey Area: NA	Survey Unit: EXTERIOR	Building: 439D
Survey Unit Description: WALLS, ROOF		
RCT Initials/Date: ME 3/3/00	RCT Initials/Date: N/A	RCT Initials/Date: N/A

Refer to the Final Survey NE Electra Scan & Investigation Survey Form for instrumentation, surveyor & approval information.

Legend: "R" - Roof, "W" - West Wall, "S" - South Wall, "E" - East Wall, "N" - North Wall
"C" - Ceiling, "F" - Floor



* Designates corner closest to A-1 point of reference

Results/Comments:

Electra alpha scans were performed at the locations detailed on the survey map(s). All required accessible areas were scanned. All initial scan results were <225 dpm/100cm², unless noted on the survey form.

Electra beta scans were performed in required accessible areas. Initial scan results indicated no detectable activity above background unless noted on the survey form.

Final Survey NE Electra Scan & Investigation Survey Form

Survey Area: NA				Survey Unit: EXTERIOR			Building: 1439D		
Survey Unit Description: WALLS, Roof									
Loc. ID #	Electra DP-6 Beta				Electra DP-6 Alpha				
	RCT ID #	Inst. ID #	Elevated Audible observed? "Y" or "N"	60-sec PAT (dpm/100cm ²)	RCT ID #	Inst. ID #	4-sec Audible observed? "Y" or "N"	30-sec Static (gcpm)	90-sec PAT (dpm/100cm ²)
B-10S	1	1	N	NA	1	1	Y	12	NA
B-12S	1	1	N	NA	1	1	N 2-3-3	NA	NA
B-18S	1	1	N	NA	1	1	N 2-3-3	NA	NA
C-2E	1	1	N	NA	1	1	N 2-3-3	NA	NA
D-2E1	1	1	N	NA	1	1	Y	8	NA
D-2E2	1	1	N	NA	1	1	Y	6	NA
D-2E3	1	1	N	NA	1	1	Y	10	NA
E-2E1	1	1	N	NA	1	1	Y	8	NA
E-2E2	1	1	N	NA	1	1	Y	4	NA
F-7RA	1	1	N	NA	1	1	NA	NA	92.6
F-7RB	1	1	N	NA	1	1	NA	NA	116.3
F-7RC	1	1	N	NA	1	1	NA	NA	116.3
F-7RD	1	1	N	NA	1	1	NA	NA	149.0
F-7RE	1	1	N	NA	1	1	NA	NA	119.5
F-7RF	1	1	N	NA	1	1	NA	NA	166.9
F-7RG	1	1	N	NA	1	1	NA	NA	140.0
F-7RH	1	1	N	NA	1	1	NA	NA	116.3
F-7RI	1	1	N	NA	1	1	NA	NA	119.5
B.6N1	2	2	N	N/A	2	2	Y	24	N/A
B.6N2	2	2	N	N/A	2	2	Y	12	N/A
B.9N1	2	2	N	N/A	2	2	Y	10	N/A
B.9N2	2	2	N	N/A	2	2	Y	12	N/A
B.9N3	2	2	N	N/A	2	2	Y	18	N/A
B.7N1	2	2	N	N/A	2	2	Y	24	N/A
B.7N2	2	2	N	N/A	2	2	Y	12	N/A
B.7N3	2	2	N	N/A	2	2	Y	16	N/A

13.2 AVG
126.3

Sample ID: 00A1148-016.001

Type: Unknown

Batch ID: unknowns
Acquisition Start: April 25, 2000 14:34:47
Analysis Date: April 25, 2000 18:32:19
Procedure: Po210 count
Device: Oasis:01:01
Analysis Method: ROI Analysis
Spectrum File: 00000490.OXS
LiveTime: 10,800.00

Calibrations:

Energy = $3.865\text{E}+01 + 2.790\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998
Calibration Date: April 03, 2000 17:45:10 Std: 1:1 energy cal
Shape not Calibrated.
Efficiency = $3.041\text{E}-01 \pm 4.004\text{E}-03$
Calibration Date: April 07, 2000 09:49:29 Std: TS4189

External Recovery No Ext.Recovery

Original Sample Amount:

1.000 ± 0.000 samp

Aliquot Amount:

1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS START	EXTENTS END	PK EN (keV)	FWHM (keV)
1 Po218	Po218	5550.0	6104.5	5826.0	2.8
2 Po214	Po214	6588.5	7874.7	7229.6	2.8
3 Po212	Po212	8393.8	8808.6	8599.7	1.4
4 Po210	Po210	2180.3	5343.3	5150.8	3.8

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	0.5 ± 1.0	0.47	$2.95\text{E}-03 \pm 5.62\text{E}-03$	Unknown
Po214	0.7 ± 1.0	0.28	$3.99\text{E}-03 \pm 5.59\text{E}-03$	Unknown
Po212	-0.1 ± 0.1	0.09	$-5.21\text{E}-04 \pm 3.68\text{E}-04$	Unknown
Po210	394.4 ± 20.0	6.56	2.191 ± 0.111	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm)
Po218	Po218	1.000	$9.71\text{E}-03 \pm 0.018$	$9.16\text{E}-02$
Po214	Po214	1.000	0.013 ± 0.018	$8.21\text{E}-02$
Po212	Po212	1.000	$-1.71\text{E}-03 \pm 1.21\text{E}-03$	$6.83\text{E}-02$
Po210	Po210	1.000	7.207 ± 0.378	$2.07\text{E}-01$

Activity reported as of April 25, 2000 14:34:47

ANALYSIS REVIEWED BY:

APPROVED BY:

Library: OAS_STD.MDB Nuclide: Am241


Acq ALL
Acquire
Stop
Exit

4096
LOG

☐ Lin ☒ Log
☐ Sqrt

Peak

Pretats
ROIs
Controls
Display
Info
FAUX Disp



4095

Spectrum ID

00A1148-016.001

System Date

25-Apr-2000 18:25:06

Message Window

Channel: 2562 Elapsed Real Time: 10800.01 Elapsed Live Time: 10800.00 Dead Time: 0.0

Energy: 7188.3 Counts: 0 ROI: Integrat: 1 Peak: 7229.64 FWHM: 2.79

Sample ID: 00A1148-017.001

Type: Unknown

Batch ID: unknowns
Acquisition Start: April 25, 2000 11:09:58
Analysis Date: April 25, 2000 14:11:29
Procedure: Po210 count
Device: Oasis:01:01
Analysis Method: ROI Analysis
Spectrum File: 00000486.OXS
LiveTime: 10,800.00

Calibrations:

Energy = $3.865\text{E}+01 + 2.790\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998
Calibration Date: April 03, 2000 17:45:10 Std: 1:1 energy cal
Shape not Calibrated.
Efficiency = $3.041\text{E}-01 \pm 4.004\text{E}-03$
Calibration Date: April 07, 2000 09:49:29 Std: TS4189

External Recovery No Ext.Recovery

Original Sample Amount:

1.000 ± 0.000 samp

Aliquot Amount: 1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS START	EXTENTS END	PK EN (keV)	FWHM (keV)
1 Po218	Po218	5550.0	6104.5	5826.0	2.8
2 Po214	Po214	6588.5	7874.7	7229.6	2.8
3 Po212	Po212	8393.8	8808.6	8599.7	1.4
4 Po210	Po210	2180.3	5343.3	5178.7	6.5

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	0.5 ± 1.0	0.47	$2.95\text{E}-03 \pm 5.62\text{E}-03$	Unknown
Po214	1.7 ± 1.4	0.28	$9.55\text{E}-03 \pm 7.88\text{E}-03$	Unknown
Po212	-0.1 ± 0.1	0.09	$-5.21\text{E}-04 \pm 3.68\text{E}-04$	Unknown
Po210	280.4 ± 17.0	6.56	1.558 ± 0.094	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm)
Po218	Po218	1.000	$9.71\text{E}-03 \pm 0.018$	$9.16\text{E}-02$
Po214	Po214	1.000	0.031 ± 0.026	$8.21\text{E}-02$
Po212	Po212	1.000	$-1.71\text{E}-03 \pm 1.21\text{E}-03$	$6.83\text{E}-02$
Po210	Po210	1.000	5.124 ± 0.317	$2.07\text{E}-01$

Activity reported as of April 25, 2000 11:09:58

ANALYSIS REVIEWED BY:

APPROVED BY:

OASIS - MCA

File

Edit

View

AcqPams

Tools

Reports

Close

Help

Library: OAS_STD.MDB

Nuclide: Am241

1:Static: 00000486.DXS

Acq ALL

Acquire

Stop

Erase

4096

LOG

Lin

Log

Sqrt

Peak

Presets

ROIs

Controls

Display

Info

Aux Disp

0

4095

00A1148-017.001

System Date

09-May-2000 14:32:56

Message Window

Channel: 958

Elapsed Real Time: 10800.04

Elapsed Live Time: 10800.00

Dead Time: 0.0

Energy: 2711.6

Counts: 0

ROI:

Integral: 287

Peak: 5,178.66

FWHM: 6.51

Sample ID: 00A1148-018.001

Type: Unknown

Batch ID: unknowns

Acquisition Start: May 04, 2000 13:14:27

Analysis Date: May 04, 2000 16:17:04

Procedure: Po210 count

Device: Oasis:01:03

Analysis Method: ROI Analysis

Spectrum File: 00000541.OXS

LiveTime: 10,800.00

Calibrations:

Energy = $6.596\text{E}+01 + 2.779\text{E}+00 * \text{Chn}$ Coeff. of Correlation: -0.998

Calibration Date: April 24, 2000 13:03:27 Std: 1:3 Energy Cal

Shape not Calibrated.

Efficiency = $3.120\text{E}-01 \pm 4.098\text{E}-03$

Calibration Date: April 24, 2000 10:05:48 Std: TS4189

External Recovery No Ext.Recovery

Air Filter Analysis Parameters:

Sample Type: Unknown

Air Filter Time on: May 04, 2000 13:12:09

Air Filter Time off: May 04, 2000 13:12:09

Total Collect Time: 0.000 hours

Air Volume: 1.000 ± 0.000 samp

ROI DATA

ROI ID #	ASSOCIATED NUCLIDE	EXTENTS START	END	PK EN (keV)	FWHM (keV)
1 Po218	Po218	5550.0	6104.5	5827.5	2.8
2 Po214	Po214	6588.5	7874.7	7231.0	2.8
3 Po212	Po212	8393.8	8808.6	8601.2	2.8
4 Po210	Po210	2180.3	5343.3	5174.3	3.7

ROI ANALYSIS RESULTS

ROI ID	NET COUNTS	BKG/INTERF	CPM	ROI TYPE
Po218	5.5 ± 2.5	0.50	0.031 ± 0.014	Unknown
Po214	0.0 ± 1.1	1.00	$0.00\text{E}+00 \pm 6.21\text{E}-03$	Unknown
Po212	4.0 ± 2.0	0.00	0.022 ± 0.011	Unknown
Po210	189.3 ± 14.1	6.75	1.051 ± 0.078	Unknown

NUCLIDE ANALYSIS RESULTS

ROI ID	ASSOC NUC	EMM. PROB	ACTIVITY (dpm/samp)	MDA (dpm/samp)
Po218	Po218	1.000	0.098 ± 0.044	$9.45\text{E}-02$
Po214	Po214	1.000	$0.00\text{E}+00 \pm 0.020$	$1.14\text{E}-01$
Po212	Po212	1.000	0.071 ± 0.036	$4.82\text{E}-02$
Po210	Po210	1.000	3.370 ± 0.254	$2.18\text{E}-01$


Activity reported as of May 04, 2000 13:14:27

ANALYSIS REVIEWED BY:

APPROVED BY:

159

Library: **OAS STD.MDB** Nuclide: **Am241**



Acq ALL Acquire Stop

4096 LOG

☐ Lin ☒ Log ☐ Sqrt

Peak

Preset ROIs Controls Display Info Aux Disp

Spectrum ID

00A1148-018.001

System Date 09-May-2000 15:58:24

Channel: 1111 Elapsed Real Time: 10800.05 Elapsed Live Time: 10800.00 Dead Time: 0.0

Message Window


Energy: 3152.9 Counts: 0 ROI: Integral: 196 Peak: 5.174.32 FWHM: 3.71

Final Survey NE Electra Scan & Investigation Survey Map

Survey Area: NA	Survey Unit: EXTERIOR	Building: T439D
Survey Unit Description: Roof Sample Locations		
RCT Initials/Date: NA 3/29/00	RCT Initials/Date: NA	RCT Initials/Date: NA

Refer to the Final Survey NE Electra Scan & Investigation Survey Form for instrumentation, surveyor & approval information.

Legend: "R" - Roof, "W" - West Wall, "S" - South Wall, "E" - East Wall, "N" - North Wall
"C" - Ceiling, "F" - Floor



⊗ Sample Cut Out

* Designates corner closest to A-1 point of reference

Results/Comments:

Electra alpha scans were performed at the locations detailed on the survey map(s). All required accessible areas were scanned. All initial scan results were <225 dpm/100cm², unless noted on the survey form.

Electra beta scans were performed in required accessible areas. Initial scan results indicated no detectable activity above background unless noted on the survey form.

161

[illegible]

162

ROOF SAMPLE LOCATIONS

F-2

T439D – Radiological Survey Data for Interior Survey Unit


- Map of Locations
 - Scans
 - Surveys
- Removable and Total Survey Results - Detail

165


Package ID: 2000-01
Building: T439D
Survey Unit: Interior

SURVEY PACKAGE SURVEY MAP



T439D Floor




T439D Ceiling



T439D Room 1 Walls



T439D Room 2 Walls



X-Coordinate	Y-Coordinate
7	9

□ = one square meter

■ = direct & swipe

X	Y	X	Y	X	Y
1	10	4	11	12	2
2	16	7	12	2	3
3	5	8	13	7	3
4	15	15	14	17	3
5	5	1	15	20	5
6	13	13	16	2	8
7	1	9	17	10	10
8	9	5	18	8	13
9	6	2	19	3	10
10	24	12	20	3	12

Total Surface Area = 370 m²

10% Scan Surface Area 37 m²

202/242

Ro

Survey Unit Description FLOORS, WALLS, & CEILINGS OF TRAILER T439D

1466

Survey Area: <u>N/A</u>	Survey Unit: <u>INTERIOR</u>	Building: <u>T439D</u>
Survey Unit Description: <u>FLOORS, WALLS, & CEILINGS OF TRAILER T439D</u>		

Total Surface Activity Data Sheet

Sample location	RCT ID #	Inst ID #		Survey count time (sec)		LAB (cpm)		Gross Count (gcpm)		Net counts (cpm)		Net Activity (dpm/100cm2)	
		α	β	α	β	α	β	α	β	α	β	α	β
Room 1				90	90								
C-7F	3	9	9	90	90	1.3	499	6.0	541	4.7	42	23	136
E-8F	3	9	9	90	90	2.7	534	2.0	533	-0.7	-1	-3	-3
C-9F	3	9	9	90	90	3.3	509	10.7	565	7.4	56	36	182
A-10F	3	9	9	90	90	1.3	508	2.7	519	1.4	11	7	36
B-11F	3	9	9	90	90	2.7	519	2.0	582	-0.7	63	-3	204
E-11F	3	9	9	90	90	2.7	539	0.7	548	-2.0	9	-10	29
B-12F	3	9	9	90	90	0.7	522	1.3	578	0.6	56	3	182
B-16F	3	9	9	90	90	2.7	532	3.3	594	0.6	62	3	201
G-16F	3	9	9	90	90	2.7	532	1.3	580	-1.4	48	-7	156
D-17F	3	9	9	90	90	1.3	509	2.0	540	0.7	31	3	101
F-17F	3	9	9	90	90	1.3	511	2.0	579	0.7	68	3	221
E-18F	3	9	9	90	90	5.3	487	2.0	533	-3.3	46	-16	149
A-6C	3	9	9	90	90	2.7	523	4.0	507	1.3	-16	6	-52
F-6C	3	9	9	90	90	2.7	507	4.7	507	2.0	0	10	0
B-7C	3	9	9	90	90	2.7	503	2.7	391	0	-112	0	-363
C-9C	3	9	9	90	90	1.3	497	1.3	367	0	-130	0	-422
B-14C	3	9	9	90	90	0.0	515	4.0	582	4.0	67	19	217
C-15C	3	9	9	90	90	2.0	497	2.0	540	0	43	0	140
E-17C	3	9	9	90	90	5.3	498	5.3	519	0	21	0	68
A-2S	3	9	9	90	90	2.0	481	1.3	421	-0.7	-60	-3	-195
A-4S	3	9	9	90	90	2.7	479	2.0	367	-0.7	-112	-3	-363
B-12S	3	9	9	90	90	1.3	494	4.7	397	3.4	-97	17	-315
A-11N	3	9	9	90	90	2.0	467	1.3	399	-0.7	-68	-3	-221
D-1W	3	9	9	90	90	2.0	509	4.0	370	2.0	-139	10	-451
B-2E	3	9	9	90	90	2.7	508	4.0	407	1.3	-101	6	-328
				90	90								
				90	90								
__QC				90	90								
__QC				90	90								
__QC				90	90								
__QC				90	90								
__QC				90	90								

Note: QC measurements are to be collected by a different technician than the original survey. Mark the QC location number in the "Sample Location" column. Material background is assumed to be zero unless otherwise noted. "LAB" - local area background.

FLOORS, WALLS, + CEILINGS OF TRANSITORY

F-3

T439D – Asbestos Inspector's Report

T439D

ASBESTOS INSPECTOR'S REPORT

I, the undersigned Certified Asbestos Inspector, certification # [REDACTED] in the state of Colorado, attest to the asbestos inspection and sampling results as described below, for the following facility (at RFETS): Trailer 439D.

General Facility Location: south of Buildings 450 and 444.

INSPECTION RESULTS

Trailer 439D contains 2' x 4' drywall ceiling panels. The ceiling panels are considered non-friable and were not sampled. Fiberglass insulation was found throughout the walls. No other suspect friable asbestos containing materials were observed and no samples were collected.

SAMPLE RESULTS

None required; none taken.

Andre Gonzalez

INSPECTOR'S NAME

Andre Gonzalez

SIGNATURE

2/6/00

DATE

F-4

T439D – D&D Facility Characterization Interview Checklist



**D&D Facility Characterization
Interview Checklist**

ID No.: T439D
Date: 6/16/99
Page 2 of 2
Groups B & C Series

What time frame did the interviewee work in the facility? Ron Nokes 89-93, Sue Anderson/Vicki Scott 94-95, Dan Coyne 95-97.

Has the building configuration changed since you worked in the building? If so, in what way? No

What types of equipment were in the building during the interviewee's time there? Copier/Fax machine.

Where was the equipment located? (specific rooms/areas) in cubicle opposite of office east wall

Were any radioactive materials or metals handled in the building? If so, what types? N/A

Which equipment handled radioactive material? N/A

Were any chemicals handled in the building? If so, what types? N/A

Did any spills or uncontrolled releases of radioactive materials or chemicals occur while you were working in the facility? No

Were these spills/releases cleaned-up? How were they cleaned-up? N/A

Where did these spills/releases occur? N/A

Interviewed by: Roy G. Alexander/ *for Roy G. Alexander* /6/16/99
Print Name Signature Interview Date

173

Type 1 Facility Checklist

TYPE 1 FACILITY	BUILDING T-439D
CURRENT LANDLORD:	RFCSS
DATE OF COMPLETION:	02/29/00

ITEM	YES	NO
Does the facility contain radiological postings?		X
Does the facility contain chemical postings?		X
Are there any installed hazards?		X
Do the historical surveys (radiological and chemical) indicate the facility is clean?	X	
Are there RCRA units within the facility		X
Is there a history of the building available?	X	
Is there any equipment/furniture left in the facility?		X
Is there a future mission identified for the facility?		X
Will the facility be left unsecured after it is vacated?		X

If any answer to any of the above questions is "Yes", complete the following questions and complete the "graded" PEP in accordance with Chapter 2.

Note: An answer of "Yes" to any question, specifically one dealing with hazards, may indicate the facility is not a Type 1 Facility. Check with the D&D Programs office.

If the answer to all question is "No" complete the "graded" PEP in accordance with Chapter 2.

1. List the Radiological Hazards, location, and quantity:

Based on the historical data found and interviews taken there are no hazards in this trailer.

2. List the Chemical Hazards, location, and quantity:

None. Based on historical data and interviews taken no asbestos data exists and the paint may be lead based.

3. List the Physical Hazards:

NONE

Appendix G, General Group B Survey and Sampling Documentation

- Chain-of-Custody (for Groups B & C samples)
- MARSSIM Pre-Survey Calculations for Survey Frequency
- MARSSIM Post-Survey Calculation for Survey Frequency (typical)
- OASIS QC Data
- Verification of OASIS Results – Offsite (GEL) Alpha Spectroscopy Results

CHAIN OF CUSTODY SAMPLE ANALYSIS REQUEST

Page 1 of 2

REETS

REFS		Contact/Requester	SYDLOWSKI TOM	NICK DEMOS	Telephone No.	8165 / 4605	MSIN		FAX
Samplet(s)	(time/date)	Sampling Origin			Purchase Order/Charge Code	NG2200C1			
RIN	00A1148	B&C Facilities			Ice Chest No.	NA	Temp.	NA	
Project Title		Logbook No.		NA					
To (Lab)	Building 559 Laboratory	Method of Shipment		Hand Carry	Bill of Lading/Air Bill No.	NA			
Protocol		Related COC (if any)		NA	PRE				

POSSIBLE SAMPLE HAZARDS/REMARKS	
Are acid preserved samples DOT hazardous per 40 CFR Part 136.3 Table II?	YES or NO
Are other known hazardous substances present?	YES or NO

SPECIAL INSTRUCTIONS	Hold Time	Total Activity Exemption:	Yes <input type="checkbox"/>	No <input type="checkbox"/>
(TRAILERS AROUND THE PLANT SITE) (METAL DISKS)				

Bottle No.	Customer Number	Matrix	Date	Time	Location	Container (size/type/quantity)	Sample Analysis	Preservative ; Packing
00A1148-003.001	T-4R/QC	SOLID	3/28/00	0820	T861A	1-SAMPLE / P/G 1/1	PA04A017 (Alpha Spec Qualitative) [Routine]	None
00A1148-006.001	M-1R/QC	SOLID	3/27/00	1447	T881B	1-SAMPLE / P/G 1/1	PA04A017 (Alpha Spec Qualitative) [Routine]	None
00A1148-009.001	F-20R/QC	SOLID	3/28/00	0850	T883A	1-SAMPLE / P/G 1/1	PA04A017 (Alpha Spec Qualitative) [Routine]	None
00A1148-012.001	F-20R/QC	SOLID	3/28/00	0908	T883B	1-SAMPLE / P/G 1/1	PA04A017 (Alpha Spec Qualitative) [Routine]	None
00A1148-015.001	A-7R/QC	SOLID	3/28/00	0932	T383C	1-SAMPLE / P/G 1/1	PA04A017 (Alpha Spec Qualitative) [Routine]	None
00A1148-018.001	S-1R/QC	SOLID	3/27/00	1415	T439D	1-SAMPLE / P/G 1/1	PA04A017 (Alpha Spec Qualitative) [Routine]	None
00A1148-021.001	A-2R/QC	SOLID	3/28/00	1243	T771D	1-SAMPLE / P/G 1/1	PA04A017 (Alpha Spec Qualitative) [Routine]	None

[illegible]

C.O.C. # 00A1148#001

Page 2 of 2

[illegible]

RMRS						CHAIN OF CUSTODY SAMPLE ANALYSIS REQUEST								C.O.C.# A1148#003							
RFETS																Page 1 of 4					
Sampler(s)		(time/date)		Contact/Requester SZYDLOWSKI TOM		Telephone No. 8165		MSIN		FAX											
RIN 00A1148				Sampling Origin				Purchase Order/Charge Code NG2200CI													
Project Title				Logbook No.				Ice Chest No.		Temp.											
To (Lab)				Method of Shipment				Bill of Lading/Air Bill No.													
Protocol				Related COC (if any)		PRE															
SPECIAL INSTRUCTIONS														Hold Time		Total Activity Exemption:		Yes <input type="checkbox"/> No <input type="checkbox"/>			
SCREENING REQUIRED														<input type="checkbox"/>							
POSSIBLE SAMPLE HAZARDS/REMARKS																					
Are acid preserved samples DOT hazardous per 40 CFR Part 136.3 Table II? YES or NO																					
Are other known hazardous substances present? YES or NO																					
*** ** *																					
Bottle No.	Customer Number	Matrix	Date	Time	Location	Container (size/type/quantity)	Sample Analysis	Preservative; Packing													
00A1148-001.001	I-4R	SOLID	3/28/00	0835	T881A	1-SAMPLE / P/G 1	PA04A017 (Alpha Spec Qualitative) [Routine]	None													
00A1148-002.001	T-4R	SOLID	3/29/00	0824	T881A	1-SAMPLE / P/G 1	PA04A017 (Alpha Spec Qualitative) [Routine]	None													
00A1148-004.001	G-3R	SOLID	3/27/00	1455	T881B	1-SAMPLE / P/G 1	PA04A017 (Alpha Spec Qualitative) [Routine]	None													
00A1148-005.001	M-1R	SOLID	3/27/00	1445	T881B	1-SAMPLE / P/G 1	PA04A017 (Alpha Spec Qualitative) [Routine]	None													
00A1148-007.001	H-5R	SOLID	3/29/00	0856	T883A	1-SAMPLE / P/G 1	PA04A017 (Alpha Spec Qualitative) [Routine]	None													
00A1148-008.001	F-20R	SOLID	3/28/00	0847	T883A	1-SAMPLE / P/G 1	PA04A017 (Alpha Spec Qualitative) [Routine]	None													
00A1148-010.001	H-19R	SOLID	3/29/00	0915	T883B	1-SAMPLE / P/G 1	PA04A017 (Alpha Spec Qualitative) [Routine]	None													
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]		4/13/00 1510	[Signature]	4/13/00 1510																	
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]		4/13/00 1510	[Signature]	5/1/00 1410																	
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]		5/1/00 1510	[Signature]	5/1/00 1510																	
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time	Received By:	Date/Time	Relinquished By:	Date/Time	Received By:	Date/Time													
[Signature]			[Signature]																		
Relinquished By:		Date/Time																			

C.O.C. # 00A1148#003

Page 4 of 4

[illegible]

Survey Area: G**Building: 779****Survey Unit (s): 77939 through 77948****Total Surface Activity Measurement Calculation Worksheet**

Step 1: Determine the relative shift (Δ/δ) in accordance with MARSSIM, Section 5.5.2.3, as follows:

$$\Delta/\delta = (\text{DCGL}_{\text{TSA}} - \text{LBGR}_{\text{TSA}}) / \text{SD}_{\text{TSA}}$$

$$\Delta/\delta_{\text{transuranics}} = 2.0 = (100 \text{ dpm}/100\text{cm}^2 - 40 \text{ dpm}/100\text{cm}^2) / 30 \text{ dpm}/100\text{cm}^2$$

Where:

Δ/δ is the relative shift or the resolution of measurements in units of measurement uncertainty (MARSSIM recommends a value between 1 and 3)

DCGL_{TSA} is the total surface activity derived concentration guideline value (DOE Order 5400.5 total surface activity limit equals 100 dpm/100cm² for transuranics, per the B779 Cluster Radiological Closeout Survey Plan)

LBGR_{TSA} is the lower bound of the gray region – the lower bound of the range of values of the parameter of interest in a survey unit where the consequences of making a decision error is relatively minor. The LBGR_{TSA} was adjusted to obtain a relative shift between 1 and 3 (i.e., 40 dpm/100cm² for transuranics).

SD_{TSA} is the estimated standard deviation of the total surface activity measurements (MARSSIM recommends assuming a 30% coefficient of variation if scoping or characterization data is not available)

Step 2: Determine the Sign P value by looking up the relative shift (Δ/δ) in Table 5.4 of MARSSIM (the Sign P value is the estimated probability that a random measurement from the survey unit will be less than the DCGL when the survey unit median is actually at the LBGR). The Sign P value from Table 5.4, equals 0.977250 for a relative shift of 2.0.

Step 3: Determine the number of total surface activity measurements for the applicable survey unit using the following MARSSIM, Section 5.5.2.3 formula that is based on Plutonium contaminants not being present in the background:

$$N = (1.645 + 1.645)^2 / 4(\text{Sign P} - 0.5)^2$$

$$N = (1.645 + 1.645)^2 / 4(0.977250 - 0.5)^2 = 11.88$$

Where:

1.645 is the alpha and beta decision error value (95% confidence) per the B779 Cluster Radiological Closeout Survey Plan

Sign P equals 0.977250

Step 4: Increase N by 20% to allow for missing or invalid data points per MARSSIM, Section 5.5.2.3.

$$N = 11.88 * 1.2 = 14.25$$

Conclusion: A minimum of 15 Total Surface Activity measurements will be obtained in each of the above survey unit(s).

Prepared By: Printed Name	Employee #	Radiological Engineer Signature	Date
Reviewed By: Printed Name	Employee #	Radiological Engineer Signature	Date

Removable Activity
(dpm/100 cm²) Alpha

Survey Area - N/A
 Survey Unit - Exterior
 Building - T331A
 Survey Unit Description - Roof and walls of Trailer T331A
 Removable Contamination Data Sheet
 DCGL_w 20 dpm/100 cm²
 n 28
 Mean 1.2 dpm/100 cm²
 Std Dev 1.7 dpm/100 cm²

No measurement exceeds the DCGL_w

0.6
 0.0
 3.3
 0.6
 4.5
 1.8
 -0.9
 3.0
 0.3
 2.1
 1.5
 1.8
 2.1
 -1.5
 0.3
 -0.9
 3.0
 1.8
 0.6
 -1.5
 1.8
 2.1
 3.0
 1.8
 2.1
 -1.5
 3.3
 -0.9

Removable Activity
(dpm/100 cm²) Beta

0.8	Survey Area - N/A
10.8	Survey Unit - Exterior
29.2	Building - T331A
14.8	Survey Unit Description - Roof and walls of Trailer T331A
12.8	Removable Contamination Data Sheet
-24.8	DCGL _w 1000 dpm/100 cm ²
-23.2	n 28
46.8	Mean 4.6 dpm/100 cm ²
-2.8	Std Dev 16.1 dpm/100 cm ²
16.8	
2.8	No measurement exceeds the DCGL _w
-2.8	
-7.2	
30.8	
15.2	
-5.2	
12.8	
11.2	
4.8	
-1.2	
-12.8	
-1.2	
4.8	
-14.8	
8.8	
12.8	
5.2	
-17.2	

**Total Surface Activity
(dpm/100 cm²) Alpha**

172.5
143.2
149.6
117.3
91.4
97.8
110.5
143.7
127.1
146.6
127.1
41.6
17.9
35.8
3.1
-2.9
22.3
31.9
-22.3
-6.2
0
9.3
-12.1
12.6
43.3
18.6
27.9
24.7

Survey Area - N/A
Survey Unit - Exterior
Building - T331A
Survey Unit Description - Roof and walls of Trailer T331A

Total Surface Activity Data Sheet

DCGL_w 100 dpm/100 cm²

n 28

Mean 59.7 dpm/100 cm²

Std Dev 61.0 dpm/100 cm²

Nine measurement exceeds the DCGL_w

Eleven measurement exceeds 75% of the DCGL_w

Precision

Location	C ₁	C ₂	C ₁ -C ₂	(C ₁ +C ₂)/2	RPD
A-1N	41.6	32.3	9.3	36.95	25.16915
O-1E	-6.2	32.7	-38.9	13.25	-293.5849
C-2W	-12.1	38.6	-50.7	13.25	-382.6415
A-1W	0.0	29.3	-29.3	14.65	-200
C-1W	9.3	52.3	-43	30.8	-139.6104

Precision (RPD) is out of specification due to low value survey measurements

Recalculated N

$$\Delta/\sigma_s = (DCGL-LBGR)/\sigma_s$$

$$\Delta/\sigma_s = (100-50)/61.0$$

$$\Delta/\sigma_s = 0.8$$

$$\text{Sign } p = 0.788145$$

$$N = 32.59$$

$$32.59 \times 1.2 = 13.06$$

$$N = 39$$

Note: All measurements that exceed 75% of the DCGL_w are from the roof.
The roof is suspected to have deposition from naturally occurring radioactivity.
Samples have been collected to verify this. As a result, the number of measurements collected is acceptable.

**Total Surface Activity
(dpm/100 cm²) Beta**

-30
-74
17
-51
249
189
138
0
37
-20
-303
-158
-53
-372
-481
171
-184
-60
37
13
-428
47
-63
80
301
170
177
40

Survey Area - N/A
Survey Unit - Exterior
Building - T331A
Survey Unit Description - Roof and walls of Trailer T331A

Total Surface Activity Data Sheet

DCGL_w 5000 dpm/100 cm²

n 28

Mean -21.8 dpm/100 cm²

Std Dev 194.4 dpm/100 cm²

No measurement exceeds the DCGL_w

No measurement exceeds 75% of the DCGL_w

Precision

Location	C ₁	C ₂	C ₁ -C ₂	(C ₁ +C ₂)/2	RPD
A-1N	-158	77	-235	-40.5	580.2469
O-1E	13	3	10	8	125
C-2W	-63	158	-221	47.5	0
A-1W	-428	111	-539	-158.5	340.0631
C-1W	47	-266	313	-109.5	-285.8447

Precision (RPD) is out of specification due to low value survey measurements

Recalculated N

$$\Delta/\sigma_s = (\text{DCGL-LBGR})/\sigma_s$$

$$\Delta/\sigma_s = (5000-2500)/194.4$$

$$\Delta/\sigma_s = 12.86 \text{ (default to 3)}$$

$$\text{Sign } p = 0.998650$$

$$N = 10.88$$

$$10.88 * 1.2 = 13.05$$

$$N = 14$$

OASIS Direct Analysis Measurement Result Information

The samples listed below were analyzed using the Oxford Alpha Spectroscopy Integrated System (OASIS) at the Rocky Flats Environmental Technology Site. These samples were counted directly in the alpha spectrometer chambers, without chemical preparation. The technical basis for this type of analysis has been established in TBD-00143, Direct Analysis of Alpha Emitters Using the Oxford Alpha Spectroscopy Integrated System (OASIS), and TBD-00153, Use of the OASIS for Direct Differentiation between Po-210 and DOE-enhanced Materials.

In order to maintain the quality of OASIS measurements, the instrument is performance tested in accordance with Operations Order OO-771-228, Direct Analysis of Alpha Emitters Using the Oxford Alpha Spectroscopy Integrated System (OASIS). This Operations Order establishes the periodicity of performance test and background measurements, and the criteria against which these measurements are judged. All samples are counted by RCTs or REs qualified per JPM 036-119-53, Direct Analysis of Alpha Emitters Using the Oxford Alpha Spectroscopy Integrated System (OASIS) and approved by qualified REs.

A sample of the calibration and performance test data is attached for your review. All such data are maintained by the OASIS analysts and are available for your perusal.

The samples were 1-in coupons with an area of 4.82 cm². Calculation of the activity per 100 cm² was performed assuming that samples were representative. Errors are quoted at one standard deviation, accounting for all associated analytical uncertainties. Uranium results refer to the presence of U-238, U-234, or U-235.

Sample Number	OASIS dpm \pm 1s		dpm/100cm ² \pm 1s	
00A1148-001.001	2.53	0.22	52.5	4.5
00A1148-002.001	1.83	0.12	37.8	2.6
00A1148-003.001	1.11	0.10	23.0	2.0
00A1148-004.001	2.90	0.24	60.0	4.9
00A1148-005.001	5.87	0.33	121.6	6.8
00A1148-006.001	3.54	0.16	73.3	3.4
00A1148-007.001	3.44	0.25	71.4	5.2
00A1148-008.001	5.93	0.22	122.8	4.5
00A1148-009.001	3.73	0.17	77.4	3.5
00A1148-010.001	4.13	0.27	85.7	5.7
00A1148-011.001	4.33	0.28	89.8	5.8
00A1148-012.001	5.58	0.21	115.7	4.4
00A1148-013.001	0.04	0.05	0.9	1.1
00A1148-014.001	7.91	0.39	163.9	8.1
00A1148-015.001	6.94	0.25	143.8	5.2
00A1148-016.001	7.21	0.38	149.4	7.8
00A1148-017.001	5.12	0.32	106.2	6.6
00A1148-018.001	3.37	0.25	69.9	5.3
00A1148-019.001	11.76	0.46	243.6	9.6
00A1148-020.001	8.92	0.40	184.8	8.4
00A1148-021.001	9.89	0.24	204.9	4.9
00A1148-022.001	0.13	0.08	2.7	1.6
00A1148-023.001	0.96	0.14	19.8	2.9

00A1148-024.001	3.27	0.16	67.7	3.3
00A1148-025.001	7.58	0.37	157.1	7.7
00A1148-026.001	10.11	0.45	209.6	9.3
00A1148-027.001	10.40	0.46	215.6	9.5
00A1148-028.001	0.62	0.12	12.8	2.4
00A1148-029.001	2.87	0.15	59.5	3.1
00A1148-030.001	3.08	0.16	63.8	3.2
00A1148-031.001	10.33	0.46	214.1	9.4
00A1148-032.001	3.31	0.25	68.6	5.2
00A1148-033.001	6.06	0.22	125.6	4.5
00A1148-034.001	10.72	0.31	222.2	6.3
00A1148-035.001	9.53	0.42	197.5	8.8
00A1148-036.001	7.51	0.38	155.6	7.9
00A1148-037.001	2.37	0.14	49.1	2.8
00A1148-038.001	1.88	0.08	38.9	1.7
00A1148-039.001	2.21	0.09	45.7	1.8

Sample ID	Identified Peaks				Detection Sensitivity (dpm/100 cm ²)			
	Pu+Am	Pu-239	Am-241	U	Pu+Am	Pu-239	Am-241	U
00A1148-001.001	No	No	No	No	79	70	10	79
00A1148-002.001	No	No	No	No	32	28	4	32
00A1148-003.001	No	No	No	No	30	26	4	30
00A1148-004.001	No	No	No	No	79	70	10	79
00A1148-005.001	No	No	No	No	79	70	10	79
00A1148-006.001	No	No	No	No	30	26	4	30
00A1148-007.001	No	No	No	No	79	70	10	79
00A1148-008.001	No	No	No	No	30	26	4	30
00A1148-009.001	No	No	No	No	30	26	4	30
00A1148-010.001	No	No	No	No	79	70	10	79
00A1148-011.001	No	No	No	No	79	70	10	79
00A1148-012.001	No	No	No	No	30	26	4	30
00A1148-013.001	No	No	No	No	79	70	10	79
00A1148-014.001	No	No	No	No	79	70	10	79
00A1148-015.001	No	No	No	No	34	30	4	34
00A1148-016.001	No	No	No	No	79	70	10	79
00A1148-017.001	No	No	No	No	79	70	10	79
00A1148-018.001	No	No	No	No	79	70	10	79
00A1148-019.001	No	No	No	No	70	61	8	70
00A1148-020.001	No	No	No	No	79	70	10	79
00A1148-021.001	No	No	No	No	17	15	2	17
00A1148-022.001	No	No	No	No	79	70	10	79
00A1148-023.001	No	No	No	No	79	70	10	79
00A1148-024.001	No	No	No	No	30	26	4	30
00A1148-025.001	No	No	No	No	79	70	10	79
00A1148-026.001	No	No	No	No	79	70	10	79
00A1148-027.001	No	No	No	No	79	70	10	79
00A1148-028.001	No	No	No	No	79	70	10	79

00A1148-029.001	No	No	No	No	30	26	4	30
00A1148-030.001	No	No	No	No	30	26	4	30
00A1148-031.001	No	No	No	No	79	70	10	79
00A1148-032.001	No	No	No	No	79	70	10	79
00A1148-033.001	No	No	No	No	30	26	4	30
00A1148-034.001	No	No	No	No	30	26	4	30
00A1148-035.001	No	No	No	No	75	66	9	75
00A1148-036.001	No	No	No	No	79	70	10	79
00A1148-037.001	No	No	No	No	30	26	4	30
00A1148-038.001	No	No	No	No	12	10	1	12
00A1148-039.001	No	No	No	No	12	10	1	12

Approved by:

C. J. Bianconi 5/10/00
C. J. Bianconi, CHP
B771 Radiological Engineering
303.966.7262
303.212.5706 dp

OASIS Direct Analysis Measurement Result Information

Two samples were received on 6/1/2000. The samples were 1-in coupons with an area of 4.82 cm².

The samples were analyzed using the Oxford Alpha Spectroscopy Integrated System (OASIS) at the Rocky Flats Environmental Technology Site. These samples were counted directly in the alpha spectrometer chamber, without chemical preparation. The basis for this type of analysis has been established in TBD-00143, Direct Analysis of Alpha Emitters Using the Oxford Alpha Spectroscopy Integrated System (OASIS), and TBD-00153, Use of the OASIS for Direct Differentiation between Po-210 and DOE-added Materials.

In order to maintain the quality of OASIS measurements, the instrument is performance tested in accordance with Operations Order OO-771-228, Direct Analysis of Alpha Emitters Using the Oxford Alpha Spectroscopy Integrated System (OASIS). This Operations Order establishes the periodicity of performance test and background measurements, and the criteria against which these measurements are judged. All samples are counted by RCTs or REs qualified per JPM 036-119-53, Direct Analysis of Alpha Emitters Using the Oxford Alpha Spectroscopy Integrated System (OASIS), and approved by qualified REs.

Calculation of the activity per 100 cm² was performed assuming that the activity was homogeneously distributed. Errors are quoted at two standard deviations in the final results, accounting for all associated analytical uncertainties. Uranium results refer to the presence of U-238, U-234, or U-235.

Sample ID	OASIS dpm \pm 1s		dpm/100cm ² \pm 2s	
00A1148-040.001 D2R1	24.3	0.5	504	19
00A1148-041.001 D2RQC	30.7	0.9	637	35

Sample ID	Count time (seconds)	Detection Sensitivity dpm/100cm ²			
		Pu+Am	Pu-239	Am-241	U
00A1148-040.001 D2R1	43200	20	17	2	20
00A1148-041.001 D2RQC	10800	79	70	10	79

Peaks for Pu-239, Am-241, and uranium were not identified in the spectra.

Approved by:



C. J. Bianconi, CHP
B771 Radiological Engineering
303.966.7262
303.212.5706 dp

00A1148
Data Package Narrative

Four waste samples, under the Subcontract Number KH700331EP6, were received on May 15, 2000. Four samples were analyzed by Alpha Spectroscopy for Polonium-210, Plutonium 239/240, Uranium-233/234,235,238, and Americium 241.

- Analytical Method: EPI A-011 (Alpha Spec)
- Matrix Interferences: There are no matrix interferences to report.
- QC Deficiencies: There were no deficiencies.
- Hold Times: All samples were analyzed within the required holding time.
- RDLs: There were no failed detection limits.
- Reanalysis Information: There were no reanalysis of the samples.
- Deviations from SOP: See following page.

Comments:

1. RC01CAL_EPI_3-JUN-2000, RC01CAL_EPI_4-JUN-2000 correspond to RC01CAL_EPI_01JUN2000.
2. The following samples did not meet the FWHM requirement of < 80 keV.

1000060362_PU	94 keV
1000060364_PU	92 keV
1000061142_UU	85 keV

3. Sample 00A1148-031.002, 00A1148-034.002 and QC 1000061142 were recounted due to failed yield.

Rocky Flats

Sample QC Results Summary
6/20/00

Batch #: 27172

RIN 00A1148

Line Item Code: TR01A187

Matrix: Misc. solid

KHCO ID #	GEL ID #	Analysis	Result pCi/g	2sigma Error pCi/g	MDA pCi/g	RDL pCi/g	Tracer Yield %
00A1148-015.002	25798001	Polonium-210	2.76E+00	8.17E-01	1.70E-01	1.00	68.72
00A1148-019.002	25798002	Polonium-210	2.74E+00	5.74E-01	1.56E-01	1.00	46.74
00A1148-031.002	25798003	Polonium-210	3.80E+00	8.39E-01	2.84E-01	1.00	54.27
00A1148-034.002	25798004	Polonium-210	5.07E+00	1.26E+00	2.22E-01	1.00	57.88
1000060356	Blank	Polonium-210	5.39E-02	8.61E-02	1.53E-01	1.00	49.73
1000061844	Duplicate 00A1057-002.001	Polonium-210	2.47E+00	5.60E-01	1.65E-01	1.00	70.11
1000060358	LCS	Polonium-210	1.37E+01	1.12E+00	1.73E-01	1.00	59.83

LCS recovery:

Po-210

Nom. Conc.
15.4

Recovery:
89%

Equivalency:
Po-210

F/E = 1.319

General Engineering Labs, Inc.

610

P. 04

FAX NO. 303 966 5279

SUPPORT SERVICES

JUN-22-00 THU 16:27

Rocky Flats

Sample QC Results Summary
6/13/00

Batch #: 27173

RIN 00A1148

Line Item Code: TR01A187

Matrix: Misc. solid

KHCO ID #	GEL ID #	Analysis	Result pCi/g	2sigma Error pCi/g	MDA pCi/g	RDL pCi/g	Tracer Yield %
00A1148-015.002	25798001	Americium-241	1.09E-01	9.57E-02	5.92E-02	0.30	81.49
00A1148-019.002	25798002	Americium-241	4.20E-02	3.72E-02	4.51E-02	0.30	89.13
00A1148-031.002	25798003	Americium-241	0.00E+00	0.00E+00	3.44E-02	0.30	85.19
00A1148-034.002	25798004	Americium-241	1.45E-02	6.08E-02	1.66E-01	0.30	64.68
1000060359	Blank	Americium-241	3.54E-02	4.01E-02	6.37E-02	0.30	86.16
1000061138	Duplicate 00A1148-031.002	Americium-241	0.00E+00	0.00E+00	4.27E-02	0.30	90.73
1000060361	LCS	Americium-241	4.39E+00	3.71E-01	2.21E-02	0.30	95.55

LCS recovery:

Am-241

Nom. Conc.
4.5Recovery:
98%Equivalency:
Am-241

F/E = 0

General Engineering Labs, Inc.

020

P. 05

FAX NO. 303 966 5279

SUPPORT SERVICES

JUN-22-00 THU 16:28

Rocky Flats

Sample QC Results Summary
6/13/00

Batch #: 27174

RIN 00A1148

Line Item Code: TR01A187

Matrix: Misc. solid

KHCO ID #	GEL ID #	Analysis	Result pCi/g	2sigma Error pCi/g	MDA pCi/g	RDL pCi/g	Tracer Yield %
00A1148-015.002	25798001	Plutonium-239/240	3.74E-01	1.68E-01	5.33E-02	0.30	95.36
00A1148-019.002	25798002	Plutonium-239/240	-9.15E-03	1.79E-02	1.13E-01	0.30	39.51
00A1148-031.002	25798003	Plutonium-239/240	-2.74E-02	3.10E-02	1.58E-01	0.30	62.53
00A1148-034.002	25798004	Plutonium-239/240	1.62E-02	6.79E-02	1.85E-01	0.30	59.66
1000060362	Blank	Plutonium-239/240	0.00E+00	0.00E+00	2.62E-02	0.30	81.37
1000061141	Duplicate 00A1148-031.002	Plutonium-239/240	0.00E+00	0.00E+00	6.06E-02	0.30	66.68
1000060364	LCS	Plutonium-239/240	5.04E+00	3.93E-01	2.16E-02	0.30	97.91

LCS recovery:

Pu-239/240

Nom. Conc.
5.7

Recovery:
88%

Equivalency:
Pu-239/240

F/E = 0.883

Sample QC Results Summary
6/19/00

Batch #: 2/175

RIN 00A1148

Line Item Code: TR01A107

Matrix: Misc. solid

KHCO ID #	GEL ID #	Analysis	Result pCi/g	2sigma Error pCi/g	MDA pCi/g	RDL pCi/g	Tracer Yield %
00A1148-015.002	25798001	Uranium-233/234	3.48E-02	6.21E-02	1.24E-01	1.00	104.52
		Uranium-235	-7.52E-03	4.34E-02	1.41E-01	1.00	104.52
		Uranium-238	6.80E-04	4.04E-02	1.24E-01	1.00	104.52
00A1148-019.002	25798002	Uranium-233/234	1.72E-02	2.85E-02	5.57E-02	1.00	99.31
		Uranium-235	-2.69E-03	2.33E-02	6.66E-02	1.00	99.31
		Uranium-238	-9.39E-03	1.93E-02	6.66E-02	1.00	99.31
00A1148-031.002	25798003	Uranium-233/234	1.54E-02	3.96E-02	8.79E-02	1.00	107.82
		Uranium-235	-1.06E-02	1.46E-02	7.70E-02	1.00	107.82
		Uranium-238	1.04E-02	2.04E-02	2.82E-02	1.00	107.82
00A1148-034.002	25798004	Uranium-233/234	1.18E-01	8.36E-02	9.73E-02	1.00	105.49
		Uranium-235	-6.60E-03	1.30E-02	7.90E-02	1.00	105.49
		Uranium-238	6.56E-02	6.58E-02	9.73E-02	1.00	105.49
1000060365	Blank	Uranium-233/234	7.74E-04	2.65E-02	6.85E-02	1.00	104.63
		Uranium-235	-1.24E-02	1.21E-02	5.91E-02	1.00	104.63
		Uranium-238	2.58E-04	1.53E-02	4.69E-02	1.00	104.63
1000061142	Duplicate 00A1148-031-002	Uranium-233/234	2.02E-02	2.87E-02	4.87E-02	1.00	97.21
		Uranium-235	-8.22E-03	1.14E-02	6.00E-02	1.00	97.21
		Uranium-238	8.04E-03	2.52E-02	6.00E-02	1.00	97.21
1000060367	LCS	Uranium-233/234	3.89E+00	3.20E-01	6.78E-02	1.00	99.19
		Uranium-235	2.12E-01	7.62E-02	4.97E-02	1.00	99.19
		Uranium-238	4.19E+00	3.32E-01	5.67E-02	1.00	99.19

LCS recovery:

U-238

Nom. Conc.
4.336Recovery:
97%

Equivalency:

U-233/234

F/E = 0.098

U-235

F/E = 0.128

U-238

F/E = 0.073

Luker, Steve

From: Salmans, Michael
Sent: Tuesday, June 13, 2000 3:04 PM
To: Luker, Steve
Subject: FW: 00A1148

Mike Salmans

Analytical Services
Phone # 303-966-5057
Pager # 303-212-3149
Fax # 303-966-3578

-----Original Message-----

From: Lee Heath [SMTP:lmh@mail.gel.com]
Sent: Tuesday, June 13, 2000 2:26 PM
To: Michael Salmans
Subject: 00A1148

The 100% size of these circular disks of metal and rubber were:

(1-4 in order)
0.7182 g
1.8692 g
2.1784 g
0.7303 g (rubber)

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE

INSTRUMENT DATA

Mfg. Eberline	Mfg. Eberline	Mfg. Eberline
Model SAC-4	Model SAC-4	Model SAC-4
Serial # 1160	Serial #	Serial #
Cal Due 7-31	Cal Due	Cal Due
Bkg. 0.2 cpm	Bkg.	Bkg.
Efficiency 0.33	Efficiency	Efficiency
MDA 20 dpm	MDA	MDA
Mfg. NE Tech.	Mfg.	Mfg.
Model Electra	Model	Model
Serial # 2358	Serial #	Serial #
Cal Due 9-29-00	Cal Due	Cal Due
Bkg. 1.0 cpm	Bkg.	Bkg.
Efficiency 22.89%	Efficiency	Efficiency
MDA 33 dpm	MDA	MDA

Survey Type: REN Contamination

Building: 771

Location: ROOM 152

Purpose: Survey Sample Coupons

RWP #: N/A

Date: 4-17-00

Time: 1500

RCT: George A. Haas

Print name

G. A. Haas

Signature

Emp. #

RCT:

Print name

Signature

Emp. #

PRN/REN #:

Comments: I.D. #'s 6, 12 and 20 were counted in SAC-4 all less than 20 dpm
 (I.D. #20 counted 4 counts #12 counted 1 #6 counted 0)

SURVEY RESULTS

I.D. #	Location/Description	dpm/100cm ² α (swipe)	(direct)
1	T331A C-13 R/C (18) COUPON Btl. No. 00A1148-036.001		<33
2	T331 C-1 R (12) COUPON BOTTLE NO. 0A1148-023.001		<33
3	883C A-7 R (2) Coupon Bottle No. 0A1148-00A1148-014.001		<33
4	T771D A-2 R (18) Coupon Bottle No. 00A1148-020.001		<33
5	T771D OIR (24) Coupon Bottle Number 00A1148-019.001		<33
6	883B H-19-R COUPON BOTTLE NO. 00A1148-00A1148-010.001	36	
7	T903A N-2N QC (12) COUPON BOTTLE NO. 00A1148-030.001		<33

	Location/Description	dpm/100cm ² α (swipe)	(direct)
8	T903A N-2N (6) COUPON BOTTLE NO. 00A1148-029.001		<33
9	883C H-11R (6) COUPON BOTTLE NO. 00A1148-013.001		<33
10	T903A L-1N (13) COUPON BOTTLE NO. 00A1148-028.001		<33
11	883B F-20R (13) COUPON BOTTLE NO. 00A1148-011.001		<33
12	T331 H-1 R (6) COUPON BOTTLE NO. 00A1148-022.001		<33
13	883 A F-20R (24) COUPON BOTTLE NO. 00A1148-008.001		<33
14	883H H-5R (18) COUPON BOTTLE NO. 00A1148-007.001		<33

Date Reviewed: 4/17/00

RS Supervision:

A. WOLFE

Print Name

1. A. Wolfe

Signature

Realty Plan

Sample QC Results Summary
6/12/00

Batch #: 27172
 BIN 00A1148
 Mno Item Code: TR01A187
 Matrix: Miso. solid

KICQ ID #	GEL ID #	Analysis	Result pCi/g	1sigma Error pCi/g	MDA pCi/g	RDL pCi/g	Tracer Yield %
00A1148-018.002	25798001	Polonium-210	2.76E+00	8.17E-01	1.70E-01	0.30	68.72
00A1148-019.002	25798002	Polonium-210	2.74E+00	5.74E-01	1.56E-01	0.30	46.74
00A1148-031.002	25798003	Polonium-210	3.80E+00	8.39E-01	2.84E-01	0.30	64.27
00A1148-034.002	25798004	Polonium-210	5.07E+00	1.26E+00	2.22E-01	0.30	57.88
1000060356	Blank	Polonium-210	5.39E-02	8.61E-02	1.69E-02	0.30	49.73
1000061844	Duplicate 00A1057-002.001	Polonium-210	2.47E+00	8.60E-01	1.65E-01	0.30	70.11
1000060458	LCS	Polonium-210	1.37E-01	1.12E+00	1.73E-01	0.30	59.83

LCS recovery:

Po-210

Nom. Conc.
15.4Recovery:
89%Equivalency:
Po-210

F/E = 1.319

General Engineering Labs, Inc.

PRELIMINARY
INFORMATION

JUN-13-2000 TUE 06:42 AM T1300

FAX NO. 303 966 3578

P. 03/04

FILE No. 272 03/12 '00 16:42 ID:

FAX:

PAGE 3

Rocky Flats

Sample QC Results Summary
6/12/00

Batch #: 27174

RIN 00A1148

Line Item Code: TR01A167

Matrix: Misc. solid

KNCO ID #	GEL ID #	Analysis	Result pCi/g	2-sigma Error pCi/g	MDA pCi/g	RDL pCi/g	Tracer Yield %
00A1148-018.002	25798001	Plutonium-239/240	3.74E-01	1.68E-01	5.33E-02	0.30	95.36
00A1148-019.002	25798002	Plutonium-239/240	-9.16E-03	1.79E-02	1.13E-02	0.30	39.51
00A1148-031.002	25798003	Plutonium-239/240	-2.74E-02	3.10E-02	1.56E-01	0.30	62.53
00A1148-034.002	25798004	Plutonium-239/240	1.62E-02	6.79E-02	1.86E-01	0.30	59.66
1000060362	Blank	Plutonium-239/240	0.00E+00	0.00E+00	2.62E-02	0.30	81.37
1020061141	Duplicate 00A1148-031.002	Plutonium-239/240	0.00E+00	0.00E+00	6.05E-02	0.30	66.68
1000060364	ICS	Plutonium-239/240	8.04E+00	3.95E-01	2.16E-02	0.30	97.91

ICS recovery:

Pu-239/240

Nom. Conc.
6.7Recovery:
88%Equivalency:
Pu-239/240

F/E = 0.883

PRELIMINARY
INFORMATION

General Engineering Labs, Inc.

Rocky Flats

Sample QC Results Summary
6/16/00

Batch #: 27175

RIN 00A1148

Line Item Code: TR01A187

Matrix: Misc. solid

KHCO ID #	GEL ID #	Analysis	Result pCi/g	2sigma Error pCi/g	MDA pCi/g	RDL pCi/g	Tracer Yield %
00A1148-015.002	25798001	Uranium-233/234	3.48E-02	6.21E-02	1.24E-01	1.00	104.52
		Uranium-235	-7.52E-03	4.30E-02	1.41E-01	1.00	104.52
		Uranium-238	6.80E-04	4.04E-02	1.24E-01	1.00	104.52
00A1148-019.002	25798002	Uranium-233/234	1.72E-02	2.85E-02	5.57E-02	1.00	99.31
		Uranium-235	-2.69E-03	2.33E-02	6.66E-02	1.00	99.31
		Uranium-238	-9.39E-03	1.93E-02	6.66E-02	1.00	99.31
00A1148-031.002	25798003	Uranium-233/234	1.54E-02	3.96E-02	8.79E-02	1.00	107.82
		Uranium-235	-1.06E-02	1.46E-02	7.70E-02	1.00	107.82
		Uranium-238	1.04E-02	2.04E-02	2.82E-02	1.00	107.82
00A1148-034.002	25798004	Uranium-233/234	1.18E-01	8.36E-02	9.73E-02	1.00	105.49
		Uranium-235	-6.60E-03	1.30E-02	7.90E-02	1.00	105.49
		Uranium-238	6.56E-02	6.58E-02	9.73E-02	1.00	105.49
1000023036	Blank	Uranium-233/234	7.70E-04	2.65E-02	6.85E-02	1.00	104.63
		Uranium-235	-1.24E-02	1.21E-02	6.92E-02	1.00	104.63
		Uranium-238	2.60E-04	1.53E-02	4.69E-02	1.00	104.63
1000023037	Duplicate	Uranium-233/234	2.02E-02	2.87E-02	4.87E-02	1.00	97.21
		Uranium-235	-8.22E-03	1.14E-02	6.00E-02	1.00	97.21
		Uranium-238	8.04E-03	2.52E-02	6.00E-02	1.00	97.21
1000023038	LCS	Uranium-233/234	3.89E+00	3.20E-01	6.78E-02	1.00	99.19
		Uranium-235	2.12E-01	7.62E-02	4.97E-02	1.00	99.19
		Uranium-238	4.19E+00	3.32E-01	5.67E-02	1.00	99.19

LCS recovery:

U-238

Nom. Conc.
4.829Recovery:
87%

Equivalency:

U-233/234

U-235

U-238

F/E = 0.09815

F/E = 0.128485

F/E = 0.07338

PRELIMINARY
INFORMATION

General Engineering Labs, Inc.

PAGE 2 / 2

FAX:

FILE NO. 428 06/16/00 16:26 ID:

203/203